



ATTACHMENT A

NOTICE UNDER THE AMERICANS WITH DISABILITIES ACT

In accordance with the requirements of title II of the Americans with Disabilities Act of 1990, the City of Atlanta will not discriminate against qualified individuals with disabilities on the basis of disability in the City's services, programs, or activities.

Employment: The City does not discriminate on the basis of disability in its hiring or employment practices and complies with all regulations promulgated by the U.S. Equal Employment Opportunity Commission under title I of the Americans with Disabilities Act (ADA).

Effective Communication: The City will generally, upon request, provide appropriate aids and services leading to effective communication for qualified persons with disabilities so they can participate equally in the City's programs, services, and activities, including qualified sign language interpreters, documents in Braille, and other ways of making information and communications accessible to people who have speech, hearing, or vision impairments.

Modifications to Policies and Procedures: The City will make all reasonable modifications to policies and programs to ensure that people with disabilities have an equal opportunity to enjoy all City programs, services, and activities. For example, individuals with service animals are welcomed in City offices, even where pets are generally prohibited.

Anyone who requires an auxiliary aid or service for effective communication, or a modification of policies or procedures to participate in a City program, service, or activity, should contact the office of **[name and contact info for ADA Coordinator]** as soon as possible but no later than 48 hours before the scheduled event.

The ADA does not require the City to take any action that would fundamentally alter the nature of its programs or services, or impose an undue financial or administrative burden.

Complaints that a City program, service, or activity is not accessible to persons with disabilities should be directed to **[Name and contact information of ADA Coordinator]**.

The City will not place a surcharge on a particular individual with a disability or any group of individuals with disabilities to cover the cost of providing auxiliary aids/services or reasonable modifications of policy, such as retrieving items from locations that are open to the public but are not accessible to persons who use wheelchairs.

[Project Civic Access](#) | [ADA Home Page](#)

City of Atlanta, Georgia
Grievance Procedure under
The Americans with Disabilities Act

This Grievance Procedure is established to meet the requirements of the Americans with Disabilities Act of 1990. It may be used by anyone who wishes to file a complaint alleging discrimination on the basis of disability in the provision of services, activities, programs, or benefits by the City. The City's Personnel Policy governs employment-related complaints of disability discrimination.

The complaint should be in writing and contain information about the alleged discrimination such as name, address, phone number of complainant and location, date, and description of the problem. Alternative means of filing complaints, such as personal interviews or a tape recording of the complaint, will be made available for persons with disabilities upon request.

The complaint should be submitted by the grievant and/or his/her designee as soon as possible but no later than 60 calendar days after the alleged violation to:

[Name and address of ADA Coordinator]

Within 15 calendar days after receipt of the complaint, ***[name of ADA Coordinator]*** or ***[his/her]*** designee will meet with the complainant to discuss the complaint and the possible resolutions. Within 15 calendar days of the meeting, ***[name of ADA Coordinator]*** or ***[his/her]*** designee will respond in writing, and where appropriate, in format accessible to the complainant, such as large print, Braille, or audio tape. The response will explain the position of the City and offer options for substantive resolution of the complaint.

If the response by ***[name of ADA Coordinator]*** or ***[his/her]*** designee does not satisfactorily resolve the issue, the complainant and/or his/her designee may appeal the decision within 15 calendar days after receipt of the response to the ***[City Manager/ other appropriate high-level official]*** or ***[his/her]*** designee.

Within 15 calendar days after receipt of the appeal, the ***[City Manager/ County Commissioner/ other appropriate high-level official]*** or ***[his/her]*** designee will meet with the complainant to discuss the complaint and possible resolutions. Within 15 calendar days after the meeting, the ***[City Manager/ County Commissioner/ other appropriate high-level official]*** or ***[his/her]*** designee will respond in writing, and, where appropriate, in a format accessible to the complainant, with a final resolution of the complaint.

All written complaints received by ***[name of ADA Coordinator]*** or ***[his/her]*** designee, appeals to the ***[City Manager/other appropriate high-level official]*** or ***[his/her]*** designee, and responses from these two offices will be retained by the City for at least three years.

[Project Civic Access](#) | [ADA Home Page](#)

ATTACHMENT C

THE CITY OF ATLANTA, GEORGIA, POLICE DEPARTMENT'S POLICY STATEMENT REGARDING EFFECTIVE COMMUNICATION WITH PEOPLE WHO ARE DEAF OR HARD OF HEARING

OVERVIEW

It is the policy of this law enforcement agency (Agency) to ensure that a consistently high level of service is provided to all community members, including those who are deaf or hard of hearing. This Agency has specific legal obligations under the Americans with Disabilities Act and the Rehabilitation Act. To carry out these policies and legal obligations, the Agency instructs its officers and employees as follows:

- People who identify themselves as deaf or hard of hearing are entitled to a level of service equivalent to that provided others.
- The Agency will make every effort to ensure that its officers and employees communicate effectively with people who have identified themselves as deaf or hard of hearing.
- Effective communication with a person who is deaf or hard of hearing involved in an incident -- whether as a victim, witness, suspect, arrestee, or other persons connected to the situation -- is essential in ascertaining what actually occurred, the urgency of the matter, and the specifics of the situation.
- Various types of communication aids – known as “auxiliary aids and services” – are used to communicate with people who are deaf or hard of hearing. These include use of gestures or visual aids to supplement oral communication; an exchange of written notes; use of a computer or typewriter; use of assistive listening devices (to amplify sound for persons who are hard of hearing); or use of qualified oral or sign language interpreters.
- The type of aid that will be required for effective communication will depend on the individual’s usual method of communication, and the nature, importance, and duration of the communication at issue.
- In many circumstances, oral communication supplemented by gestures and visual aids, an exchange of written notes, use of a computer or typewriter, or use of an assistive listening device may be effective. In other circumstances, qualified sign language or oral interpreters are needed to communicate effectively with persons who are deaf or hard of hearing. The

more lengthy, complex, and important the communication, the more likely it is that a qualified interpreter will be required for effective communication with a person whose primary means of communication is sign language or speech reading. For example:

- If there has been an incident and the officer is conducting witness interviews, a qualified sign language interpreter may be required to communicate effectively with someone whose primary means of communication is sign language.
 - If a person is asking an officer for directions to a location, gestures and an exchange of written notes will likely be sufficient to communicate effectively and a sign language interpreter is often not required.
- To serve each individual effectively, primary consideration should be given to the communication aid or service that works best for that person. Officers must ask persons who are deaf or hard of hearing what type of auxiliary aid or service they need. Officers must defer to those expressed choices, unless there is another equally effective way of communicating, given the circumstances, length, complexity, and importance of the communication, as well as the communication skills of the person who is deaf or hard of hearing.
 - The Agency is not required to provide a particular auxiliary aid or service if doing so would fundamentally alter the nature of the law enforcement activity in question, or if it would cause an undue administrative or financial burden. Only the Agency head or his or her designee may make this determination.
 - The input of people who are deaf or hard of hearing who are involved in incidents is just as important to the law enforcement process as the input of others. Officers must not draw conclusions about incidents unless they fully understand -- and are understood by -- all those involved, including persons who are deaf or hard of hearing.
 - Auxiliary aids or services are to be provided free of charge.

ON-CALL INTERPRETER SERVICES

- The Agency will maintain a list of sign language and oral interpreting services that are available (on-call 24 hours per day) to provide qualified interpreters as needed. Each of these services will be chosen after having been screened for the quality and skill of its interpreters, its reliability, and other factors. The Agency will update this list annually.
- A qualified sign language or oral interpreter is one who is able to interpret effectively, accurately, and impartially, both receptively and expressively, using any necessary specialized vocabulary. Accordingly, an interpreter must be able to sign to the deaf individual (or interpret orally to the person who does not use sign language) what is being said by the hearing person and to voice to the hearing person what is being signed or said by

the deaf individual. The interpreter must be able to interpret in the language the deaf person uses (e.g., American Sign Language or Signed English) and must be familiar with law enforcement terms and phrases. Because a qualified interpreter must be able to interpret impartially, a family member, child, or friend of the individual who is deaf may not be qualified to render the necessary interpretation because of factors such as professional, emotional, or personal involvement, or considerations of confidentiality. Additionally, although a “qualified” interpreter may be certified, a certified interpreter is not necessarily “qualified,” if he or she is not a good communications match for the deaf person (e.g., where the deaf person uses Signed English and the interpreter uses American Sign Language) or the situation (e.g., where the interpreter is unfamiliar with law enforcement vocabulary). Certification is not required in order for an interpreter to be “qualified.”

TTY AND RELAY SERVICES

- In situations when a nondisabled person would have access to a telephone, officers must provide persons who are deaf or hard of hearing the opportunity to place calls using a text telephone (TTY, also known as a telecommunications device for deaf people, or TDD). Officers must also accept telephone calls placed by persons who are deaf or hard of hearing through the Telecommunications Relay Service.

TECHNIQUES FOR OFFICERS TO COMMUNICATE EFFECTIVELY

- Officers must review and have a working knowledge of *Guide for Law Enforcement Officers When In Contact With People Who Are Deaf or Hard of Hearing*. This document reviews how officers should communicate effectively in the types of situations officers will encounter. These situations include:
 - Issuing a noncriminal or motor vehicle citation.
 - Communicating with a person who initiates contact with an officer.
 - Interviewing a victim or critical witness to an incident.
 - Questioning a person who is a suspect in a crime.
 - Making an arrest or taking a person into custody.
 - Issuing *Miranda Warnings* to a person under arrest or in custody.
 - Interrogating a person under arrest or in custody.

TYPES OF AUXILIARY AIDS AND SERVICES

- Officers must utilize the following auxiliary aids as appropriate, when available, to communicate effectively:

- Use of gestures
- Use of visual aids
- Exchange of written notes
- Use of computers
- Use of assistive listening devices
- Use of teletypewriters (TTY's)
- Use of qualified oral or sign language interpreters

[Project Civic Access](#) | [ADA Home Page](#)

U.S. Department of Justice
Civil Rights Division
Disability Rights Section



GUIDE FOR LAW ENFORCEMENT OFFICERS

When In Contact With People Who Are Deaf or Hard of Hearing

As a law enforcement officer, you can expect to come into contact with people who are deaf or hard of hearing.

Title II of the Americans with Disabilities Act (ADA) of 1990 prohibits State and local governments from discriminating against an individual with a disability. Municipal and State police and county sheriff departments are bound by this Federal law. Your office has adopted a more detailed policy regarding law enforcement officers' communication with people who are deaf or hard of hearing. You should become familiar with this policy.

What does title II require of you when interacting with persons who are deaf or hard of hearing?

Among other things, your communication with such an individual must be as effective as your communication with hearing people.

How do you communicate? Provide aids or services as necessary to ensure that the deaf or hard of hearing individual understands what you are saying and that you understand him or her. These can include:

- use of qualified sign language or oral interpreters,
- for people who are hard of hearing, speaking loudly and clearly, and use of assistive listening devices (to amplify sound),
- use of gestures or visual aids to supplement oral communication,
- an exchange of written notes, or
- use of a computer.

What method of communication should you use? The law requires you to give primary consideration to the individual's preference. Ask how the person wishes to communicate.

For example, some people who are deaf do not use sign language and may need to use a different aid or rely on lipreading. In one-on-one communication with an individual who lip reads, an officer should face the

individual directly, and should ensure that the communication takes place in a well-lighted area.

Honor the individual's choice unless it would significantly interfere with your law enforcement responsibilities or you are confident that other means of communicating, that may be easier to provide, are just as effective. Remember that deaf or hard of hearing persons must be able to understand you as well as those who do not have hearing impairments.

DO NOT ask a family member or friend to interpret for a deaf individual unless it is urgent to communicate immediately and that is the only option. If the deaf person requests that arrangement and the other person agrees, however, you can proceed.

How do you know when you are communicating clearly to an individual who is deaf or hard of hearing? Ask the person to summarize what you are saying.

If the person uses sign language, what kinds of communication require an interpreter? Consider the length, importance, and complexity of the communication, as well as the context.

- In a simple encounter, such as checking a driver's license or giving directions, a notepad and pencil or perhaps gestures will normally be sufficient.
- During interrogations and arrests, a sign language interpreter will often be necessary.
- If the legality of a conversation will be questioned in court, such as situations where *Miranda* warnings are issued, a sign language interpreter may be necessary. You should be careful about misunderstandings in the absence of a qualified interpreter. A nod of the head may be an attempt to appear cooperative in the midst of misunderstanding, rather than consent or a confession of wrongdoing.
- In general, if an individual who does not have a hearing disability would be subject to police action without interrogation, then an interpreter will not be required, unless one is necessary to explain the action being taken.

Example: An officer clocks a car on the highway driving 15 miles above the speed limit. The driver, who is deaf, is pulled over and issued a noncriminal citation. The individual is able to understand the reasons for the citation, because the officer exchanges notes and points to information on the citation. A sign language interpreter is not needed.

Example: An officer responds to an aggravated battery call and upon arriving at the scene observes a bleeding victim and an individual holding a weapon. Eyewitnesses observed the individual strike the victim. The individual with the weapon is deaf. Because the officer has probable cause to make a felony arrest without an interrogation, an interpreter is not necessary to carry out the arrest.

Example: An officer responds to the scene of a domestic disturbance. The husband says the wife has been beating their children and he has been trying to restrain her. The wife, who is deaf, requests an interpreter. The officer begins by exchanging notes but the woman's responses indicate a lack of comprehension. An interpreter should be called. If the woman's behavior is threatening, the officer can make an arrest and call for an interpreter to be available at the booking station.

Do you have to take a sign language interpreter to a call about a violent crime in progress or a similar urgent situation involving a person who is deaf? No. An officer's immediate priority is to stabilize the

situation. If the person being arrested is deaf, the officer can make an arrest and call for an interpreter to be available later at the booking station.

Contact numbers for your local sign language interpreters:

Note: Reproduction of this document is encouraged.

[Project Civic Access](#) | [ADA Home Page](#)

U.S. Department of Justice
Civil Rights Division
Disability Rights Section



Accessibility of State and Local Government Websites to People with Disabilities

The Internet is dramatically changing the way that American government serves the public. Taking advantage of new technology, many State and local governments are using the web to offer citizens a host of services including:

- corresponding online with local officials;
- providing information about government services;
- renewing library books or driver's licenses;
- providing tax information and accepting tax returns; and
- applying for jobs or benefits.

These government websites are important because they:

- allow programs and services to be offered in a more dynamic, interactive way, increasing citizen participation;
- increase convenience and speed in obtaining information or services;
- reduce costs in providing programs and information about government services;
- reduce the amount of paperwork; and
- expand the possibilities of reaching new sectors of the community or offering new programs.

City of Fullerton Official Web Site -- City of Fullerton, CA
<http://www.ci.fullerton.ca.us/>

Official Web Site of the City of Fullerton

What's New | FAQs | City Facts | Links | Help | Home

Disclaimer
 303 W. Commonwealth, Fullerton, CA 92832 * (714) 738-6317
 Hours: 7:00 to 5:30 Mon-Thu, 7:30 to 5:00 Friday, Closed alternate Fridays

City Hall Hours of Operation
 City Council
 Agendas & Minutes
 Job Opportunities
 Municipal Code
 Classes & Excursions
 Downtown Fullerton
 Press Releases
 Community Calendar
 "Focus on Fullerton"
 Library Catalog and Patron Information
 Recycling Programs
 Departments:
 Administrative Services
 Airport
 City Clerk
 City Manager
 Community Services
 Development Services
 Engineering
 Fire
 Library

The material provided here is designed to help you become better acquainted with Fullerton and the services it has to offer, as well as assist you in obtaining the information you need to live, work, conduct business, and have fun in our community.

Welcome to Downtown

Located 22 miles southeast of metropolitan Los Angeles, in the center of North Orange County, Fullerton is a full-service city renowned for its unique mix of residential, commercial and industrial, educational, and cultural environments which provide an outstanding quality of life for both residents and businesses alike. Fullerton, one of the largest cities in Orange County, is a community with a strong sense of tradition, one that treasures its historic past as it prepares to meet the challenges of its future.

We hope you will find our web site helpful. We will be updating it regularly, adding more to it in the future. If you would like further information about the City or this home page, please call the Fullerton Public Information Office at (714) 738-6317.

Emergency Preparedness
 A Guide to Domestic Preparedness
 For more emergency preparedness information, please check the Department of Homeland Security website at www.dhs.gov

Special Events:
 Fullerton Memorial Day Observance
 Fullerton Railroad Days
 Fullerton Market Returns
 Other events

Local government websites provide important information and services to citizens

When government is constantly being asked to do more with less, the Internet is playing a vital role in allowing government to better serve all of its citizens.

The Americans with Disabilities Act (ADA) and, if the government entities receive Federal funding, the Rehabilitation Act of 1973, generally require that State and local governments provide qualified individuals with disabilities equal access to their programs, services, or activities unless doing so would fundamentally alter the nature of their programs, services, or activities or would impose an undue burden. One way to help meet these requirements is to ensure that government websites have accessible features for people with disabilities, using the simple steps described in this document. An agency with an inaccessible website may also meet its legal obligations by providing an alternative accessible way for citizens to use the programs or services, such as a staffed telephone information line. These alternatives, however, are unlikely to provide an equal degree of access in terms of hours of operation and the range of options and programs available. For example, job announcements and application forms, if posted on an accessible website, would be available to people with disabilities 24 hours a day, 7 days a week.

Online Barriers Faced By People with Disabilities

Many people with disabilities use "assistive technology" to enable them to use computers and access the Internet. Blind people who cannot see computer monitors may use screen readers – devices that speak the text that would normally appear on a monitor. People who have difficulty using a computer mouse can use voice recognition software to control their computers with verbal commands. People with other types of disabilities may use still other kinds of assistive technology. New and innovative assistive technologies are being introduced every day.

Poorly designed websites can create unnecessary barriers for people with disabilities, just as poorly designed buildings prevent some from entering. Designers may not realize how simple features built into a web page will assist someone who, for instance, cannot see a computer monitor or use a mouse.

One example of a barrier would be a photograph of a Mayor on a town website with no text identifying it. Because screen readers cannot interpret images unless there is text associated with it, a blind person would have no way of knowing whether the image is an unidentified photo or logo, artwork, a link to another page, or something else. Simply adding a line of simple hidden computer code to label the photograph "Photograph of Mayor Jane Smith" will allow the blind user to make sense of the image.

Accessible Design Benefits Everyone

When accessible features are built into web pages, websites are more convenient and more available to everyone – including users with disabilities. Web designers can follow techniques developed by private and government organizations to make even complex web pages usable by everyone including people with disabilities. For most websites, implementing accessibility features is not difficult and will seldom change the layout or appearance of web pages. These techniques also make web pages more usable both by people using older computers and by people using the latest technologies (such as personal digital assistants, handheld computers, or web-enabled cellular phones).

With the rapid changes in the Internet and in assistive technologies used by people with disabilities to access computers, private and government organizations have worked to establish flexible guidelines for accessible web pages that permit innovation to continue.

Resources for Web Developers

To make web pages accessible, the web developer needs to know about web page features that can make a web page less accessible or more accessible. Information about such features is easily available and many software developers are adding tools to web development software to make it easier to make web pages accessible.

Two important resources provide guidance for web developers designing accessible web pages. One is the **Section 508 Standards**, which Federal agencies must follow for their own new web pages. To learn more about the Section 508 Standards:

- The Access Board maintains information on its website at www.access-board.gov and has a useful guide for web developers at www.access-board.gov/sec508/guide/1194.22.htm;
- The Department of Justice has information about accessible web page design in an April 2000 report to the President. This report is available at www.usdoj.gov/crt/508/report/content.htm, and
- The General Services Administration hosts an online course for web developers interested in accessible web design. This program was developed in conjunction with the Access Board, the Department of Justice, and the Department of Education and provides an interactive demonstration of how to build accessible web pages. This course is available at www.section508.gov, which also provides information about the Federal government's initiative to make its electronic and information technology accessible to people with disabilities.

A more comprehensive resource is the **Web Content Accessibility Guidelines** developed by the Web Accessibility Initiative. These guidelines help designers make web pages as accessible as possible to the widest range of users, including users with disabilities. The Web Accessibility

Initiative is a subgroup of the World Wide Web Consortium — the same organization that standardizes the programming language followed by all web developers.


- Information for web developers interested in making their web pages as accessible as possible, including the current version of the **Web Content Accessibility Guidelines** (and associated checklists), can be found at www.w3c.org/WAI/Resources, and
- Information about the Web Accessibility Initiative can be found at www.w3c.org/WAI.

Voluntary Action Plan for Accessible Websites

- **Establish a policy that your web pages will be accessible** and create a process for implementation.
- **Ensure that all new and modified web pages and content are accessible:**
 - Check the HTML¹ of all new web pages. Make sure that accessible elements are used, including alt tags, long descriptions, and captions, as needed.
 - If images are used, including photos, graphics, scanned images, or image maps, make sure to include alt tags and/or long descriptions for each.
 - If you use online forms and tables, make those elements accessible.
 - When posting documents on the website, always provide them in HTML or a text-based format (even if you are also providing them in another format, such as Portable Document Format (PDF)).
- **Develop a plan for making your existing web content more accessible.** Describe your plan on an accessible web page. Encourage input on improvements, including which pages should be given high priority for change. Let citizens know about the standards or guidelines that are being used. Consider making the more popular web pages a priority.
- **Ensure that in-house staff and contractors responsible for web page and content development are properly trained.**
- **Provide a way for visitors to request accessible information or services by posting a telephone number or E-mail address on your home page.** Establish procedures to assure a quick response to users with disabilities who are trying to obtain information or services in this way.
- **Periodically enlist disability groups to test your pages for ease of use;** use this information to increase accessibility.

¹ Web pages are written using a language called HTML (or “hypertext markup language”). HTML is a “markup language” that tells a computer program (called a “browser”) how information will appear or will be arranged on a computer screen. HTML tags are specific instructions understood by a web browser or screen reader. ([back](#))

Examples of Accessible Features for Websites



Notes:

1. When navigation links are used, people who use a screen reader must listen to all the links before proceeding. A skip navigation link provides a way to bypass the row of navigation links by jumping to the start of the web page content. ([back](#))
2. All images and graphics need to have an alt tag or long description. ([back](#))
3. Use alt tags for image maps and for graphics associated with the image map so that a person using a screen reader will have access to the links and information. ([back](#))
4. Some photos and images contain content that cannot be described with the limited text of an alt tag. Using a long description tag provides a way to have as much text as necessary to explain the image so it is accessible to a person using a screen reader but not visible on the web page. ([back](#))

5. Text links do not require any additional information or description if the text clearly indicates what the link is supposed to do. Links such as “click here” may confuse a user. ([back](#))
 6. When tables with header and row identifiers are used to display information or data, the header and row information should be associated with each data cell by using HTML so a person using a screen reader can understand the information. ([back](#))
 7. A link with contact information provides a way for users to request accessible services or to make suggestions. ([back](#))
-

For More Information

Technical Information Regarding Web Accessibility

For technical assistance regarding Section 508 Standards and how to make web pages accessible to people with disabilities, please contact the Access Board:

800-872-2253 (voice)

800-993-2822 (TTY)

Information about the ADA

The Department of Justice provides technical assistance to help State and local governments understand and comply with the ADA. An important source of ADA information is the Department's ADA Home Page on the World Wide Web. This extensive website provides access to ADA regulations; all Department ADA technical assistance materials, including newly-released publications; proposed changes in the ADA regulations; and access to Freedom of Information Act materials, including technical assistance letters. The website also provides links to other Federal agencies with ADA responsibilities.

In addition, the Department of Justice operates a toll-free ADA Information Line that provides access to ADA specialists during business hours.

ADA Information Line

800-514-0301 (voice)

800-514-0383 (TTY)

Reproduction

Reproduction of this document is encouraged.

June 2003

The Attorney General has determined that publication of this periodical is necessary in the transaction of the public business required by law of the Department of Justice.

[PDF Screen Version of this Document](#)

[PDF Print Version of this Document](#)

Last updated: October 09, 2008

Attachment G

Reserved.

[Project Civic Access](#) | [ADA Home Page](#)

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| Item # | Access Issue | Required Action | Completion Date |
|------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|-----------------|
| 1 | COAN PARK, located at 1530 Woodbine Avenue, SE | | |
| 1.1 | Exterior Accessible Route. The route from the parking lot to the park is inaccessible because the curb ramp has a cross slope of 3.3%, and there is a 1 inch change in level at the bottom of the curb ramp. | AR5 | 30 months |
| 2 | MUNICIPAL COURT, located at 150 Garnett St, SW | | |
| 2.1 | Exterior Accessible Route. The route from on-street parking to the main entrance is inaccessible because the running slope is greater than 5% although it has no ramp features, and the cross-slope is greater than 2%. | AR1 | 30 months |
| 2.2 | Main Entrance. The main entrance is inaccessible because there is a 1 inch high threshold. | D22 | 30 months |
| 2.3 | Interior Accessible Route: Lobby. The route from the vestibule to the lobby is inaccessible because it narrows to 30 inches wide. | AR3 | 24 months |
| 2.4 | Employee Parking. The parking lot, with 25 total parking spaces, has no van accessible parking space and no vertical signage designating spaces as accessible. This lot requires 1 van accessible space. | P3 | 24 months |
| 2.5 | Interior Accessible Route: Side Security Entrance. The route through the security scanner is inaccessible because it is only 29 inches wide. | AR3 | 24 months |
| 2.6 | Judges's Parking: Basement. The parking lot, with a total of 55 parking spaces, has only 2 designated accessible spaces, it has no van accessible space, and the vertical sign is mounted too low. This lot requires 1 van accessible space and 2 standard accessible spaces. | P3 | 24 months |
| 2.7 | Accessible Route: Judge's Parking Entrance. The door from the Judge's parking area is inaccessible because there is a 1 inch high threshold. | D22 | 24 months |
| 2.8 | Interior Doors: General. The doors throughout the facility are inaccessible because they require more than 5 pounds of force to open. | D2 | 12 months |
| 2.9 | Toilet Rooms: General | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------|
| 2.9.a | The lavatories throughout the facility are inaccessible because the rims or counters are between 34½ and 35 high to the top. | TR11 | 30 months |
| 2.9.b | The side grab bars at designated accessible toilets throughout the facility are inaccessible because they are obstructed by the toilet paper dispensers. | ST8 SU7 | 24 months |
| 2.10 | Drinking Fountains: General. The higher drinking fountains throughout the facility protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 24 months |
| 2.11 | Interview Room 118. The bench on the prisoner side obstructs the clear floor space at the window. | PJ7 | 24 months |
| 2.12 | Drinking Fountain: Holding Area. Although an accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |
| 2.13 | Women's Employee Toilet Room With Stalls: First Floor | | |
| 2.13.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 24 months |
| 2.13.b | The pull side of the door to the toilet room, which is accessed through a front approach, is inaccessible because it has only 11 inches of maneuvering space on the latch side. | D6 | 30 months |
| 2.14 | Men's Employee Toilet Room With Stalls: First Floor. The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 24 months |
| 2.15 | Court Room 1A | | |
| 2.15.a | The court room sign is mounted on the door and lacks raised or Braille characters. | D26 | 24 months |
| 2.15.b | There is no signage informing the public of the availability of an assistive listening system. | AA3 | 24 months |
| 2.16 | Court Room 1B | | |
| 2.16.a | The court room sign is mounted on the door and lacks raised or Braille characters. | D26 | 24 months |
| 2.16.b | There is no signage informing the public of the availability of an assistive listening system. | AA3 | 24 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 2.16.c | The ramp to the court reporter's stand is inaccessible because the running slope is 9.7%. | R5 | 24 months |
| 2.16.d | The counsel's table in the court room is inaccessible because the bottom edge is 25 inches high. | T1 | 12 months |
| 2.17 | Drinking Fountains: First Floor. Although accessible drinking fountains are provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |
| 2.18 | Women's Public Toilet Rooms with Stalls: First Floor. The tampon dispenser is inaccessible because it requires wrist-twisting to operate. | TR3 | 24 months |
| 2.19 | Employee Single-User Toilet Room: Roll Call Room 186 | | |
| 2.19.a | The pull side of the door to the toilet room, which is accessed from the latch side of the door, is inaccessible because it has only 39 inches of clear width. | D10 | 24 months |
| 2.19.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 2.19.c | No accessible mirror has been provided. | TR14 | 24 months |
| 2.19.d | The rear grab bar at the toilet is inaccessible because the soap dispenser interferes with its use. | SU4 | 24 months |
| 2.20 | Closed Records Room 185 | | |
| 2.20.a | The pull side of the door, which is accessed through a front approach, is inaccessible because it has only 10 inches of maneuvering space on the latch side. | D6 | 30 months |
| 2.20.b | The counter is inaccessible because it is 39 inches high. | C6 | 24 months |
| 2.21 | Probation Services, Records Management, Warrant Services, Room 195A. The pull side of the door, which is accessed through a front approach, is inaccessible because it has only 15 inches of maneuvering space on the latch side. | D6 | 30 months |
| 2.22 | Rosie Robinson, Captain, Court Detention Unit. The route into Captain Robinson's office is inaccessible because it is only 27 inches wide. | AR3 | 24 months |
| 2.23 | Interior Accessible Route First Floor: Near DIT Repair. The defibrillator | AR8 | 24 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | protrudes into the walkway and is not detectable to blind persons using a cane. | | |
| 2.24 | Dining/Vending Room 276. The room sign is mounted on the hinge side of the door. | D26 | 12 months |
| 2.25 | Telephone: Second Floor | | |
| 2.25.a | The pay telephone on the second floor is mounted with the coin slot 60 inches high, has a cord 28 inches long, and does not have volume control. | TT1 | 24 months |
| 2.25.b | The telephone protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 2.26 | Men's Staff Toilet Room With Stalls: Second Floor. The seat cover dispenser is inaccessible because the controls are mounted 58 inches high. | TR5 | 12 months |
| 2.27 | Staff Break Room 293. The pull side of the door, which is accessed from the latch side of the door, is inaccessible because it has 39 inches of maneuvering width. | D10 | 30 months |
| 2.28 | Single-User Toilet Room Second Floor: Court Program Clerk | | |
| 2.28.a | No accessible mirror has been provided. | TR14 | 12 months |
| 2.28.b | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 2.29 | Community Service Conference Room. The conference table is inaccessible because it is 24½ inches high to the bottom. | T1 | 24 months |
| 2.30 | Court Room 3A | | |
| 2.30.a | The sign is mounted on the door and has no raised or Braille characters. | D26 | 24 months |
| 2.30.b | There is no signage informing the public of the availability of an assistive listening system. | AA3 | 24 months |
| 2.31 | Assembly Area Third Floor: Court Room 3B | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 2.31.a | The sign is mounted above the door and has no raised or Braille characters. | D26 | 24 months |
| 2.31.b | There is no signage informing the public of the availability of an assistive listening system. | AA3 | 24 months |
| 2.32 | Watershed Management Call Center: Fourth Floor. The ramp is inaccessible because the handrails do not have extensions parallel with the floor at the top and bottom. | R4 | 30 months |
| 2.33 | Men's Employee Toilet Room With Stalls: Watershed Management Call Center | | |
| 2.33.a | The rear grab bar at the designated accessible toilet is inaccessible because it is mounted 7 inches from the side wall. | ST4 | 12 months |
| 2.33.b | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 2.34 | Break Room Single-User Toilet Room: Watershed Management Call Center | | |
| 2.34.a | The lavatory is inaccessible because the apron is 28½ inches high to the bottom. | TR11 | 24 months |
| 2.34.b | The toilet is inaccessible because its centerline is 19 inches from the side wall. | SU15 | 30 months |
| 2.34.c | The toilet is inaccessible because the flush control is on the closed side. | SU1 | 30 months |
| 2.35 | Accessible Route: Fifth Floor Public Hallway. The defibrillator protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 2.36 | Men's Public Toilet Room With Stalls: Fifth Floor. The designated accessible toilet is inaccessible because its centerline is 18½ inches from the side wall. | ST17 | 30 months |
| 2.37 | Court Room 6A | | |
| 2.37.a | The sign is mounted above the door and has no raised or Braille characters. | D26 | 24 months |
| 2.37.b | There is no signage informing the public of the availability of an assistive listening system. | AA3 | 24 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 2.38 | Jury Deliberation Single-User Toilet Room: Sixth Floor | | |
| 2.38.a | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 2.38.b | The toilet is inaccessible because its centerline is 17½ inches from the side wall. | SU15 | 24 months |
| 2.39 | Staff Single-User Toilet Room: Sixth Floor | | |
| 2.39.a | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 2.39.b | The toilet is inaccessible because its centerline is 17½ inches from the side wall. | SU15 | 30 months |
| 2.40 | Men's Public Toilet Room With Stalls Sixth Floor. The toilet is inaccessible because its centerline is 17½ inches from the side wall. | ST17 | 30 months |
| 2.41 | Women's Public Toilet Room With Stalls Sixth Floor. The toilet is inaccessible because its centerline is 18½ inches from the side wall. | ST17 | 30 months |
| 3 | ATLANTA POLICE DEPARTMENT ZONE 1, located at 2315 Donald Lee Hollowell Parkway | | |
| 3.1 | Parking Lot | | |
| 3.1.a | The parking lot, with a total of 58 parking spaces, has only 2 spaces designated as reserved for people with disabilities, and neither of these spaces is designated as van accessible. This lot requires 1 van accessible space and 2 standard accessible spaces. | P3 | 30 months |
| 3.1.b | The curb ramp from the parking area onto the sidewalk has flared sides that slope more than 10%. | AR5 | 30 months |
| 3.2 | Single-User Toilet Room: Main Lobby | | |
| 3.2.a | The toilet room sign is mounted on the door. | TR18 | 12 months |
| 3.2.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 3.2.c | No accessible mirror has been provided. | TR14 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 3.2.d | The lavatory is inaccessible because the apron is 27 inches high to the bottom. | TR11 | 24 months |
| 3.2.e | The toilet is inaccessible because its centerline is 17½ inches from the side wall. | SU15 | 30 months |
| 3.2.f | The toilet paper dispenser is inaccessible because it is mounted 44 inches from the rear wall. | SU17 | 12 months |
| 3.2.g | The side grab bar at the toilet is inaccessible because it is 36 inches long and it is mounted 15 inches from the rear wall. | SU6 | 12 months |
| 3.2.h | The rear grab bar at the toilet is inaccessible because it is 30 inches long. | SU3 | 12 months |
| 3.3 | Men's Locker Room: First Floor | | |
| 3.3.a | The room sign is mounted on the door. | TR18 | 12 months |
| 3.3.b | The pull side of the door, which is accessed from the latch side of the door, is inaccessible because it has only 14 inches of clear space on the latch side. | D10 | 30 months |
| 3.3.c | No accessible mirror has been provided. | TR14 | 12 months |
| 3.3.d | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 3.3.e | The designated accessible toilet is inaccessible because its centerline is 17½ inches from the side wall. | ST17 | 30 months |
| 3.3.f | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 3.3.g | The toilet paper dispenser is inaccessible because its mounted 43 inches from the rear wall. | ST19 | 12 months |
| 3.3.h | The rear grab bar at the designated accessible toilet is inaccessible because it is mounted 9 inches from the near side wall. | ST4 | 12 months |
| 3.3.i | The designated accessible shower is inaccessible because the stall dimensions are 36 inches by 34 inches, there is insufficient clear floor space outside the shower, the seat is mounted 21 inches high on the wall adjacent to the shower controls, and there are no grab bars. | B8 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 3.4 | Women's Locker Room: First Floor | | |
| 3.4.a | The room sign is mounted on the door. | TR18 | 12 months |
| 3.4.b | No accessible mirror has been provided. | TR14 | 12 months |
| 3.4.c | The designated accessible toilet is inaccessible because its centerline is 17½ inches from the side wall. | ST17 | 30 months |
| 3.4.d | The shower is inaccessible because the stall dimensions are 39 inches by 38 inches, there is no transfer seat, there are no grab bars, and there is insufficient clear floor space outside the shower | B8 | 30 months |
| 3.5 | Men's Toilet Room With Stalls: Second Floor | | |
| 3.5.a | The room sign is mounted on the door. | TR18 | 12 months |
| 3.5.b | No accessible mirror has been provided. | TR14 | 12 months |
| 3.5.c | The urinal is inaccessible because the rim is 24 inches high. | TR20 | 30 months |
| 3.5.d | There is no accessible toilet stall provided. | ST15 | 30 months |
| 3.6 | Women's Toilet Room With Stalls: Second Floor | | |
| 3.6.a | The room sign is mounted on the door. | TR18 | 12 months |
| 3.6.b | No accessible mirror has been provided. | TR14 | 12 months |
| 3.6.c | The lavatory is inaccessible because a table is blocking the clear floor space. | TR8 | 12 months |
| 3.6.d | There is no accessible toilet stall provided. | ST15 | 30 months |
| 4 | ATLANTA POLICE DEPARTMENT ZONE 5, located at 398 Centennial Olympic Park Drive | | |
| 4.1 | Accessible Route: From Parking Lot to Main Entrance. The route is inaccessible because the slope of the curb ramp is 8.8% and the slopes of the flared sides are 21.1% and 26%. | AR5 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 4.2 | Drinking Fountains: By Lockers. The higher drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 4.3 | Women's Locker Room | | |
| 4.3.a | The sign is mounted 59 inches high. | TR18 | 12 months |
| 4.3.b | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 4.3.c | The toilet is inaccessible because its centerline is 19½ inches from the side wall. | ST17 | 30 months |
| 4.3.d | No accessible coat hook has been provided. | TR1 | 12 months |
| 4.3.e | The shower is inaccessible because the stall dimensions are 50 inches deep by 47 inches wide, the controls are 50 inches high, and the shower does not have grab bars on three walls. | B8 | 30 months |
| 4.3.f | The bench is 9½ inches wide and 20 inches above the finished floor and is not fixed to the wall along the bench's longer dimension. | LR1 | 30 months |
| 4.3.g | There is no accessible locker provided. | LR3 | 30 months |
| 4.4 | Men's Locker Room | | |
| 4.4.a | The sign is mounted 59 inches high. | TR18 | 12 months |
| 4.4.b | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 4.4.c | The toilet is inaccessible because its centerline is 21½ inches from the side wall. | ST17 | 30 months |
| 4.4.d | The toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 4.4.e | No accessible coat hook has been provided. | TR1 | 12 months |
| 4.4.f | The shower is inaccessible because the stall dimensions are 50 inches deep by 48 inches wide, the controls are 50 inches high, and the shower does not have grab bars on three walls. | B8 | 30 months |
| 4.4.g | The bench is 9½ inches wide and 20 inches above the finished floor and | LR1 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | is not fixed to the wall along the bench's longer dimension. | | |
| 4.4.h | There is no accessible locker provided. | LR3 | 30 months |
| 4.5 | Front Desk. The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 4.6 | Sergeant Butler's Office. The route into Sergeant Butler's office is inaccessible because it is only 27½ inches wide. | AR3 | 24 months |
| 5 | WASHINGTON PARK NATATORIUM, located at 102 Ollie St, NW | | |
| 5.1 | Exterior Accessible Route. The route from the parking lot to the sidewalk is inaccessible because the slope of the curb ramp is 9%. | AR5 | 30 months |
| 5.2 | Drinking Fountains. The drinking fountains on both floors protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 5.3 | Women's Toilet Room with Stalls: Upper Level | | |
| 5.3.a | The toilet room sign is mounted 56 inches high. | TR18 | 30 months |
| 5.3.b | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 5.4 | Men's Toilet Room With Stalls: Upper Level | | |
| 5.4.a | The toilet room sign is mounted 56 inches high. | TR18 | 12 months |
| 5.4.b | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 5.5 | Elevator. The elevator is inaccessible because, although emergency communications are provided, the system does not operate without voice communication. | E8 | 30 months |
| 5.6 | Men's Locker Room: Lower Level | | |
| 5.6.a | The locker room sign is mounted 57 inches high. | TR18 | 12 months |
| 5.6.b | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 5.6.c | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 5.6.d | The designated accessible transfer shower is inaccessible because the stall is 39 inches by 47 inches, the seat does not extend the full depth of the stall, the shower spray unit cannot be fixed, and there is no shower head. | B8 | 30 months |
| 5.6.e | There is no accessible locker provided. | LR3 | 30 months |
| 5.7 | Women's Locker Room: Lower Level | | |
| 5.7.a | The locker room sign is mounted 57 inches high. | TR18 | 12 months |
| 5.7.b | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 5.7.c | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 5.7.d | The designated accessible transfer shower is inaccessible because the stall is 39 inches by 47 inches and the seat does not extend the full depth of the stall. | B8 | 30 months |
| 5.7.e | There is no accessible locker provided. | LR3 | 30 months |
| 5.8 | Pavilions. The route to the pavilions is not firm, stable, or slip resistant and lacks a curb ramp. | AR1 | 30 months |
| 6 | ATLANTA FIRE STATION 14, located at 1203 Lee Street SW | | |
| 6.1 | Parking Lot. The parking lot, with a total of 10 parking spaces, has no van accessible parking space, and the access aisle is 48 inches wide. This lot requires 1 van accessible space. | P3 | 24 months |
| 6.2 | Exterior Accessible Route: From Parking Lot to Main Entrance. The route near the main entrance is inaccessible because it slopes 8.9%. | AR1 | 30 months |
| 6.3 | Main Lobby. The drinking fountains protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 6.4 | Men's Single-User Toilet Room: Lobby. The toilet is inaccessible because its centerline is 17 inches from the side wall. | SU15 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.5 | Gear Room 108 | | |
| 6.5.a | The door is inaccessible because it requires 6 pounds of force to open. | D2 | 12 months |
| 6.5.b | The room sign is mounted on the hinge side of the door. | D26 | 12 months |
| 6.6 | Physical Training Room 110 | | |
| 6.6.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 6.6.b | The room sign is mounted 61½ inches high. | D26 | 12 months |
| 6.7 | Captain's Office. The pull side of the door, which is accessed through a front approach, is inaccessible because it only has 12 inches of maneuvering space on the latch side. | D6 | 30 months |
| 6.8 | Kitchen. The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 6.9 | Dormitory | | |
| 6.9.a | The door is inaccessible because it requires 6 pounds of force to open. | D2 | 12 months |
| 6.9.b | The fire extinguisher protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 6.10 | Women's Locker Room 119 | | |
| 6.10.a | The locker room sign is mounted 55 inches high. | TR18 | 12 months |
| 6.10.b | The pull side of the door, which is accessed from the latch side of the door, is inaccessible because it has only 6½ inches of space on the latch side. | D10 | 30 months |
| 6.10.c | The locker room door swings into the required clear floor space at the lavatory. | TR6 | 30 months |
| 6.10.d | The paper towel dispenser is inaccessible because the controls are mounted 54 inches high over the bench. | TR4 | 12 months |
| 6.10.e | The designated accessible toilet is inaccessible because the clear floor | ST18 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | space is 47 inches wide. | | |
| 6.10.f | The designated accessible toilet is inaccessible because the top of the seat is 16 inches high. | ST20 | 30 months |
| 6.10.g | The designated accessible toilet is inaccessible because its centerline is 22 inches from the side wall. | ST17 | 30 months |
| 6.10.h | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 6.10.i | There are no grab bars provided at the designated accessible toilet. | ST11 | 30 months |
| 6.10.j | There is no accessible shower provided. | B8 | 30 months |
| 6.10.k | The bench in the dressing area is inaccessible because it is 24 inches long, is 9½ inches wide, and is not fixed to the wall. | LR1 | 30 months |
| 6.10.l | There is no accessible locker provided. | LR3 | 30 months |
| 6.11 | Men's Locker Room | | |
| 6.11.a | The paper towel dispenser is inaccessible because the controls are mounted 54 inches high over the bench. | TR4 | 12 months |
| 6.11.b | The urinal is inaccessible because the rim is 24 inches high. | TR20 | 30 months |
| 6.11.c | The designated accessible toilet is inaccessible because the clear floor space is 47 inches wide. | ST18 | 30 months |
| 6.11.d | The designated accessible toilet is inaccessible because the top of the seat is 16 inches high. | ST20 | 30 months |
| 6.11.e | The designated accessible toilet is inaccessible because its centerline is 19 inches from the side wall. | ST17 | 30 months |
| 6.11.f | There are no grab bars provided at the designated accessible toilet. | ST11 | 30 months |
| 6.11.g | There is no accessible shower provided. | B8 | 30 months |
| 6.11.h | The bench in the dressing area is inaccessible because it is 9½ inches wide and is not fixed to the wall. | LR1 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.11.i | There is no accessible locker provided. | LR3 | 30 months |
| 7 | ATLANTA FIRE STATION 4, located at 309 Edgewood Avenue | | |
| 7.1 | Parking Lot. The parking lot, with a total of 8 parking spaces, has two designated accessible parking spaces with no vertical signage and with slopes between 6.4% and 7.9%. This lot requires 1 van accessible space. | P3 | 30 months |
| 7.2 | Exterior Accessible Route: From Parking Lot to Front Entrance. The route is inaccessible because the slope of the curb ramp is 9.3% and the slope of the flared sides is between 20.9% and 23.9%. | AR5 | 30 months |
| 7.3 | Interior Doors. Many of the interior doors are inaccessible because they require more than 5 pounds of force to open. | D2 | 12 months |
| 7.4 | Women's Single-User Toilet Room: Lobby | | |
| 7.4.a | The toilet is inaccessible because the centerline is 19 inches from the side wall. | SU15 | 30 months |
| 7.4.b | The toilet paper is not mounted in an accessible location. | SU17 | 12 months |
| 7.5 | Men's Single-User Toilet Room: Lobby. The toilet is inaccessible because the centerline is 19½ inches from the side wall. | SU15 | 30 months |
| 7.6 | Community Room 103. The push side of the door, which is accessed through a front approach and which has both a closer and a latch, is inaccessible because it has only 2 inches of clear space on the latch side. | D7 | 30 months |
| 7.7 | Watch Officer Room 121. The room sign is mounted 71 inches high. | D26 | 12 months |
| 7.8 | Apparatus Room 129. The room sign is mounted 70 inches high. | D26 | 12 months |
| 7.9 | Women's Locker Room 105 | | |
| 7.9.a | The room sign is mounted 63 inches high. | TR18 | 12 months |
| 7.9.b | The lavatories are inaccessible because they do not have adequate knee clearance. | TR11 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 7.9.c | There is no accessible toilet stall provided. | ST15 | 30 months |
| 7.9.d | There is no accessible shower stall provided. | B8 | 30 months |
| 7.9.e | The bench in the dressing area is inaccessible because it is 9½ inches wide and is not fixed to the wall. | LR1 | 30 months |
| 7.10 | Men's Locker Room 109 | | |
| 7.10.a | The room sign is mounted 62½ inches high. | TR18 | 12 months |
| 7.10.b | No accessible mirror has been provided. | TR14 | 12 months |
| 7.10.c | The lavatories are inaccessible because they do not have adequate knee clearance. | TR11 | 30 months |
| 7.10.d | The urinal is inaccessible because the rim is 24 inches high. | TR20 | 30 months |
| 7.10.e | There is no accessible toilet stall provided. | ST15 | 30 months |
| 7.10.f | There is no accessible shower stall provided. | B8 | 30 months |
| 7.10.g | The bench in the dressing area is inaccessible because it is 9½ inches wide and is not fixed to the wall. | LR1 | 30 months |
| 7.11 | Dormitory Room 107. The room sign is mounted 68 inches high. | D26 | 12 months |
| 8 | ADAMSVILLE RECREATION CENTER, located at 3201 MLK Jr. Drive, SW | | |
| 8.1 | Exterior Accessible Route: From Parking Lot to Main Entrance. The curb ramps have flared sides that slope more than 10%. | AR5 | 30 months |
| 8.2 | Interior Accessible Route: Beneath Stairs. The route is inaccessible because there are less than 80 inches of head room provided. | AR7 | 24 months |
| 8.3 | Women's Toilet Room With Stalls: Second Floor | | |
| 8.3.a | The door is inaccessible because it requires 6 pounds of force to open. | D2 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 8.3.b | No accessible mirror has been provided | TR14 | 12 months |
| 8.3.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.3.d | The designated accessible toilet is inaccessible because the centerline is 17 inches from the side partition. | ST17 | 30 months |
| 8.3.e | Although there are 6 toilet stalls, there is no ambulatory stall provided. | ST1 | 30 months |
| 8.4 | Men's Toilet Room With Stalls: Second Floor | | |
| 8.4.a | The door is inaccessible because it requires 6 pounds of force to open. | D2 | 12 months |
| 8.4.b | No accessible mirror has been provided | TR14 | 12 months |
| 8.4.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.4.d | The designated accessible urinal is inaccessible because the rim is 18 inches high and the flush control is 47 inches high. | TR20 | 30 months |
| 8.4.e | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 8.5 | Concession Stand: Second Floor | | |
| 8.5.a | The counter is inaccessible because it is 42 inches high. | C6 | 30 months |
| 8.5.b | The dining tables near the snack area are inaccessible because none provides the required knee space. | PD3 | 30 months |
| 8.6 | First Aid Counter: First Floor. The counter is inaccessible because it is 41 inches high. | C6 | 30 months |
| 8.7 | Pool Check-in Counter: First Floor. The counter is inaccessible because it is 41 inches high. | C6 | 30 months |
| 8.8 | Women's Locker Room: Pool Area First Floor | | |
| 8.8.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|-------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 8.8.b | The toilet in the ambulatory stall is not centered within the stall. | ST1 | 30 months |
| 8.8.c | The bench in the dressing area is inaccessible because it is less than 24 inches deep. | LR1 | 30 months |
| 8.8.d | There is no accessible locker provided. | LR3 | 30 months |
| 8.8.e | The air dryers in the dressing room are inaccessible because they are mounted 62 inches above the finished floor. | TR5 | 12 months |
| 8.8.f | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.8.g | There is no accessible coat hook provided in the designated accessible toilet stall. | TR1 | 12 months |
| 8.8.h | The roll-in shower is inaccessible because it does not have grab bars on three walls. | B8 | 30 months |
| 8.9 | Men's Locker Room Pool Area: First Floor | | |
| 8.9.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 8.9.b | The toilet in the ambulatory stall is not centered within the stall. | ST1 | 30 months |
| 8.9.c | The bench in the dressing area is inaccessible because it is less than 24 inches deep. | LR1 | 30 months |
| 8.9.d | There is no accessible locker provided. | LR3 | 30 months |
| 8.9.e | The air dryers in the dressing room are inaccessible because they are mounted 72 inches above the finished floor. | TR5 | 12 months |
| 8.9.f | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.9.g | There is no accessible coat hook provided in the designated accessible toilet stall. | TR1 | 12 months |
| 8.9.h | The roll-in shower is inaccessible because it does not have grab bars on three walls. | B8 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 8.10 | Drinking Fountains: First Floor. The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.11 | Women's Toilet Room With Stalls: First Floor | | |
| 8.11.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 8.11.b | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.11.c | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 8.11.d | Although there are 6 toilet stalls, there is no ambulatory stall provided. | ST1 | 30 months |
| 8.12 | Men's Toilet Room With Stalls: First Floor | | |
| 8.12.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 8.12.b | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.12.c | The designated accessible urinal is inaccessible because the rim is 18 inches high and the flush control is 46 inches high. | TR20 | 30 months |
| 8.12.d | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 8.12.e | The designated accessible toilet is inaccessible because the centerline is 16½ inches from the side partition | ST17 | 30 months |
| 8.13 | Women's Locker Room: First Floor | | |
| 8.13.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 8.13.b | The air dryer is inaccessible because it is mounted with the controls 57 inches high. | TR5 | 12 months |
| 8.13.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.13.d | The shower is inaccessible because the seat does not extend the full | B10 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | depth of the stall. | | |
| 8.13.e | The bench in the dressing area is inaccessible because it is less than 24 inches deep. | LR1 | 30 months |
| 8.13.f | There is no accessible locker provided. | LR3 | 30 months |
| 8.14 | Men's Locker Room: First Floor | | |
| 8.14.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 8.14.b | The air dryer is inaccessible because it is mounted with the controls 70½ inches high. | TR5 | 12 months |
| 8.14.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.14.d | The shower is inaccessible because the seat does not extend the full depth of the stall. | B10 | 30 months |
| 8.14.e | The bench in the dressing area is inaccessible because it is less than 24 inches deep. | LR1 | 30 months |
| 8.14.f | There is no accessible locker provided. | LR3 | 30 months |
| 9 | BESSIE BRANHAM RECREATION CENTER, located at 2051 Brownwood Ave, SE | | |
| 9.1 | Exterior Accessible Route: From Parking Lot to Main Entrance | | |
| 9.1.a | The curb ramp from the parking lot is inaccessible because it has flared sides that slope more than 10%. | AR5 | 30 months |
| 9.1.b | The ramp to the entrance has no level landing at the bottom, and the handrails do not have extensions at the bottom. | R5 | 30 months |
| 9.2 | Building Entrances. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 12 months |
| 9.3 | Community Room. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 9.4 | Drinking Fountains. The drinking fountains in the lobby and by the toilet rooms protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 9.5 | Men's Locker Room | | |
| 9.5.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 9.5.b | The lavatory is inaccessible because the rim or counter is 27 inches high to the top. | TR11 | 30 months |
| 9.5.c | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 9.5.d | The urinal is inaccessible because the rim is 18 inches high. | TR20 | 30 months |
| 9.5.e | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 9.5.f | The transfer shower stall is inaccessible because it is 48 inches by 36 inches, has a seat that does not extend the full depth of the stall, and does not have an adjustable height shower spray unit. | B8 | 30 months |
| 9.5.g | The benches in the dressing area are inaccessible because they are 9 inches deep, are not attached to the wall, and do not have adequate clear floor space alongside to allow a transfer. | LR1 | 30 months |
| 9.5.h | There are no accessible towel hooks provided. | TR1 | 12 months |
| 9.5.i | There is no accessible locker provided. | LR3 | 30 months |
| 9.6 | Women's Locker Room | | |
| 9.6.a | The sign does not have raised or Braille characters. | TR18 | 24 months |
| 9.6.b | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 9.6.c | The soap dispenser is inaccessible because the controls are mounted 51 inches high over the lavatory. | TR4 | 12 months |
| 9.6.d | The designated accessible toilet is inaccessible because the centerline is 16½ inches from the side partition. | ST17 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 9.6.e | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 9.6.f | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 9.6.g | The transfer shower stall is inaccessible because it is 48 inches by 36 inches, has a seat that does not extend the full depth of the stall, and does not have an adjustable height shower spray unit. | B8 | 30 months |
| 9.6.h | The benches in the dressing area are inaccessible because they are 9 inches deep, are not attached to the wall, and do not have adequate clear floor space alongside to allow a transfer. | LR1 | 30 months |
| 9.6.i | There are no accessible towel hooks provided. | TR1 | 12 months |
| 9.6.j | There is no accessible locker provided. | LR3 | 30 months |
| 9.7 | Interior Accessible Route: Through New Section of Building | | |
| 9.7.a | The double door leading to the office and toilet room area is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 9.7.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 9.8 | AWDA Computer Classroom. No accessible coat rack has been provided. | TR1 | 24 months |
| 9.9 | Gymnasium. The door is inaccessible because the door requires 8 pounds of force to open. | D2 | 12 months |
| 9.10 | Exterior Drinking Fountain: Tennis Courts. The drinking fountain is not accessible to people with disabilities. | DF1 | 30 months |
| 9.11 | Exterior Accessible Route: To Urban Treehouse. The walkway has a slope exceeding 5% but has no handrails. | R4 | 30 months |
| 10 | UTOY CREEK WATER RECLAMATION CENTER, located at 805 Selig Drive, SW | | |
| 10.1 | Parking Lot. The van accessible parking reserved for persons with disabilities lacks the appropriate signage. | P6 | 24 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 10.2 | Interior Doors. The interior doors throughout the facility require more than 5 pounds of force to open. | D2 | 12 months |
| 10.3 | Drinking Fountains: Main/Second Level. Although an accessible drinking fountain is provided, there is no fountain for people who have difficulty bending or stooping. | DF3 | 30 months |
| 10.4 | Women's Toilet Room With Stalls: Second Floor | | |
| 10.4.a | The seat cover dispenser is inaccessible because it is mounted 62 inches high. | TR5 | 12 months |
| 10.4.b | The tampon dispenser is inaccessible because it requires pinching and twisting of the wrist to operate. | TR3 | 30 months |
| 10.4.c | The designated accessible stall is incorrectly configured as an ambulatory stall, and a standard accessible stall is not provided. | ST15 | 30 months |
| 10.5 | Men's Toilet Room With Stalls: Second Floor | | |
| 10.5.a | The seat cover dispenser is inaccessible because it is mounted 61½ inches high. | TR5 | 12 months |
| 10.5.b | The designated accessible stall is incorrectly configured as an ambulatory stall, and a standard accessible stall is not provided. | ST15 | 30 months |
| 10.6 | Elevator. The elevator is inaccessible because, although emergency communications are provided, the door to the controls requires tight grasping and pinching to open. | E8 | 30 months |
| 10.7 | Men's Toilet Room with Stalls: First Floor by Locker Rooms. The toilet stall is incorrectly configured as an ambulatory stall, and a standard accessible stall is not provided. | ST15 | 30 months |
| 10.8 | Men's Locker Room: First Floor | | |
| 10.8.a | There is no accessible locker provided. | LR3 | 30 months |
| 10.8.b | The shower stall is inaccessible because it lacks clear floor space beyond the transfer seat. | B8 | 30 months |
| 10.9 | Women's Toilet Room with Stalls: First Floor by Locker Rooms | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 10.9.a | The seat cover dispenser is inaccessible because it is mounted 56 inches high. | TR5 | 12 months |
| 10.9.b | The tampon dispenser is inaccessible because it requires pinching and twisting of the wrist to operate. | TR3 | 30 months |
| 10.9.c | The designated accessible toilet stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 10.10 | Women's Locker Room: First Floor | | |
| 10.10.a | There is no accessible locker provided. | LR3 | 30 months |
| 10.10.b | The shower stall is inaccessible because it lacks clear floor space beyond the transfer seat. | B8 | 30 months |
| 10.11 | Drinking Fountains: First Floor | | |
| 10.11.a | The fountain by the auditorium protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 10.11.b | The wall-mounted fountain by the toilet rooms is inaccessible because the knee space is 26¼ inches high. | DF5 | 24 months |
| 10.11.c | Although an accessible drinking fountain is provided, there is no fountain accessible for people who have difficulty bending or stooping. | DF3 | 30 months |
| 10.12 | Lower Level Auditorium | | |
| 10.12.a | The lower level auditorium, containing 73 fixed seats, is inaccessible because only 2 wheelchair seating areas are provided. A total of 4 wheelchair seating areas is required. | AA6 | 30 months |
| 10.12.b | The auditorium is inaccessible to people with hearing disabilities because, although there are more than 50 fixed seats, there is no assistive listening system provided. This auditorium requires 3 receivers. | AA4 | 30 months |
| 10.13 | Men's Toilet Room With Stalls: Lower Level by Auditorium | | |
| 10.13.a | No accessible mirror has been provided. | TR14 | 12 months |
| 10.13.b | The seat cover dispenser is inaccessible because it is mounted 60 | TR5 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | inches high. | | |
| 10.13.c | The designated accessible stall is incorrectly configured as an ambulatory stall, and a standard accessible stall is not provided. | ST15 | 30 months |
| 10.14 | Women's Toilet Room With Stalls: Lower Level by Auditorium | | |
| 10.14.a | The toilet room is inaccessible because the door threshold is 1 inch high. | D22 | 24 months |
| 10.14.b | The seat cover dispenser is inaccessible because it is mounted 58 inches high. | TR5 | 12 months |
| 10.14.c | The tampon dispenser is inaccessible because it requires pinching and twisting of the wrist to operate. | TR3 | 30 months |
| 10.14.d | The designated accessible stall is incorrectly configured as an ambulatory stall, and a standard accessible stall is not provided. | ST15 | 30 months |
| 10.15 | Men's Locker Room: Lower Level | | |
| 10.15.a | There is no accessible locker provided. | LR3 | 12 months |
| 10.15.b | The bench is inaccessible because it is 9 inches wide and is not attached to the wall. | LR1 | 30 months |
| 10.15.c | The shower transfer seat is inaccessible because it does not extend the full depth of the shower. | B10 | 30 months |
| 10.16 | Women's Locker Room: Lower Level | | |
| 10.16.a | There is no accessible locker provided. | LR3 | 30 months |
| 10.16.b | The bench is inaccessible because it is 9 inches wide and is not attached to the wall. | LR1 | 30 months |
| 10.16.c | The shower transfer seat is inaccessible because it does not extend the full depth of the shower. | B10 | 30 months |
| 11 | WASHINGTON PARK TENNIS CENTER, located at 1125 Lena Street, NW, Building D | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------|
| 11.1 | Parking Lot | | |
| 11.1.a | The parking lot is inaccessible because the designated accessible parking spaces and access aisles have cross-slopes measuring between 6.6% and 7.5%. | P7 | 30 months |
| 11.1.b | The built-up curb ramp impermissibly extends into the required parking space's access aisle, and its flared sides slope more than 10%. | AR4 AR5 | 30 months |
| 11.2 | Exterior Accessible Route: From Parking Lot to Main Entrance | | |
| 11.2.a | The route from the parking area to the entrance ramp is inaccessible because it has a slope of 7.2% and a cross-slope of 3.5%. | AR1 | 30 months |
| 11.2.b | The entrance ramp is inaccessible because it slopes 9.1% at the bottom, it lacks handrails along several portions, and it does not have adequate edge protection. | R3 | 30 months |
| 11.3 | Drinking Fountain: Main Lobby: Although an accessible drinking fountain is provided, it is not accessible for people who have difficulty bending or stooping. | DF3 | 30 months |
| 11.4 | Alarms: Although the facility contains an emergency alarm system, not all common use areas have visual alarms. | AL1 | 12 months |
| 11.5 | Men's Locker Room | | |
| 11.5.a | The door is inaccessible because it requires 18 pounds of force to open. | D2 | 12 months |
| 11.5.b | The transfer shower stall is inaccessible because it is 45 inches by 40½ inches, the transfer seat does not extend the full depth of the stall, and the controls are not on the open side of the stall. | B8 | 30 months |
| 11.5.c | The bench in the dressing room is inaccessible because it is 13½ inches wide and is not attached to the wall. | LR1 | 30 months |
| 11.5.d | No accessible coat hook has been provided. | TR1 | 12 months |
| 11.5.e | There is no accessible locker provided. | LR3 | 30 months |
| 11.6 | Women's Locker Room | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 11.6.a | The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 11.6.b | The designated accessible toilet stall is inaccessible because it is 59 inches by 57 inches. | ST16 | 30 months |
| 11.6.c | The designated accessible toilet is inaccessible because the centerline is 19 inches from the side wall. | ST17 | 30 months |
| 11.6.d | The transfer shower stall is inaccessible because it is 40 inches by 40½ inches, the transfer seat does not extend the full depth of the stall, and the controls are not on the open side of the stall. | B8 | 30 months |
| 11.6.e | The bench in the dressing room is inaccessible because it is 13½ inches wide and is not attached to the wall. | LR1 | 30 months |
| 11.6.f | No accessible coat hook has been provided. | TR1 | 12 months |
| 11.6.g | There is no accessible locker provided. | LR3 | 30 months |
| 11.7 | Exterior Accessible Route: Rear Exit Ramp to Tennis Courts. The ramp has inadequate edge protection, handrails are not provided on several portions, and the handrails lack extensions. | R3 | 30 months |
| 11.8 | Tennis Courts | | |
| 11.8.a | The tennis courts are inaccessible because the entrance has a step approximately 4 inches high. | AR1 | 30 months |
| 11.8.b | The seating area has no wheelchair seating available. | AA6 | 30 months |
| 12 | ROSEL FANN RECREATION CENTER, located at 365 Cleveland Avenue, SE | | |
| 12.1 | Parking Lot. The parking lot, with a total of 103 parking spaces, has 4 designated accessible parking spaces, none of which is designated as van accessible, one of which has no vertical signage, and the other 3 of which have signage that is mounted too low. This lot requires 1 van accessible space and 4 standard accessible spaces. | P3 | 30 months |
| 12.2 | Exterior Accessible Route: Parking Lot to Main Entrance. The running slope up to the main entrance is 6.4%, and there are no ramp features. | R3 | 30 months |
| 12.3 | Interior Doors. The doors throughout the facility are inaccessible because they require more than 5 pounds of force to open. | D2 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12.4 | Concession Counter. The counter is inaccessible because it is 42 inches high. | C5 | 30 months |
| 12.5 | Classroom 203. The computer is inaccessible because the computer table is 24½ inches high to the bottom. | C3 | 30 months |
| 12.6 | Women's Toilet Room With Stalls: First Floor | | |
| 12.6.a | The toilet room sign is centered 69 inches high. | TR18 | 12 months |
| 12.6.b | The door is inaccessible because the threshold is ½ inch high and is not beveled. | D22 | 24 months |
| 12.6.c | No accessible mirror has been provided. | TR14 | 12 months |
| 12.6.d | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 12.6.e | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.7 | Men's Toilet Room With Stalls: First Floor | | |
| 12.7.a | The door is inaccessible because the threshold is ½ inch high and is not beveled. | D22 | 24 months |
| 12.7.b | No accessible mirror has been provided. | TR14 | 12 months |
| 12.7.c | The designated accessible toilet is inaccessible because the centerline is 19 inches from the side wall. | ST17 | 30 months |
| 12.7.d | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 12.7.e | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 12.7.f | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.8 | Drinking Fountains: Upper Level. Although two accessible drinking fountains are provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12.9 | Elevator | | |
| 12.9.a | The elevator is inaccessible because the main entry floor call button is not designated by a raised star. | E3 | 30 months |
| 12.9.b | The elevator is inaccessible because, although emergency communications are provided, the system is not identified by a raised symbol or lettering, the door to the system requires tight grasping or pinching to open, and the system does not work without voice communication. | E8 | 30 months |
| 12.10 | Men's Toilet Room With Stalls: Lower Level | | |
| 12.10.a | The toilet room sign is centered 62 inches high and is mounted on the hinge side of the door. | TR18 | 12 months |
| 12.10.b | No accessible mirror has been provided. | TR14 | 12 months |
| 12.10.c | The urinal is inaccessible because the rim is 25 inches high. | TR20 | 30 months |
| 12.10.d | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 12.11 | Women's Toilet Room With Stalls: Lower Level | | |
| 12.11.a | The toilet room sign is mounted on the hinge side of the door. | TR18 | 12 months |
| 12.11.b | No accessible mirror has been provided. | TR14 | 12 months |
| 12.11.c | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 12.11.d | The designated accessible toilet stall is inaccessible because it is 48 inches wide. | ST16 | 30 months |
| 12.11.e | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 12.11.f | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 12.11.g | The rear grab bar at the designated accessible toilet is inaccessible because it is mounted 7 inches from the near side wall. | ST4 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12.12 | Drinking Fountains: Near Toilet Rooms and Elevator. Although two drinking fountains are provided, there is no fountain for people who have trouble bending or stooping, and the water trajectory is 3 inches high on the existing fountains. | DF1 | 30 months |
| 12.13 | Men's Locker Room: Lower Level Gym Side | | |
| 12.13.a | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.13.b | The designated accessible toilet is inaccessible because the centerline is 17 inches from the side wall. | ST17 | 30 months |
| 12.13.c | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 12.13.d | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 12.13.e | The transfer shower is inaccessible because it is 37 inches wide, the transfer seat is 20 inches above the finished floor, there is no clear floor space beyond the transfer seat, one of the grab bars is split in the middle, and the shower control is not on the open side of the shower. | B8 | 30 months |
| 12.13.f | The benches are inaccessible because they are less than 24 inches wide and are not attached at the wall. | LR1 | 30 months |
| 12.13.g | There is no accessible locker provided. | LR3 | 30 months |
| 12.14 | Women's Locker Room: Lower Level Pool Side | | |
| 12.14.a | The baby changing station is inaccessible because the handle is 56 inches high. | TR5 | 12 months |
| 12.14.b | The lavatory is inaccessible because the rim or counter is 27 inches high to the bottom. | TR11 | 30 months |
| 12.14.c | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.14.d | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 12.14.e | The shower stall is inaccessible because it lacks clear floor space beyond the transfer seat, the transfer seat is not "L" shaped, does not | B8 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | extend the full depth of the stall, and is 24 inches above the finished floor, one of the grab bars is split in the middle, and the shower control is not on the open side of the shower. | | |
| 12.14.f | The benches are inaccessible because they are less than 24 inches wide and are not attached at the wall. | LR1 | 30 months |
| 12.14.g | There is no accessible locker provided. | LR3 | 30 months |
| 12.15 | Racquetball Court | | |
| 12.15.a | The racquetball court is inaccessible because the door has an opening width of 30 inches. | D25 | 30 months |
| 12.15.b | The door is inaccessible because the threshold is ¾ inches high. | D22 | 24 months |
| 12.16 | Men's Locker Room: Lower Level Pool Side | | |
| 12.16.a | The men's locker room sign is not mounted 60 inches high. | TR18 | 12 months |
| 12.16.b | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.16.c | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 12.16.d | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 12.16.e | The shower stall is inaccessible because it lacks clear floor space beyond the transfer seat, the transfer seat is not "L" shaped, does not extend the full depth of the stall, and is 24 inches above the finished floor, one of the grab bars is split in the middle, and the shower control is not on the open side of the shower. | B8 | 30 months |
| 12.16.f | The benches are less than 24 inches wide and are not attached at the wall. | LR1 | 30 months |
| 12.16.g | There is no accessible locker provided. | LR3 | 30 months |
| 13 | CLEVELAND AVENUE RECREATION CENTER, located at 47 Cleveland Avenue, SE | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 13.1 | Parking Lot. The parking lot, with a total of 38 parking spaces, has no van accessible space, and one of the designated accessible parking spaces has no vertical signage. This lot requires 1 van accessible space and 1 standard accessible space. | P3 | 30 months |
| 13.2 | Exterior Accessible Route: Parking Lot to Main Entrance. The curb ramp from the parking lot has a cross-slope of 3.1%. | AR5 | 30 months |
| 13.3 | Recreation Room. The door is inaccessible because it requires more than 5 pounds of force to open. | D2 | 12 months |
| 13.4 | Men's Toilet Room With Stalls: Main Level | | |
| 13.4.a | The sign is mounted on the hinge side of the door. | TR18 | 12 months |
| 13.4.b | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 13.4.c | The push side of the door, which is accessed through a front approach and which has both a closer and a latch, is inaccessible because it has 7½ inches of clearance on the latch side. | D7 | 30 months |
| 13.4.d | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 13.4.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 13.5 | Women's Toilet Room With Stalls: By Recreation Room Main Level | | |
| 13.5.a | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 13.5.b | The paper towel dispenser is inaccessible because it is mounted 55 inches high. | TR5 | 12 months |
| 13.5.c | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 13.5.d | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 14 | BEN HILL RECREATION CENTER, located at 2405 Fairburn Road, SW | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 14.1 | Parking Lot. The van accessible parking reserved for persons with disabilities lacks the appropriate signage. | P6 | 12 months |
| 14.2 | Exterior Accessible Routes: To Tennis Court and Play Area. The routes are inaccessible because they contain steps. | AR1 | 30 months |
| 14.3 | Drinking Fountains: First Floor. The drinking fountains protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 14.4 | Women's Toilet Room With Stalls: First Floor | | |
| 14.4.a | The room sign mounted on the latch side of the door is obstructed. | TR18 | 12 months |
| 14.4.b | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 14.4.c | The lavatory is inaccessible because the faucet requires tight grasping and twisting to operate. | TR10 | 24 months |
| 14.4.d | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 14.4.e | The designated accessible toilet stall is inaccessible because it is 47 inches wide. | ST16 | 30 months |
| 14.4.f | The designated accessible toilet is inaccessible because the top of the seat is 20 inches high. | ST20 | 30 months |
| 14.4.g | The toilet paper dispenser is mounted on the wall opposite the side grab bar. | ST19 | 12 months |
| 14.5 | Men's Toilet Room With Stalls: First Floor | | |
| 14.5.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 14.5.b | The lavatory is inaccessible because the faucet requires tight grasping and twisting to operate. | TR10 | 24 months |
| 14.5.c | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 14.6 | Women's Locker Room: Lower Level | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 14.6.a | The door is inaccessible because it requires 9 pounds of force to open. | D2 | 12 months |
| 14.6.b | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 14.6.c | The designated accessible roll-in shower is inaccessible because it has grab bars on only 2 walls, and the seat is not mounted on the wall adjacent to the controls. | B8 | 30 months |
| 14.6.d | The route into the shower is inaccessible because there are only 72 inches of head room below the bar over the shower entrance. | AR7 | 12 months |
| 14.6.e | The bench is inaccessible because it is 9¼ inches wide and is not attached to the wall. | LR1 | 30 months |
| 14.6.f | The air dryer is inaccessible because the controls are 62½ inches high. | TR5 | 12 months |
| 14.6.g | There is no accessible locker provided. | LR3 | 30 months |
| 14.7 | Mens Locker Room: Lower Level | | |
| 14.7.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 14.7.b | The lavatory is inaccessible because the hot water pipes are not covered or configured to protect against contact. | TR12 | 24 months |
| 14.7.c | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 14.7.d | The air dryer is inaccessible because the controls are 58 inches high. | TR5 | 12 months |
| 14.7.e | The designated accessible transfer shower is inaccessible because it is 48 inches deep, and the controls are not mounted on the open side of the shower. | B8 | 30 months |
| 14.7.f | The route into the shower is inaccessible because there are only 74 inches of head room below the bar over the shower entrance. | AR7 | 12 months |
| 14.7.g | The bench is inaccessible because it is 9¼ inches wide and is not attached to the wall. | LR1 | 30 months |
| 14.7.h | There is no accessible locker provided. | LR3 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 14.8 | Weight Room: Lower Level. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 14.9 | Gymnasium | | |
| 14.9.a | The higher drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 14.9.b | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 14.9.c | The wheelchair seating area has no fixed companion seats. | AA6 | 30 months |
| 15 | MORNINGSIDE RECREATION CENTER, located at 1053 E. Rock Springs Road, NE | | |
| 15.1 | Parking Lot. The van accessible parking reserved for persons with disabilities lacks the appropriate signage. | P6 | 24 months |
| 15.2 | Exterior Accessible Route: Ramp to Main Entrance. The ramp slopes between 10.3% and 12.0%, and lacks handrail extensions. | R5 | 30 months |
| 15.3 | Upper Level: Classroom. The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 15.4 | Elevator. The elevator is inoperable, and there is no other accessible route to other levels of the facility. | E1 | 30 months |
| 15.5 | Unisex Single-User Toilet Room: Upper Level | | |
| 15.5.a | The toilet room sign is mounted on the door and does not have raised or Braille characters. | TR18 | 24 months |
| 15.5.b | The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 15.5.c | The toilet is inaccessible because the top of the seat is 20 inches high. | SU18 | 30 months |
| 15.5.d | The toilet is inaccessible because its centerline is 20 inches from the side wall. | SU15 | 30 months |
| 15.6 | Girl's Toilet Room With Stalls: Lower Level | | |
| 15.6.a | The toilet room sign is mounted on the door and does not have raised or | TR18 | 24 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | Braille characters. | | |
| 15.6.b | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 15.7 | Boy's Toilet Room With Stalls: Lower Level | | |
| 15.7.a | The toilet room sign is mounted on the door and does not have raised or Braille characters. | TR18 | 24 months |
| 15.7.b | The door is inaccessible because it requires 12 pounds of force to open. | D2 | 12 months |
| 15.7.c | The pull side of the door, which can be accessed from the latch side of the door, is inaccessible because it has only 10 inches of clear space on the latch side. | D10 | 30 months |
| 16 | M. L. K. JR. RECREATION CENTER, located at 90 Boulevard Street, NE | | |
| 16.1 | Parking Lot: Pool and MLK Recreation Center Shared Parking. The parking lot, with a total of 42 parking spaces, has no accessible parking spaces. This lot requires 1 van accessible space and 1 standard accessible space. | P3 | 30 months |
| 16.2 | Exterior Accessible Route | | |
| 16.2.a | The route from the parking lot to the main entrance is inaccessible because it is often obstructed by parked cars. | AR1 | 12 months |
| 16.2.b | The route to the first floor gymnasium entrance (west) has a slope of 6.8% and has no ramp features. | R3 | 30 months |
| 16.3 | Drinking Fountains | | |
| 16.3.a | The water flow on the lower drinking fountain on the first level is one inch high. | DF7 | 12 months |
| 16.3.b | The higher drinking fountain on each level protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 16.4 | Women's Toilet Room With Stalls: Second Level | | |
| 16.4.a | The door is inaccessible because it requires 11 pounds of force to open. | D2 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 16.4.b | The lavatory is inaccessible because the hot water pipes are not covered or configured to protect against contact. | TR12 | 24 months |
| 16.5 | Men's Toilet Room With Stalls: Second Level | | |
| 16.5.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 16.5.b | The lavatory is inaccessible because the hot water pipes are not covered or configured to protect against contact. | TR12 | 24 months |
| 16.5.c | The urinal is inaccessible because the rim is 25 inches high and the flush control is 45 inches high. | TR20 | 30 months |
| 16.6 | Women's Toilet Room With Stalls: First Level | | |
| 16.6.a | The door is inaccessible because it requires 11 pounds of force to open. | D2 | 12 months |
| 16.6.b | The soap dispenser is inaccessible because it is mounted with the controls 52 inches high with a forward reach required. | TR5 | 12 months |
| 16.6.c | The lavatory is inaccessible because the hot water pipes are not covered or configured to protect against contact. | TR12 | 24 months |
| 16.7 | Men's Toilet Room With Stalls: First Level | | |
| 16.7.a | The door is inaccessible because it requires 11 pounds of force to open. | D2 | 12 months |
| 16.7.b | The lavatory is inaccessible because the hot water pipes are not covered or configured to protect against contact. | TR12 | 24 months |
| 16.7.c | The urinal is inaccessible because the rim is 25 inches high. | TR20 | 30 months |
| 16.7.d | The designated accessible toilet is inaccessible because the centerline is 19 inches from the side wall. | ST17 | 30 months |
| 16.8 | Elevators | | |
| 16.8.a | The elevator is inaccessible because the hall call buttons are centered 38 inches high. | E3 | 24 months |
| 16.8.b | The elevator is inaccessible because, although emergency communications are provided, the system is not identified by raised | E8 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | symbols and lettering, the door to the emergency communications requires tight grasping or pinching to open, and the system does not work without voice communication. | | |
| 16.9 | Gymnasium | | |
| 16.9.a | The gymnasium has no wheelchair seating areas provided. | AA6 | 30 months |
| 16.9.b | The route through the gymnasium is inaccessible because there is an area where only 65 inches of head room is provided. | AR7 | 24 months |
| 16.10 | First Level: Computer Room. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 16.11 | First Level: Arts and Crafts Room. The door is inaccessible because it requires 9 pounds of force to open. | D2 | 12 months |
| 17 | ATLANTA CITY DETENTION CENTER, located at 254 Peachtree Street, SW | | |
| 17.1 | Parking Lot: Staff Only. Although a designated van accessible parking space is provided, the vertical sign can be obstructed by a parked car, and the access aisle is 90 inches wide. | P3 | 30 months |
| 17.2 | Ramp: Main Entrance. The ramp has a handrail on only one side, and the existing handrail has no extension at the bottom. | R4 | 30 months |
| 17.3 | Women's Toilet Room With Stalls: Lobby | | |
| 17.3.a | The door is inaccessible because it requires more than 5 pounds of force to open. | D2 | 12 months |
| 17.3.b | The latch on the designated accessible toilet stall door is broken and requires pinching and twisting of the wrist to operate. | TR3 | 24 months |
| 17.3.c | The designated accessible toilet is inaccessible because the rear grab bar is obstructed by the flush valve. | ST5 | 30 months |
| 17.3.d | No accessible coat hook has been provided. | TR1 | 12 months |
| 17.4 | Men's Toilet Room With Stalls: Lobby | | |
| 17.4.a | The door is inaccessible because it requires more than 5 pounds of | D2 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | force to open. | | |
| 17.4.b | The designated accessible toilet is inaccessible because the rear grab bar is obstructed by the flush valve. | ST5 | 30 months |
| 17.4.c | No accessible coat hook has been provided. | TR1 | 12 months |
| 17.5 | Women's Toilet Room With Stalls: Staff Auditorium | | |
| 17.5.a | The door is inaccessible because it requires more than 5 pounds of force to open. | D2 | 30 months |
| 17.5.b | The feminine products dispenser and the air dryer protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 17.5.c | The designated accessible toilet is inaccessible because the rear grab bar is obstructed by the flush valve. | ST5 | 30 months |
| 17.5.d | No accessible coat hook has been provided. | TR1 | 12 months |
| 17.6 | Men's Toilet Room With Stalls: Staff Auditorium | | |
| 17.6.a | The door is inaccessible because it requires more than 5 pounds of force to open. | D2 | 12 months |
| 17.6.b | The designated accessible toilet is inaccessible because the rear grab bar is obstructed by the flush valve. | ST5 | 30 months |
| 17.6.c | No accessible coat hook has been provided. | TR1 | 12 months |
| 17.7 | Elevators | | |
| 17.7.a | Both elevators are inaccessible because, although emergency communications are provided, the highest operable part is 57 inches above the elevator floor. | E8 | 30 months |
| 17.7.b | The elevator is inaccessible because the emergency controls are grouped at the top of the panel. | E9 | 30 months |
| 17.8 | Drinking Fountains. The higher drinking fountains throughout the facility (except by the auditorium) protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 17.9 | Women's Single-User Staff Toilet Room: Administration Office Area | | |
| 17.9.a | The door is inaccessible because it requires more than 5 pounds of force to open. | D2 | 12 months |
| 17.9.b | No accessible coat hook has been provided. | TR1 | 12 months |
| 17.9.c | The toilet is inaccessible because the overall length of the rear grab bar is 30 inches and the flush valve and toilet cleanser interfere with its use. | SU2 | 30 months |
| 17.10 | Men's Single-User Staff Toilet Room: Administration Office Area | | |
| 17.10.a | The door is inaccessible because it requires more than 5 pounds of force to open. | D2 | 12 months |
| 17.10.b | The toilet is inaccessible because the overall length of the rear grab bar is 30 inches and the flush valve and toilet cleanser interfere with its use. | SU2 | 30 months |
| 17.11 | Telephones: Intake Area. The telephones are inaccessible because they have cords less than 29 inches long. | TT1 | 24 months |
| 17.12 | Housing Units. The routes through the units are inaccessible because the undersides of the stairs pose an overhead hazard. | AR7 | 30 months |
| 17.13 | Holding Cells 112 and 113. No accessible mirror has been provided. | TR14 | 12 months |
| 17.14 | Single-User Toilet Room: Women's Medical Unit Off Lobby. The rear grab bar at the toilet is inaccessible because it is obstructed by the toilet flush valve. | SU4 | 30 months |
| 17.15 | Single-User Toilet Room: Inmate Medical Unit. The rear grab bar at the toilet is inaccessible because it is obstructed by the toilet flush valve. | SU4 | 30 months |
| 17.16 | Single-User Toilet Room: Cell 118 3NE Maximum Security. The toilet is inaccessible because there is no side grab bar provided. | SU5 | 24 months |
| 17.17 | Single-User Toilet Room: 3SW Medical Dormitory. The rear grab bar at the toilet is inaccessible because it is obstructed by the toilet flush valve. | SU4 | 30 months |
| 17.18 | Shower Stalls: Cell 120 4NW Women's. The designated accessible transfer shower is inaccessible because there is no transfer seat provided. | B10 | 30 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|--------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 17.19 | Shower Stalls: Cell 104 4SE Women's. The designated accessible transfer shower is inaccessible because there is no transfer seat provided. | B10 | 30 months |
| 17.20 | Shower Stalls: 6NW. The designated accessible shower is inaccessible because the control is missing. | B8 | 30 months |
| 17.21 | Shower Stalls: 6SW. The designated accessible shower is inaccessible because the control, transfer seat, and side grab bar are missing. | B8 | 30 months |
| 17.22 | Shower Stalls: 6SE. The designated accessible shower is inaccessible because the transfer seat is crooked. | B10 | 24 months |
| 17.23 | Toilet Room With Stalls: 7NE Dormitory | | |
| 17.23.a | No accessible mirror has been provided. | TR14 | 12 months |
| 17.23.b | The designated accessible toilet is inaccessible because the rear grab bar is obstructed by the flush valve. | ST5 | 30 months |
| 17.24 | Toilet Room With Stalls: 7NW Dormitory | | |
| 17.24.a | No accessible mirror has been provided. | TR14 | 12 months |
| 17.24.b | The designated accessible toilet is inaccessible because the rear grab bar is obstructed by the flush valve. | ST5 | 30 months |
| 17.25 | Shower Stalls: 7NE. The designated accessible shower is inaccessible because the control is missing. | B8 | 30 months |
| 17.26 | Shower Stalls: 7NW. The designated accessible transfer shower is inaccessible because there is no transfer seat provided. | B10 | 30 months |
| 17.27 | Shower Stalls 7 th Floor Housing Unit: 7SE. The designated accessible shower is inaccessible because the control is missing. | B8 | 30 months |
| 17.28 | Shower Stalls 7 th Floor Housing Unit: 7SW. The designated accessible shower is inaccessible because the control is missing. | B8 | 30 months |
| 17.29 | Shower Stalls: 8SE. The designated accessible shower is inaccessible because the control is missing. | B8 | 30 months |
| 18 | ATLANTA FIRE STATION 33, located at 1401 South Loop Road | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 18.1 | Exterior Accessible Route: Parking Lot to Main Entrance. The curb ramp from the parking lot slopes 10%, and the right side flare slopes 17.5%. | AR5 | 30 months |
| 18.2 | Unisex Single-User Toilet Rooms: Main Entrance | | |
| 18.2.a | The toilet rooms are inaccessible because the doors require 7 pounds and 9 pounds of force to open. | D2 | 12 months |
| 18.2.b | No accessible mirror has been provided in either room. | TR14 | 12 months |
| 18.2.c | The toilet in each room is inaccessible because the top of the seat is 16 inches high. | SU18 | 30 months |
| 18.2.d | The toilet in each room is inaccessible because the centerline is 19 inches to 20½ inches from the side wall. | SU15 | 30 months |
| 18.3 | Drinking Fountains: Near Main Entrance. The higher drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 18.4 | 102 Conference Room. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 18.5 | 104 Copy Room | | |
| 18.5.a | The door is inaccessible because it requires 17 pounds of force to open. | D2 | 12 months |
| 18.5.b | The cabinets along one wall protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 30 months |
| 18.6 | 106 Captain's Office and Dormitory | | |
| 18.6.a | The door is inaccessible because it requires 13 pounds of force to open. | D2 | 12 months |
| 18.6.b | No accessible mirror has been provided in the toilet room. | TR14 | 12 months |
| 18.6.c | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 18.6.d | The toilet is inaccessible because the top of the seat is 16 inches high. | SU18 | 12 months |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 18.6.e | The toilet is inaccessible because there are no grab bars provided. | SU10 | 30 months |
| 18.6.f | The shower is inaccessible because it lacks a transfer seat and grab bars and has inadequate clear floor space to allow a transfer. | B8 | 30 months |
| 18.6.g | The bench is inaccessible because it is 9½ inches wide and is not attached at the wall. | LR1 | 30 months |
| 18.7 | 111 Storage Room/Bed. The door is inaccessible because it requires 17 pounds of force to open. | D2 | 12 months |
| 18.8 | 150 EMS Supervisor/Captain Office. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 18.9 | 149 Lieutenant's Office. The door is inaccessible because it requires 9 pounds of force to open. | D2 | 12 months |
| 18.10 | 146 Lieutenant Dormitory. The bench is inaccessible because it is 9½ inches wide and 36 inches long and is not attached at the wall. | LR1 | 30 months |
| 18.11 | Lieutenant's Dorm | | |
| 18.11.a | No accessible mirror has been provided in either toilet room. | TR14 | 12 months |
| 18.11.b | The lavatories in each toilet room are inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 18.11.c | The toilet in each room is inaccessible because the top of the seat is 15½ inches high | SU18 | 30 months |
| 18.11.d | The toilet in each room is inaccessible because the centerline is between 19 and 20½ inches from the side wall. | SU15 | 30 months |
| 18.11.e | The toilet in each room is inaccessible because there are no grab bars provided in either room. | SU10 | 30 months |
| 18.11.f | The transfer shower stall in each room is inaccessible because it is 40 inches deep and has no transfer seat and no grab bars. | B8 | 30 months |
| 18.11.g | The bench is inaccessible because it is 9½ inches wide and 36 inches long and is not attached at the wall. | LR1 | 30 months |
| 18.12 | 116 Dormitory Room | | |

ATTACHMENT I: Modifications to Newly Constructed Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities for which construction was commenced after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| | | | |
|----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 18.12.a | The door is inaccessible because it requires 9 pounds of force to open. | D2 | 12 months |
| 18.12.b | The women's and men's locker rooms are inaccessible because the doors require 7 and 14 pounds of force, respectively, to open. | D2 | 12 months |
| 18.12.c | No accessible mirror has been provided in either locker room. | TR14 | 12 months |
| 18.12.d | The designated accessible toilet in the women's and men's locker rooms is inaccessible because the centerline is 18½ inches and 17½ inches, respectively, from the side wall. | ST17 | 30 months |
| 18.12.e | The designated accessible toilet in each locker room is inaccessible because it has no grab bars provided. | ST11 | 30 months |
| 18.12.f | The designated accessible transfer shower in each locker room is inaccessible because there is no transfer seat provided. | B10 | 30 months |
| 18.12.g | The designated accessible transfer shower in each locker room is inaccessible because there are no grab bars provided. | B9 | 30 months |
| 18.12.h | The bench in each locker room is inaccessible because it is 9½ inches wide and is not attached at the wall. | LR1 | 30 months |
| 18.13 | 132 Exercise Room. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 18.14 | 133 Laundry Room. The door is inaccessible because it requires 16 pounds of force to open. | D2 | 12 months |
| 18.15 | 141 Lockers. The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 18.16 | 138 Laundry Room. The door is inaccessible because it requires 17 pounds of force to open. | D2 | 12 months |
| 18.17 | 137 Apparatus Room. The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |

ATTACHMENT J: Modifications to Altered Facilities

Please Note: Paragraph 42 of the Settlement Agreement requires that within three months of the effective date of this Agreement, the City provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

In order to ensure that the following spaces and elements in City facilities in which alterations occurred after January 26, 1992, are readily accessible to and usable by persons with disabilities, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| Item # | Access Issue | Required Action | Completion Date |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|-----------------|
| 1 | ATLANTA WORKFORCE DEVELOPMENT AGENCY, located at 818 Pollard Boulevard | | |
| 1.1 | Parking. The parking lot is inaccessible because the designated standard accessible spaces are between 89 and 92 inches wide, they have no access aisles, they have no vertical signage, and the van accessible space has no "Van Accessible" sign. | P3 | 30 months |
| 1.2 | Exterior Accessible Route. The curb ramp from the parking lot to the entrance is inaccessible because it has a slope of 16%. | AR5 | 30 months |
| 1.3 | Interior Signage. Much of the permanent room signage inside the facility is mounted above the doors and does not have Braille or raised lettering. | D26 | 30 months |

| | | | |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|-----------|
| 1.4 | Drinking Fountains: Main Entrance. Although accessible drinking fountains are provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 24 months |
| 1.5 | Men's Toilet Room With Stalls First Floor: Near Main Entrance | | |
| 1.5.a | The room is inaccessible because the toilet room sign is mounted on the door and has no raised letters and no International Symbol of Accessibility. | TR17 | 24 months |
| 1.5.b | No accessible mirror has been provided. | TR14 | 12 months |
| 1.5.c | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.5.d | The urinal is inaccessible because the rims are 23 inches high. | TR20 | 30 months |
| 1.5.e | The designated accessible toilet is inaccessible because the centerline is 16½ inches from the side wall. | ST17 | 30 months |
| 1.5.f | No accessible coat hook has been provided in the wide stall. | TR1 | 12 months |
| 1.5.g | The designated accessible toilet is inaccessible because the side grab bar is obstructed by the toilet paper dispenser and is mounted 37 inches high. | ST8 ST12 | 12 months |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 1.6 | Women's Toilet Room With Stalls: First Floor Near Main Entrance | | |
| 1.6.a | The room is inaccessible because the room sign is mounted on the door and has no raised letters and no International Symbol of Accessibility. | TR17 | 24 months |
| 1.6.b | The seat cover dispenser is inaccessible because it is mounted 62 inches high. | TR5 | 12 months |
| 1.6.c | The soap dispenser is inaccessible because it is mounted with the controls 55 inches high. | TR5 | 12 months |
| 1.6.d | The designated accessible toilet is inaccessible because the centerline is 16 inches from the side wall. | ST17 | 30 months |
| 1.6.e | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 1.6.f | No accessible coat hook has been provided in the wide stall. | TR1 | 12 months |
| 1.6.g | The designated accessible toilet is inaccessible because the side grab bar is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 1.6.h | Although there are 7 toilet stalls, there is no ambulatory stall provided. | ST1 | 30 months |
| 1.7 | Literacy Services. The counter is more than 36 inches high. | C6 | 30 months |

| | | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 1.8 | Sullivan Hall Auditorium | | |
| 1.8.a | The auditorium is inaccessible to people with hearing disabilities because, although there are 500 fixed seats, there is no permanently installed assistive listening system provided. This auditorium requires 20 receivers. | AA4 | 30 months |
| 1.8.b | The seating is inaccessible because there is no fixed companion seating adjacent to wheelchair seating locations. | AA6 | 30 months |
| 1.9 | Elevators | | |
| 1.9.a | The elevator is inaccessible because it has no audible hall arrival signal. | E11 | 30 months |
| 1.9.b | The elevator is inaccessible because there is hoistway signage on only one side, and it has no Braille. | E12 | 30 months |
| 1.9.c | The elevator is inaccessible because the clearance between the car platform sill and the edge of the hoistway landing is 1½ inches. | E10 | 30 months |
| 1.9.d | The elevator is inaccessible because the car control buttons have no Braille or raised characters, and the main entry floor is not designated by a raised star. | E4 | 30 months |
| 1.9.e | The elevator is inaccessible because the emergency | E8 | 30 months |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | communications are not identified by raised lettering, and the door requires pinching to open. | | |
| 1.10 | Conference Room 240. There is no assistive listening system available. This room requires 2 receivers. | AA5 | 30 months |
| 1.11 | Platform Lift: Near Taxicab Services. The lift cannot be operated without the user first obtaining a key. | LF1 | 24 months |
| 1.12 | Taxi Bureau. The room is inaccessible because the double doors are each 27 inches wide, require 7 pounds of force to open, and have thumb latch hardware. | D4 | 30 months |
| 1.13 | Men's Toilet Room: Near Classrooms | | |
| 1.13.a | The room is inaccessible because the room sign is painted on the door and has no Braille or raised lettering. | TR18 | 24 months |
| 1.13.b | There is no signage directing people with disabilities to the accessible toilet rooms. | TR16 | 24 months |
| 1.14 | Drinking Fountain: Near Classrooms. The drinking fountain is inaccessible because it has a spout 41 inches high and the water trajectory is 1 inch high. | DF1 | 24 months |
| 1.15 | Administrative Office: Room 217. The door is inaccessible because it requires 8 pounds of force to open. | D2 | 24 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 1.16 | Interior Accessible Route: Second Floor Near Administrative Office. The fire extinguisher and the hanging plants in the hallway protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.17 | Men's Toilet Room: Second Floor Near Elevators | | |
| 1.17.a | The room is inaccessible because the room sign is mounted on the door and has no raised letters and no International Symbol of Accessibility. | TR17 | 24 months |
| 1.17.b | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.17.c | The urinals are inaccessible because the rims are 23 inches high. | TR20 | 30 months |
| 1.17.d | No accessible coat hook has been provided. | TR1 | 12 months |
| 1.17.e | The designated accessible toilet is inaccessible because the side grab bar is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 1.17.f | The designated accessible toilet is inaccessible because the grab bars are mounted 1¾ inches from the wall. | ST13 | 12 months |
| 1.18 | Women's Toilet Room: Second Floor Near Elevators | | |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 1.18.a | The room is inaccessible because the room sign is mounted on the door and has no raised letters and no International Symbol of Accessibility. | TR17 | 24 months |
| 1.18.b | The soap dispenser is inaccessible because it is mounted with the controls 55 inches high behind the lavatory. | TR4 | 12 months |
| 1.18.c | The designated accessible toilet is inaccessible because the centerline is 18½ inches from the side wall. | ST17 | 30 months |
| 1.18.d | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 1.18.e | No accessible coat hook has been provided. | TR1 | 12 months |
| 1.18.f | The designated accessible toilet is inaccessible because the side grab bar is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 1.18.g | The designated accessible toilet is inaccessible because the grab bars are mounted 36½ inches high. | ST12 | 12 months |
| 1.18.h | The designated accessible toilet is inaccessible because the grab bars are mounted 1¾ inches from the wall. | ST13 | 12 months |
| 1.18.i | Although there are 7 stalls, there is no ambulatory stall provided. | ST1 | 30 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 1.19 | Men's Toilet Room: Third Floor Near Elevators | | |
| 1.19.a | The room is inaccessible because the room sign has no raised or Braille characters and no International Symbol of Accessibility. | TR17 | 24 months |
| 1.19.b | The door is inaccessible because it requires more than 5 pounds to open. | D2 | 12 months |
| 1.19.c | No accessible mirror has been provided. | TR14 | 12 months |
| 1.19.d | The soap dispenser is inaccessible because it is mounted with the controls 48 inches behind the lavatory. | TR4 | 12 months |
| 1.19.e | The towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.19.f | The urinals are inaccessible because the rims are 23 inches high. | TR20 | 30 months |
| 1.19.g | No accessible coat hook has been provided. | TR1 | 12 months |
| 1.19.h | There are no grab bars provided at the toilet. | ST11 | 30 months |
| 1.20 | Women's Toilet Room: Third Floor Near Elevators | | |
| 1.20.a | The room is inaccessible because | TR17 | 24 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | the room sign has no raised or Braille characters and no International Symbol of Accessibility. | | |
| 1.20.b | The door is inaccessible because it requires more than 5 pounds to open. | D2 | 12 months |
| 1.20.c | The soap dispenser is inaccessible because it is mounted with the controls 49 inches behind the lavatory. | TR4 | 12 months |
| 1.20.d | The towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.20.e | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 1.20.f | The designated accessible toilet is inaccessible because the side grab bar is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 1.20.g | The designated accessible toilet is inaccessible because the grab bars are mounted 1 $\frac{3}{4}$ inches from the wall. | ST13 | 12 months |
| 1.20.h | The designated accessible toilet is inaccessible because the grab bars are mounted 37 inches high. | ST12 | 12 months |
| 1.20.i | Although there are 7 stalls, there is no ambulatory stall provided. | ST1 | 30 months |
| 1.21 | Georgia Center for Children: Third | | |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | Floor Single User Toilet Room | | |
| 1.21.a | The lavatory is inaccessible because the rim or counter is 27½ inches high to the bottom. | TR11 | 30 months |
| 1.21.b | The toilet is inaccessible because the far end of the side grab bar is 45 inches from the rear wall, the rear grab bar is 24 inches long, and both grab bars are mounted 1¾ inches from the wall. | SU5 | 24 months |
| 2 | COAN PARK RECREATION CENTER, located at 1530 Woodbine Ave, SE | | |
| 2.1 | Parking: Near Playground. The parking lot, with a total of 28 parking spaces, is inaccessible because none of the spaces is accessible. This lot requires 1 van accessible space. | P3 | 30 months |
| 2.2 | Exterior Accessible Route: Parking Lot To Recreation Center. The route to the entrance is inaccessible because the curb ramp from the parking area has a slope of 10.8%, a cross-slope of 3.3% and very steep side flares. | AR5 | 30 months |
| 2.3 | Gymnasium. The gymnasium is inaccessible because the entry doors have a 1½ inch high threshold. | D22 | 24 months |
| 2.4 | Drinking Fountain: Near Toilet Rooms. The drinking fountain is inaccessible because the spout is 37 inches above the finished floor. | DF6 | 24 months |

| | | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 2.5 | Toilet Rooms with Stalls. The men's and women's toilet rooms contain a number of inaccessible elements and are not accessible to people with disabilities. | ST14 | 30 months |
| 2.6 | Computer Room | | |
| 2.6.a | The door is inaccessible because it has an opening width of only 29½ inches. | D25 | 30 months |
| 2.6.b | The computers are inaccessible because the keyboards are on tables 26½ inches high. | C3 | 30 months |
| 2.7 | Parking: Pavilion. The parking is inaccessible because the signage designating parking as reserved for persons with disabilities is too low. | P6 | 12 months |
| 2.8 | Accessible Exterior Route: Parking Lot to Pavilion | | |
| 2.8.a | The route to the pavilion is inaccessible because the curb ramp from the parking area has a slope of 13.7%. | AR5 | 30 months |
| 2.8.b | The route to the pavilion is inaccessible because the ramp does not have adequate edge protection on the bottom portion, and the handrails are mounted 3½ inches from the wall. | R5 | 30 months |
| 3 | POLICE OFFICE OF PROFESSIONAL STANDARDS, located at 950 Lowery Boulevard | | |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 3.1 | Parking. The parking is inaccessible because the space marked as van accessible has a 60 inch wide access aisle. | P3 | 24 months |
| 3.2 | Exterior Accessible Route: Parking to Entrance. The route is inaccessible because the ramp has a slope of 9.3%, there is no handrail extension at the top on one side, and the handrail is mounted 5½ inches from the wall. | R5 | 30 months |
| 3.3 | Entrance. The entrance is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 3.4 | Women's Toilet Room Single-User: Lobby Area | | |
| 3.4.a | The room is inaccessible because the room sign is mounted 56 inches high and has no Braille. | TR18 | 24 months |
| 3.4.b | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 3.4.c | The room is inaccessible because the door has a ½ inch high unbeveled threshold. | D22 | 24 months |
| 3.4.d | No accessible mirror has been provided. | TR14 | 12 months |
| 3.4.e | The toilet is inaccessible because the side grab bar is mounted with its far end 48 inches from the rear wall. | SU6 | 12 months |
| 3.4.f | The toilet is inaccessible because | SU2 | 24 months |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | the rear grab bar is only 30 inches long and is obstructed by the seat cover dispenser. | | |
| 3.5 | Men's Toilet Room Single-User: Lobby Area | | |
| 3.5.a | The room is inaccessible because the room sign is mounted 56 inches high and has no Braille. | TR18 | 24 months |
| 3.5.b | The room is inaccessible because the door has a ½ inch high unbeveled threshold. | D22 | 24 months |
| 3.5.c | The toilet is inaccessible because the side grab bar is mounted with its far end 48 inches from the rear wall. | SU6 | 12 months |
| 3.6 | Interview Room #2. The pull side of the door, which is accessed from the hinge side of the door, has inadequate maneuvering space | D8 | 30 months |
| 3.7 | Men's Single-User Toilet Room: Office Area | | |
| 3.7.a | The room is inaccessible because the room sign is mounted 56 inches high and has no Braille. | TR18 | 24 months |
| 3.7.b | The room is inaccessible because the door has an unbeveled threshold greater than ¼ inch. | D22 | 24 months |
| 3.7.c | No accessible mirror has been provided. | TR14 | 12 months |

| | | | |
|--------------|----------------------------------------------------------------------------------------------------------------|------|-----------|
| 3.7.d | The toilet is inaccessible because the side grab bar is mounted with its far end 48 inches from the rear wall. | SU6 | 12 months |
| 3.8 | Women's Single-User Toilet Room: Office Area | | |
| 3.8.a | The room is inaccessible because the room sign is mounted 56 inches high and has no Braille. | TR18 | 24 months |
| 3.8.b | The room is inaccessible because the door has an unbeveled threshold greater than ¼ inch. | D22 | 24 months |
| 3.8.c | No accessible mirror has been provided. | TR14 | 12 months |
| 3.8.d | The toilet is inaccessible because the centerline is 19 inches from the side wall. | SU15 | 30 months |
| 3.8.e | The toilet is inaccessible because the flush control is on the closed side. | SU1 | 30 months |
| 3.8.f | The toilet is inaccessible because the side grab bar is mounted with its far end 48 inches from the rear wall. | SU6 | 12 months |
| 4 | ANDERSON PARK RECREATION CENTER, located at 120 Anderson Ave, NW | | |
| 4.1 | Parking | | |
| 4.1.a | Although the parking lot has a total of 29 parking spaces, there is | P3 | 30 months |

| | | | |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | no van accessible space provided, and neither designated accessible space has vertical signage. | | |
| 4.1.b | The built-up curb ramp impermissibly extends into the required accessible parking space's access aisle. | AR4 | 30 months |
| 4.2 | Main Entrance. The entrance is inaccessible because the door has hardware that requires tight pinching to open. | D1 | 24 months |
| 4.3 | Drinking Fountain: Lobby | | |
| 4.3.a | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 4.3.b | Although a designated accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |
| 4.4 | Men's Toilet Room with Stalls: Lobby | | |
| 4.4.a | The room is inaccessible because the room sign is mounted on the hinge side of the door. | TR18 | 12 months |
| 4.4.b | No accessible mirror has been provided. | TR14 | 12 months |
| 4.4.c | The soap dispenser is inaccessible because it is mounted with the controls 55 inches high over the lavatories. | TR4 | 12 months |

| | | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------|-------------|-----------|
| 4.4.d | The urinals are inaccessible because they are mounted with their rims 24 inches high and their flush controls 50 inches high. | TR20 | 30 months |
| 4.4.e | The toilet is inaccessible because the stall is 42 inches wide. | ST16 | 30 months |
| 4.4.f | The toilet is inaccessible because the centerline is 20½ inches from one side wall and 21½ inches from the other. | ST17 | 30 months |
| 4.4.g | No accessible coat hook has been provided. | TR1 | 12 months |
| 4.5 | Women's Toilet Room with Stalls: Lobby | | |
| 4.5.a | No accessible mirror has been provided. | TR14 | 12 months |
| 4.5.b | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 4.5.c | The toilet is inaccessible because the stall is 46 inches wide | ST16 | 30 months |
| 4.5.d | No accessible coat hook has been provided. | TR1 | 12 months |
| 4.6 | Gymnasium Floor. The gymnasium is inaccessible because the route onto the floor of the gymnasium contains stairs. | AR2 | 30 months |
| 4.7 | Locker Rooms. The men's and women's locker rooms contain a number of inaccessible elements. | ST14 LR1 | 30 months |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-----------|
| | | LR2 LR3 B8 | |
| 5 | A. D. WILLIAMS PARK, located at 1154 James P. Brawley Parkway, NW | | |
| 5.1 | Parking. Although the parking lot has a total of 19 parking spaces, there is no van accessible space provided, and one of the designated accessible space's access aisles has a cross slope of 4.7%. | P3 | 36 months |
| 5.2 | Exterior Accessible Route: Parking to Entrance | | |
| 5.2.a | The route to the entrance is inaccessible because the curb ramp leading from the parking lot has a slope of 12.2%. | AR5 | 30 months |
| 5.2.b | The ramp to the entrance is inaccessible because it has a cross-slope of 3.9% in one area, it has handrails on only one side, the handrail lacks extensions at the top and bottom and the ends are not rounded or returned. | R5 | 30 months |
| 5.3 | Exterior Accessible Route: To Playground. The route to the playground is inaccessible because it is covered in mulch and is not firm, stable, and slip resistant. | AR1 | 30 months |
| 5.4 | Entrances. The building does not have directional signage posted at | D16 | 24 months |

| | | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | | |
| 5.5 | Men's Toilet Room with Stalls | | |
| 5.5.a | The room is inaccessible because the room sign does not have raised or Braille characters. | TR18 | 24 months |
| 5.5.b | The toilet room is inaccessible because the route into the room narrows to 20 inches at the vent unit. | AR3 | 24 months |
| 5.5.c | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 5.5.d | No accessible mirror has been provided. | TR14 | 12 months |
| 5.5.e | The lavatory is inaccessible because the rim or counter is 28 inches high to the top. | TR11 | 24 months |
| 5.5.f | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 5.5.g | The lavatory is inaccessible because it has twist-type hardware. | TR10 | 24 months |
| 5.5.h | The urinal is inaccessible because the rim is 24 inches high. | TR20 | 30 months |

| | | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 5.5.i | The designated accessible toilet is inaccessible because its centerline is 16 inches from the side wall. | ST17 | 30 months |
| 5.5.j | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 5.5.k | The toilet paper dispenser in the designated accessible stall is inaccessible because it is mounted 43 inches from the rear wall. | ST19 | 12 months |
| 5.5.l | The toilet is inaccessible because the side grab bar is 32 inches long, with the near end 23 inches from the rear wall, it is mounted 2 inches from the side wall, and it is obstructed by the cleaning products and toilet paper rolls placed on it. | ST6 | 24 months |
| 5.5.m | The rear grab bar at the designated accessible toilet is inaccessible because it is mounted 4 inches from the rear wall. | ST13 | 12 months |
| 5.5.n | The toilet is inaccessible because the rear grab bar is obstructed by the toilet pipe and by the toilet paper rolls placed on it. | ST5 | 30 months |
| 5.6 | Women's Toilet Room with Stalls | | |
| 5.6.a | The room is inaccessible because the room sign is not mounted on the latch side of the door and does not have raised or Braille characters. | TR18 | 24 months |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 5.6.b | The toilet room is inaccessible because the route into the room narrows to 18 inches at the vent unit. | AR3 | 24 months |
| 5.6.c | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 5.6.d | No accessible mirror has been provided. | TR14 | 12 months |
| 5.6.e | The lavatory is inaccessible because the rim or counter is 28 inches high to the top. | TR11 | 24 months |
| 5.6.f | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 5.6.g | The lavatory is inaccessible because it has twist-type hardware. | TR10 | 24 months |
| 5.6.h | There is no accessible stall provided. | ST15 | 30 months |
| 6 | GATEWAY HOMELESS SERVICES CENTER, located at 275 Pryor St, SW | | |
| 6.1 | Exterior Accessible Route: Bus Stop to Entrance. The route to the entrance is inaccessible because there is no curb ramp to allow access from the street onto the sidewalk. | AR5 | 30 months |

| | | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.2 | Men's Toilet Room with Stalls: First Floor | | |
| 6.2.a | The room is inaccessible because the room sign is mounted 55 inches high to the center. | TR18 | 12 months |
| 6.2.b | The toilet paper dispenser is inaccessible because it is mounted 40 inches from the rear wall. | ST19 | 12 months |
| 6.3 | Drinking Fountains. The high drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 6.4 | Men's Shower: First Floor. The shower is inaccessible because it has grab bars on only 2 walls. | B8 | 30 months |
| 6.5 | Women's Single-User Toilet Room | | |
| 6.5.a | The room is inaccessible because the room sign is mounted 55 inches high to the center. | TR18 | 12 months |
| 6.5.b | No accessible coat hook has been provided. | TR1 | 12 months |
| 6.6 | Intake Counter. The counter is inaccessible because it is 42½ inches high. | C6 | 30 months |
| 6.7 | Men's Toilet Room with Stalls: First Floor North Wing | | |
| 6.7.a | The room is inaccessible because the sign is mounted 56½ inches high to the center. | TR18 | 12 months |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.7.b | The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 6.8 | Women's Toilet Room with Stalls: First Floor North Wing | | |
| 6.8.a | The room is inaccessible because the sign is mounted 56½ inches high to the center. | TR18 | 12 months |
| 6.8.b | The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 6.9 | Drinking Fountains: First Floor North. The lower drinking fountain is inaccessible because it has 26 inches of knee height. | DF5 | 24 months |
| 6.10 | Elevators: First Floor East Bank | | |
| 6.10.a | The elevator is inaccessible because the hall lanterns do not signal once for up and twice for down. | E11 | 30 months |
| 6.10.b | The elevator is inaccessible because the hoistway signage is mounted 61½ inches high. | E12 | 30 months |
| 6.11 | Women's and Children's Center: First Floor. The counter is inaccessible because it is 42½ inches high. | C6 | 30 months |
| 6.12 | Bedroom #150: First Floor. The door is inaccessible because knob hardware is used. | D1 | 24 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------|------|-----------|
| 6.13 | Bedroom #149: First Floor. The door is inaccessible because knob hardware is used. | D1 | 24 months |
| 6.14 | Women's Shower Room: First Floor | | |
| 6.14.a | The room is inaccessible because the sign is mounted 57 inches high to the center. | TR18 | 12 months |
| 6.14.b | No accessible coat hook is provided in the designated accessible toilet stall. | TR1 | 12 months |
| 6.14.c | The shower is inaccessible because it has grab bars on only 2 walls. | B8 | 30 months |
| 6.15 | Men's Dormitory Reception: Second Floor. The counter is inaccessible because it is 42½ inches high. | C6 | 30 months |
| 6.16 | Unisex Locker Room: Second Floor Men's Dorm Eastside | | |
| 6.16.a | The room is inaccessible because the sign is mounted 57 inches high to the center. | TR18 | 12 months |
| 6.16.b | The lockers are inaccessible because the hardware requires tight grasping to operate. | LR3 | 30 months |
| 6.16.c | The designated accessible toilet is inaccessible because its centerline is 17 inches from the side wall. | ST17 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.16.d | The shower is inaccessible because it has grab bars on only 2 walls. | B8 | 30 months |
| 6.17 | Sleeping Pods. None of the tables provides the required knee space to accommodate a person in a wheelchair. | PD3 | 30 months |
| 6.18 | Unisex Locker Room: Second Floor Men's Dorm Westside | | |
| 6.18.a | The room is inaccessible because the sign is mounted 54 inches high to the center. | TR18 | 12 months |
| 6.18.b | The shower is inaccessible because it has grab bars on only 2 walls. | B8 | 30 months |
| 6.19 | Clinic Room 202A: Second Floor | | |
| 6.19.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 6.19.b | There is no signage directing people with disabilities to the accessible toilet rooms. | TR16 | 24 months |
| 6.20 | Unisex Single-User Toilet Room/Shower: Third Floor Men's Dorm | | |
| 6.20.a | The room is inaccessible because the sign is mounted 55 inches high to the center. | TR18 | 12 months |
| 6.20.b | The shower is inaccessible because it has grab bars on only 2 | B8 | 30 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | walls. | | |
| 6.21 | Unisex Single-User Toilet Room/Shower: Fourth Floor Men's Dorm | | |
| 6.21.a | The room is inaccessible because the sign is mounted 57 inches high to the center. | TR18 | 12 months |
| 6.21.b | The toilet paper dispenser is inaccessible because it is mounted 40 inches from the rear wall. | SU17 | 12 months |
| 6.21.c | The shower is inaccessible because it has grab bars on only 2 walls. | B8 | 30 months |
| 7 | ATLANTA FIRE STATION 31, located at 2406 Fairburn Road, SW | | |
| 7.1 | Main Entrance. The entrance is inaccessible because it does not have level maneuvering clearance, there is only 8 inches of clearance on the latch side, pull side, the threshold is 1¼ inches high, and there is knob hardware. | D17 | 30 months |
| 7.2 | Accessible Route: Public Entrance through Truck Bay to Toilet Rooms | | |
| 7.2.a | The route is inaccessible because it is less than 36 inches wide. | AR3 | 24 months |
| 7.2.b | There is equipment on the truck that protrudes into the walkway and is not detectable to blind | AR8 | 12 months |

| | | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | persons using a cane. | | |
| 7.3 | Unisex Single-User Toilet Room. The toilet room contains a number of inaccessible elements and is not accessible to people with disabilities. | SU13 | 30 months |
| 8 | GEORGIA HILL NEIGHBORHOOD FACILITY, located at 250 Georgia Avenue, SE | | |
| 8.1 | Parking Lot. The parking lot, with a total of 89 parking spaces, is inaccessible because it only has 3 spaces designated as accessible, there is no van accessible space, there are no access aisles, and the signs are mounted too low. This lot requires 1 van accessible space and 3 standard accessible spaces. | P3 | 30 months |
| 8.2 | Exterior Accessible Route: Parking to Main Entrance | | |
| 8.2.a | The route is inaccessible because the curb ramp from the parking area onto the sidewalk has a slope of 16% and side flares that slope 33.7% and 46.1%. | AR5 | 30 months |
| 8.2.b | The route is inaccessible because the walk leading to the entrance has a cross slope of 3.7% and a slope between 5.6% and 6.5% and has no ramp features. | R5 | 30 months |
| 8.3 | Interior Signage. The signage provided throughout the facility is mounted above the door or on the | D26 | 30 months |

| | | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | door and does not have raised or Braille characters. | | |
| 8.4 | Alarms. Although the facility contains an emergency alarm system, the alarm system is inaccessible because visual alarms are not provided in all hallways, corridors or toilet rooms. | AL1 | 30 months |
| 8.5 | Interior Accessible Route: First Floor Hallway. The fire extinguisher protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.6 | Welcome Desk: First Floor | | |
| 8.6.a | The counter is inaccessible because it is 43 inches high. | C6 | 30 months |
| 8.6.b | The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.7 | Women's Toilet Room with Stalls: First Floor | | |
| 8.7.a | The door is inaccessible because it requires 6 pounds of force to open. | D2 | 12 months |
| 8.7.b | No accessible mirror has been provided. | TR14 | 12 months |
| 8.7.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.7.d | The designated accessible stall is | ST1 | 30 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | | |
| 8.8 | Men's Toilet Room with Stalls: First Floor | | |
| 8.8.a | The door is inaccessible because it requires 6 pounds of force to open. | D2 | 12 months |
| 8.8.b | The light switch is inaccessible because it is mounted 68 inches high. | TR5 | 12 months |
| 8.8.c | No accessible mirror has been provided. | TR14 | 12 months |
| 8.8.d | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.8.e | The urinals are inaccessible because they are 22 inches high to the rim and 45¾ inches high to the flush control. | TR20 | 30 months |
| 8.8.f | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST1 | 30 months |
| 8.9 | Day Care: First Floor. The door is inaccessible because it requires 9 pounds of force to open. | D2 | 12 months |
| 8.10 | Boys Toilet Rooms with Stalls: First Floor Day Care | | |
| 8.10.a | The door is inaccessible because | D25 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | it has an opening width of only 27 inches. | | |
| 8.10.b | The toilet room contains a number of inaccessible elements and is not accessible to people with disabilities. | ST14 | 30 months |
| 8.11 | Girls Toilet Rooms with Stalls: First Floor Day Care | | |
| 8.11.a | The door is inaccessible because it has an opening width of only 27 inches. | D25 | 30 months |
| 8.11.b | The toilet room contains a number of inaccessible elements and is not accessible to people with disabilities. | ST14 | 30 months |
| 8.12 | Library: First Floor | | |
| 8.12.a | The tables are inaccessible because they are 24½ inches high to the bottom. | L4 | 24 months |
| 8.12.b | The check-out area is inaccessible because the counter is 39 inches high. | L2 | 30 months |
| 8.12.c | The book stacks are inaccessible because the space between stacks is only 32 inches wide. | L5 | 24 months |
| 8.13 | Elevators | | |
| 8.13.a | The elevator is inaccessible because the hall call buttons do not have visual signals indicating when calls are registered or | E3 | 30 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | answered. | | |
| 8.13.b | The elevator is inaccessible because the emergency communications are not identified by raised or Braille symbols, and the system does not work without voice communication. | E8 | 30 months |
| 8.14 | Women's Toilet Room with Stalls: Second Floor | | |
| 8.14.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 8.14.b | The light switch is inaccessible because it is mounted 70½ inches high. | TR5 | 12 months |
| 8.14.c | No accessible mirror has been provided. | TR14 | 12 months |
| 8.14.d | The paper towel dispenser is inaccessible because it is mounted with the controls 59 inches high. | TR5 | 12 months |
| 8.14.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 8.15 | Men's Toilet Room with Stalls: Second Floor | | |
| 8.15.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 8.15.b | The light switch is inaccessible because it is mounted 69½ inches high. | TR5 | 12 months |
| 8.15.c | No accessible mirror has been provided. | TR14 | 12 months |
| 8.15.d | The urinals are inaccessible because the rims are 22 inches high and the flush controls are 45 inches high. | TR20 | 30 months |
| 8.15.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 12 months |
| 8.16 | Women's Toilet Room with Stalls: Third Floor | | |
| 8.16.a | The door is inaccessible because it requires 13 pounds of force to open. | D2 | 12 months |
| 8.16.b | The light switch is inaccessible because it is mounted 74 inches high. | TR5 | 12 months |
| 8.16.c | No accessible mirror has been provided. | TR14 | 12 months |
| 8.16.d | The paper towel dispenser is inaccessible because it is mounted with the controls 59 inches high. | TR5 | 12 months |
| 8.16.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 8.17 | Men's Toilet Room with Stalls: Third Floor | | |
| 8.17.a | The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 8.17.b | The light switch is inaccessible because it is mounted 69½ inches high. | TR5 | 12 months |
| 8.18 | No accessible mirror has been provided. | TR14 | 12 months |
| 8.18.a | The urinals are inaccessible because the rims are 24 inches high and the flush controls are 45½ inches high. | TR20 | 30 months |
| 8.18.b | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 9 | M. L. K. NATATORIUM, located at 70 Boulevard Street, NE | | |
| 9.1 | Entrances. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 24 months |
| 9.2 | Accessible Route: To Pool Bleachers. The route to the bleachers at the pool is inaccessible because it contains a 1 inch high step | AR2 | 24 months |
| 9.3 | Elevators | | |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------|------|-----------|
| 9.3.a | The elevator is inaccessible because the hall call buttons are centered 41 inches high. | E3 | 30 months |
| 9.3.b | The elevator is inaccessible because hoistway signage is not provided on both door jambs. | E12 | 30 months |
| 9.3.c | The elevator is inaccessible because the doors do not reopen automatically when obstructed. | E6 | 30 months |
| 9.4 | Women's Locker Room | | |
| 9.4.a | The door is inaccessible because it requires 13 pounds of force to open. | D2 | 12 months |
| 9.4.b | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 9.4.c | The designated accessible toilet is inaccessible because the top of the seat is 20 inches high. | ST20 | 30 months |
| 9.4.d | The designated accessible toilet is inaccessible because the centerline is 22¼ inches from the side wall. | ST17 | 30 months |
| 9.4.e | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 9.4.f | No accessible coat hook has been provided. | TR1 | 12 months |
| 9.4.g | The designated accessible toilet is inaccessible because there are no | ST11 | 12 months |

| | | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | grab bars. | | |
| 9.4.h | There is no accessible shower provided. | B8 | 30 months |
| 9.4.i | No accessible towel hook has been provided. | TR1 | 12 months |
| 9.5 | Men's Locker Room | | |
| 9.5.a | The door is inaccessible because it requires 12 pounds of force to open. | D2 | 12 months |
| 9.5.b | The air dryers protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 9.5.c | The urinals are inaccessible because they are mounted with the rims 19 inches high and the flush controls 46 inches high. | TR20 | 30 months |
| 9.5.d | There is no accessible toilet stall provided. | ST15 | 30 months |
| 9.5.e | There is no accessible shower provided. | B8 | 30 months |
| 9.5.f | No accessible towel hook has been provided. | TR1 | 12 months |
| 9.6 | Drinking Fountain: Lower Level. Although a designated accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 9.7 | Exterior Accessible Route: Public Access to Future Entrance. Although the route slopes 6.3% and must therefore be constructed as a ramp, there are handrails on only one side and there is a cross slope of 9.9%. | R3 | 30 months |
| 10 | BASS RECREATION CENTER, located at 326 Moreland Avenue, NE | | |
| 10.1 | Parking Lot: Upper Level | | |
| 10.1.a | The parking lot is inaccessible because there are no access aisles provided. | P1 | 24 months |
| 10.1.b | The parking lot is inaccessible because there is no van accessible space provided. | P3 | 24 months |
| 10.2 | Ramp: Main Entrance. The ramp is inaccessible because the lower section slopes 9.2%, the handrails lack extensions, the handrail ends are not rounded or returned, and the handrails do not have a diameter of 1¼ to 1½ inches. | R5 | 30 months |
| 10.3 | Main Entrance. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 12 months |
| 10.4 | Multi-Purpose Room. No accessible coat hook has been provided. | TR1 | 12 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 10.5 | Drinking Fountain: Main Floor | | |
| 10.5.a | Although a designated accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |
| 10.5.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 10.6 | Women's Toilet Room with Stalls: Main Floor | | |
| 10.6.a | The door is inaccessible because it requires 9 pounds of force to open. | D2 | 12 months |
| 10.6.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 10.6.c | No accessible mirror has been provided. | TR14 | 12 months |
| 10.6.d | The designated accessible toilet is inaccessible because there is insufficient clear floor space. | ST18 | 30 months |
| 10.6.e | The designated accessible toilet is inaccessible because the centerline is 19 inches from the side wall. | ST17 | 30 months |
| 10.6.f | No accessible coat hook has been provided. | TR1 | 12 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 10.6.g | The designated accessible toilet is inaccessible because the side grab bar is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 10.6.h | There is no rear grab bar provided at the designated accessible toilet. | ST3 | 30 months |
| 10.7 | Men's Toilet Room with Stalls: Main Floor | | |
| 10.7.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 10.7.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 10.7.c | No accessible mirror has been provided. | TR14 | 12 months |
| 10.7.d | The urinal is inaccessible because the rim is 18 inches high. | TR20 | 30 months |
| 10.7.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 11 | CHASTAIN PARK AMPHITHEATER, located at 4469 Stella Drive, NW | | |
| 11.1 | Parking Lot | | |
| 11.1.a | There is no van accessible parking space provided. | P3 | 24 months |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 11.1.b | The parking is inaccessible because the spaces reserved for persons with disabilities are 88 inches wide, and the access aisles are 56 inches wide. | P8 | 24 months |
| 11.1.c | The curb ramp from parking to the entrance is inaccessible because it slopes 12% and has a cross slope of 6.1% | AR5 | 30months |
| 11.2 | Concession Counter: Near Seating. The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 11.3 | Starbucks and Whole Foods Counter | | |
| 11.3.a | The route to the Starbucks and Whole Foods counter is inaccessible because it contains many steps. | AR1 | 30 months |
| 11.3.b | The retail counter is inaccessible because it is 44 inches high. | C5 | 30 months |
| 11.4 | Winery Area and Sun Room Bar. The routes to the Winery area and Sun Room bar are inaccessible because they contain steps and gravel. | AR1 | 30 months |
| 11.5 | Drinking Fountains: Near Toilet Rooms. The higher drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 11.6 | Men's Toilet Room with Stalls: Near Entrance | | |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 11.6.a | The room is inaccessible because the sign is not mounted in an accessible location and does not have raised or Braille characters. | TR17 | 24 months |
| 11.6.b | The toilet room contains a number of inaccessible elements and is currently being renovated. | ST14 | 30 months |
| 11.7 | Women's Toilet Room with Stalls: Near Entrance | | |
| 11.7.a | The room is inaccessible because the sign is not mounted in an accessible location and does not have raised or Braille characters. | TR17 | 24 months |
| 11.7.b | The paper towel dispensers are inaccessible because they are mounted with the controls 60½ inches high. | TR5 | 12 months |
| 11.7.c | No accessible coat hook has been provided in the pink designated accessible stall. | TR1 | 12 months |
| 11.7.d | The side grab bar in the pink designated accessible stall is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 11.7.e | The toilet centerline in the grey designated accessible stall is 17 inches from the side wall. | ST17 | 30 months |
| 11.7.f | The side grab bar in the grey designated accessible stall is 38 inches high. | ST12 | 12 months |
| 11.7.g | Although there are 26 stalls, there is no ambulatory stall provided. | ST1 | 30 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 11.8 | Amphitheater | | |
| 11.8.a | The amphitheater, containing 6839 seats, is inaccessible because it does not have sufficient accessible seats and does not have fixed companion seats next to each wheelchair location. A total of 69 wheelchair seating areas is required. | AA6 | 30 months |
| 11.8.b | The amphitheater is inaccessible to people with hearing disabilities because, although there are more than 50 fixed seats, there is no assistive listening system provided. This amphitheater requires 274 receivers. | AA4 | 30 months |
| 11.8.c | The amphitheater is inaccessible because there is no accessible route connecting the wheelchair seating areas and the stage. | AA1 | 30 months |
| 11.8.d | The newly constructed concession stand has no accessible features. | C5 | 12 months |
| 12 | PITTMAN POOL/RECREATION CENTER, located at 4950 Garibaldi Street, SE | | |
| 12.1 | Parking Lot. The parking lot, with a total of 29 parking spaces, is inaccessible because it only has 1 space designated as accessible. This lot requires 1 van accessible space and 1 standard accessible space. | P3 | 30 months |
| 12.2 | Main Entrance | | |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12.2.a | The curb ramp at the main entrance drop off area is inaccessible because it has a slope of 14.1% and a cross slope of 7.9%. | AR5 | 30 months |
| 12.2.b | The entrance is inaccessible because the threshold is 2¼ inches high. | D22 | 24 months |
| 12.3 | Arts and Crafts. The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 12.4 | Drinking Fountain: Multi-Purpose Room. Although an accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |
| 12.5 | Women's Toilet Room with Stalls: Upper Level | | |
| 12.5.a | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 12.5.b | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 12.5.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.6 | Men's Toilet Room with Stalls: Upper Level | | |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12.6.a | The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 12.6.b | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 12.6.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.7 | Elevator | | |
| 12.7.a | The elevator is inaccessible because the hall call buttons are mounted 39 inches high. | E3 | 30 months |
| 12.7.b | The elevator is inaccessible because the emergency system requires voice communication. | E8 | 30 months |
| 12.8 | Ramp: Lower Level From Exit to Pool Deck. The ramp is inaccessible because the lower portion slopes 10%, the upper portion slopes 13.8%, there is a handrail on only one side, the handrail is 29 inches high, it lacks extensions, and it does have ends that are rounded or returned. | R5 | 30 months |
| 12.9 | Gymnasium. The gymnasium is inaccessible because the threshold at the door is 2½ inches high. | D22 | 24 months |
| 12.10 | Men's Locker Room: Lower Level | | |

| | | | |
|----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12.10.a | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 12.10.b | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 12.10.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.10.d | The shower is inaccessible because it is incorrect dimensions, there are grab bars on only 2 walls, and the shower spray unit is fixed at more than 48 inches high. | B8 | 30 months |
| 12.10.e | The benches are inaccessible because they are too narrow and are not attached at the wall. | LR1 | 30 months |
| 12.11 | Women's Locker Room: Lower Level | | |
| 12.11.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 12.11.b | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 12.11.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 12.11.d | The shower is inaccessible because it is 48 inches deep and | B8 | 30 months |

| | | | |
|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | 47 inches wide, there are grab bars on only 2 walls, and the shower spray unit cannot be fixed. | | |
| 12.11.e | The benches are inaccessible because they are too narrow and are not attached at the wall. | LR1 | 30 months |
| 13 | PEACHTREE HILLS RECREATION CENTER, located at 308 Peachtree Hills Road, NE | | |
| 13.1 | Route: Parking Lot to Main Entrance | | |
| 13.1.a | The route is inaccessible because the curb ramp has a slope of 9.3% and a cross slope of 4.7%. | AR5 | 30 months |
| 13.1.b | The route is inaccessible because the walk to the entrance slopes 7.8%, with a cross slope of 4.8%, and it has no ramp features | R3 | 30 months |
| 13.2 | Entrances. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 24 months |
| 13.3 | Men's Toilet Room with Stalls: First Floor | | |
| 13.3.a | The room is inaccessible because the sign is mounted on the hinge side of the door. | TR18 | 12 months |
| 13.3.b | The door is inaccessible because it requires 12 pounds of force to open. | D2 | 12 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 13.3.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 13.3.d | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 13.3.e | The lavatory is inaccessible because it has twist hardware. | TR10 | 24 months |
| 13.3.f | The urinal is inaccessible because the rim is 18 inches high. | TR20 | 30 months |
| 13.3.g | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 13.3.h | The toilet paper dispenser is inaccessible because it is mounted 42 inches from the rear wall. | ST19 | 12 months |
| 13.4 | Women's Toilet Room with Stalls: First Floor | | |
| 13.4.a | The door is inaccessible because it requires 11 pounds of force to open. | D2 | 12 months |
| 13.4.b | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 13.4.c | The soap dispenser is inaccessible because it is mounted with the controls 55 inches high | TR5 | 12 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 13.4.d | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 13.4.e | The toilet paper dispenser is inaccessible because it is mounted 44 inches from the rear wall. | ST19 | 12 months |
| 13.5 | Main Lobby. The underside of the stairs creates an overhead hazard for people with vision disabilities. | AR7 | 30 months |
| 14 | CENTRAL PARK RECREATION CENTER, located at 400 Merritt Avenue, NE | | |
| 14.1 | Central Park Recreation Center is currently under renovation. Ensure that the facility is fully accessible in accordance with the Standards when renovations are complete. 28 C.F.R. § 35.151. | | |

ATTACHMENT K: Program Access in Existing Facilities

Please Note: Paragraph 42 of the Agreement requires that within three months of the effective date of this Agreement, the City will provide signage as necessary to comply with 28 C.F.R. § 35.163(b), after having surveyed all facilities that are the subject of this Agreement for the purpose of identifying those that have multiple entrances not all of which are accessible.

The technical requirements and, where appropriate, the scoping requirements of the Standards are used as a guide for determining whether a program or activity held in an existing facility is “readily accessible to and usable by” persons with disabilities and for determining what changes are necessary to make this program or activity accessible if it continues to be provided in the existing facility in question. See 28 C.F.R. §§ 35.150(b)(1), 35.151.

In order to ensure that each of the City’s programs, services, and activities operating at a facility that is the subject of this Agreement, when viewed in its entirety, is readily accessible to and usable by persons with mobility impairments, the City will take the actions referenced by the alphanumeric code and described in detail in Attachment M to this Settlement Agreement. Actions are to be completed before the end of the time specified in the Completion Date column.

| Item # | Access Issue | Required Action | Completion Date |
|---------------|-------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------|
| 1 | CITY HALL SOUTH, located at 55 Trinity Avenue | | |
| 1.1 | Interior Signage. Much of the signage provided is inaccessible because it does not have raised or Braille characters. | D26 | 24 months |
| 1.2 | Interior Doors. Many of the interior doors are inaccessible because they require more than 5 pounds of force to open. | D2 | 12 months |
| 1.3 | Assistive Listening Systems. There are a number of conference rooms, council chambers, committee rooms, etc., but there | AA5 | 30 months |

| | | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | are no assistive listening systems provided. | | |
| 1.4 | Women's Toilet Rooms with Stalls: Ground Floor | | |
| 1.4.a | The toilet room sign lacks the International Symbol of Accessibility and does not have raised or Braille characters. | TR17 | 24 months |
| 1.4.b | The seat cover dispenser is inaccessible because it is mounted 64 inches high. | TR5 | 12 months |
| 1.4.c | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.4.d | The lavatory is inaccessible because the rim or counter is 27 inches high to the bottom. | TR11 | 24 months |
| 1.4.e | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 1.4.f | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 1.5 | Men's Toilet Rooms with Stalls: Ground Floor | | |
| 1.5.a | The toilet room sign lacks the International Symbol of | TR17 | 24 months |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | Accessibility and does not have raised or Braille characters. | | |
| 1.5.b | The seat cover dispenser is inaccessible because it is mounted 60 inches high. | TR5 | 12 months |
| 1.5.c | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.5.d | The lavatory is inaccessible because the rim or counter is 27¼ inches high to the bottom. | TR11 | 24 months |
| 1.5.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 1.6 | Drinking Fountains: Ground Floor. The drinking fountain is inaccessible because it requires 11 pounds of force to operate. | DF2 | 12 months |
| 1.7 | Ramp To Stage: 1 st Floor. The ramp is inaccessible because the handrails do not have extensions at the top and bottom, they are mounted 2 inches from the wall, and the ends are not rounded or returned. | R4 | 30 months |
| 1.8 | Department of Finance. The counter is inaccessible because it is 40½ inches high. | C6 | 24 months |
| 1.9 | Contract Compliance Room 1700. The pull side of the door, | D6 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | which is accessed through a front approach, has 8½ inches of clearance on the latch side. | | |
| 1.10 | Water Department Reception. The Water Department Reception counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 30 months |
| 1.11 | Unisex Single-User Toilet Room 1 st Floor: By Room 1450 | | |
| 1.11.a | The toilet room door swings into the required clear floor space at the lavatory. | TR6 | 30 months |
| 1.11.b | No accessible mirror has been provided. | TR14 | 12 months |
| 1.11.c | The seat cover dispenser is inaccessible because it is mounted with the controls 58 inches high. | TR5 | 12 months |
| 1.11.d | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.11.e | The lavatory is inaccessible because the rim or counter is 26¾ inches high to the bottom. | TR11 | 24 months |
| 1.11.f | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 1.11.g | The toilet is inaccessible because the centerline is 22 inches from the side wall. | SU15 | 30 months |
| 1.11.h | The toilet is inaccessible because the flush control is on the closed side. | SU1 | 30 months |
| 1.11.i | The side grab bar at the toilet is inaccessible because it is obstructed by the toilet paper dispenser. | SU7 | 12 months |
| 1.11.j | The toilet is inaccessible because both rear grab bars are 24 inches long; one grab bar is approximately 47 inches high and is mounted with the near end more than 6 inches from the side wall; and the other grab bar is obstructed by the flush valve and the higher grab bar and is mounted $\frac{3}{4}$ inches from the wall where it is bent around the pipe. | SU2 | 30 months |
| 1.12 | Unisex Single-User Toilet Room 1 st Floor: By Room 1750 | | |
| 1.12.a | The toilet room door swings into the required clear floor space at the lavatory. | TR6 | 24 months |
| 1.12.b | No accessible mirror has been provided. | TR14 | 12 months |
| 1.12.c | The paper towel dispenser protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 1.12.d | The lavatory is inaccessible | TR11 | 24 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | because the rim or counter is 25½ inches high to the bottom. | | |
| 1.12.e | The side grab bar at the toilet is inaccessible because it is obstructed by the toilet paper dispenser. | SU7 | 12 months |
| 1.12.f | The toilet is inaccessible because both rear grab bars are 24 inches long; one grab bar is approximately 47 inches high; and the other grab bar is obstructed by the flush valve and the higher grab bar and is mounted ¾ inches from the wall where it is bent around the pipe | SU2 | 30 months |
| 1.13 | Drinking Fountains 1 st Floor: West Side By Room 1450. The drinking fountain is inaccessible because the height of the water flow is 1 inch, and the controls require 9 pounds of force to operate. | DF1 | 12 months |
| 1.14 | Drinking Fountains 1 st Floor: East Side By Room 1750. The drinking fountain is inaccessible because the controls require 9 pounds of force to operate. | DF2 | 12 months |
| 1.15 | 1 st Floor: Procurement Room 1790. The counter is inaccessible because it is 43½ inches high. | C6 | 24 months |
| 1.16 | 1 st Floor: Constituent Services Room 1920 | | |
| 1.16.a | The counter is inaccessible because it is 43 inches high. | C6 | 24 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 1.16.b | The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 1.17 | 1 st Floor: Conference Room 1900. The pull side of the door, which is accessed through a front approach, has only 8 inches of clear space on the latch side. | D6 | 24 months |
| 1.18 | Elevators: Cab 2. The elevator is inaccessible because the hoistway signage does not have Braille. | E12 | 24 months |
| 1.19 | 2 nd Floor: Council Chambers | | |
| 1.19.a | The Council Chamber, containing 230 fixed seats, is inaccessible because no wheelchair seating areas are provided. A total of 4 wheelchair seating areas is required. | AA6 | 30 months |
| 1.19.b | The ramp to the council platform is inaccessible because it has a slope of 12.2% near the top, a landing 38 inches by 42 inches at the change in direction, and the handrails are 31 inches high and mounted 2½ inches from the wall. | R3 | 30 months |
| 1.20 | Accessible Route 2 nd Floor: From Elevators to Conference Room #1. The defibrillator protrudes into the walkway and would not be detectable to a blind person using a cane. | AR8 | 12 months |
| 1.21 | Women's and Men's Toilet Room with Stalls: 2 nd Floor East and | TR16 | 12 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | West Side. The toilet rooms lack accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | | |
| 1.22 | 3 rd Floor: HVAC Division Room 3700 | | |
| 1.22.a | The pull side of the door, which is accessed through a front approach, has 14½ inches of clear space on the latch side. | D6 | 24 months |
| 1.22.b | The counter is inaccessible because it is 43 inches high. | C6 | 24 months |
| 1.22.c | The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 1.23 | 3 rd Floor: Helen Smith, Arborist | | |
| 1.23.a | The counter is inaccessible because it is 43 inches high. | C6 | 24 months |
| 1.23.b | The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 1.24 | 3 rd Floor: Main Electrical. The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 1.25 | 3 rd Floor: Bureau of Buildings Room 3900. The computer desks are inaccessible because they do not have sufficient knee space. | C3 | 24 months |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 1.26 | 3 rd Floor: Bureau of Planning Room 3350. The courtesy phone is inaccessible because it is mounted 60 inches high. | TR5 | 12 months |
| 1.27 | 3 rd Floor: Housing Code Enforcement Room 3450 | | |
| 1.27.a | The counter is inaccessible because it is 42½ inches high. | C6 | 24 months |
| 1.27.b | The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 1.28 | Unisex Single-User Toilet Room 3 rd Floor Near Room 3800. The toilet room lacks accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | TR16 | 12 months |
| 1.29 | Unisex Single-User Toilet Room 3 rd Floor Near Room 3450. The toilet room lacks accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | TR16 | 12 months |
| 1.30 | Drinking Fountain 4 th Floor: Near Room 4700. The drinking fountain is inaccessible because the controls require 9 pounds of force to operate. | DF2 | 24 months |
| 1.31 | Unisex Single-User Toilet Room 4 th Floor Near Room 4800. The | TR16 | 12 months |

| | | | |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | toilet room lacks accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | | |
| 1.32 | 4 th Floor: Public Works Department (Under Construction). The counter is inaccessible because it is 44 inches high. | C6 | 24 months |
| 1.33 | 4 th Floor: Sanitary Services Room 4800. The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 1.34 | 4 th Floor: Traffic and Transportation Room 4900. The counter is inaccessible because it is 42 inches high. | C6 | 24 months |
| 1.35 | Drinking Fountains 4 th Floor: Near Room 4400. The drinking fountain is inaccessible because the controls require 20 pounds of force to operate. | DF2 | 12 months |
| 1.36 | Women's Toilet Room With Stalls 4 th Floor Near Room 4400. The toilet room lacks accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | TR16 | 12 months |
| 1.37 | Men's Toilet Room With Stalls 4 th Floor Near Room 4400. The toilet room lacks accessible directional | TR16 | 12 months |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | | |
| 2 | ATLANTA CITY HALL TOWER, located at 68 Mitchell St., NW | | |
| 2.1 | Entrances. The accessible entrances are locked at all times, and a call button is provided. | D14 | 24 months |
| 2.2 | Interior Doors. Many of the interior doors throughout the facility are inaccessible because they require more than 5 pounds of force to open. | D2 | 24 months |
| 2.3 | Interior Signage. The signage provided throughout the facility is inaccessible because it lacks raised and Braille characters. | D26 | 24 months |
| 2.4 | Interior Routes. The AED's throughout the facility protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 2.5 | Elevators 2 and 3 | | |
| 2.5.a | The elevators are inaccessible because the hall lanterns provide no audible arrival signal on some floors. | E11 | 24 months |
| 2.5.b | The elevator is inaccessible because the hall call buttons are mounted 38½ inches high on some floors. | E3 | 24 months |

| | | | |
|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 2.5.c | The elevator is inaccessible because the hoistway signage is mounted 47 inches high. | E12 | 24 months |
| 2.5.d | The elevator is inaccessible because the emergency communications system is not identified by raised lettering, the door requires tight grasping to open, and the handset cord is less than 29 inches long. | E8 | 24 months |
| 2.6 | Exterior Route: From Corner of Mitchell & Washington to Entrance Ramp. The route is inaccessible because it has uneven and broken pavement, and it slopes between 6.4% and 8.1% without having any ramp features. | AR1 | 30 months |
| 2.7 | Exterior Ramp: To City Hall Tower Washington St. Entrance. The ramp is inaccessible because it slopes 9.1% at the bottom and 10.9% at the top, there is no edge protection at the drop off sides, and the handrails lack 12 inch long extensions at the bottom. | R5 | 30 months |
| 2.8 | Drinking Fountains 2 nd Floor | | |
| 2.8.a | Both drinking fountains are inaccessible because the flow of water is less than 4 inches high. | DF7 | 12months |
| 2.8.b | The drinking fountains protrude into the walkway and are not detectable to blind persons using a cane. | AR8 | 12 months |
| 2.9 | Women's Toilet Room With Stalls | | |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | 3 rd Floor | | |
| 2.9.a | The seat cover dispenser is inaccessible because it is mounted 62 inches above the finished floor. | TR5 | 12 months |
| 2.9.b | The lavatory is inaccessible because the rim or counter is 26½ inches high to the bottom. | TR11 | 24 months |
| 2.9.c | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 2.9.d | The side grab bar at the designated accessible toilet is inaccessible because it is mounted 2 inches from the side wall and with the far end 45 inches from the rear wall. | ST6 | 12 months |
| 2.9.e | The rear grab bar at the toilet is inaccessible because it is 33 inches long, it is obstructed by the flush valve, and it is mounted a varying distance from the rear wall. | ST3 | 30 months |
| 2.10 | Men's Toilet Room With Stalls 3 rd Floor | | |
| 2.10.a | The seat cover dispenser is inaccessible because it is mounted 62 inches above the finished floor. | TR5 | 12 months |
| 2.10.b | The lavatory is inaccessible because the rim or counter is 26½ | TR11 | 24 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | inches high to the bottom. | | |
| 2.10.c | The urinal is inaccessible because its rim is 22 inches above the finished floor. | TR20 | 24 months |
| 2.10.d | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 2.10.e | The side grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 2.10.f | The side grab bar at the designated accessible toilet is inaccessible because it is 35 inches long and is mounted a varying distance from the side wall with the far end 38½ inches from the rear wall. | ST6 | 24 months |
| 2.10.g | The rear grab bar at the toilet is inaccessible because it is 33 inches long, is obstructed by the flush valve, and is mounted a varying distance from the rear wall. | ST3 | 24 months |
| 2.11 | 3 rd Floor: HR Policy and Planning Room 3200. The door is inaccessible because it has knob hardware. | D1 | 24 months |
| 2.12 | 3 rd Floor: Auditorium Room 3100. The auditorium is inaccessible because it has no assistive listening system provided. | AA5 | 24 months |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 2.13 | Drinking Fountain 4 th Floor | | |
| 2.13.a | The drinking fountain is inaccessible because the controls require 8 pounds of force to operate. | DF2 | 12 months |
| 2.13.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 2.14 | Men's Single-User Toilet Room 4 th Floor Near Snack Bar Area. The toilet room lacks accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | T16 | 12 months |
| 2.15 | Women's Single-User Toilet Room 4 th Floor Near Snack Bar Area. The toilet room lacks accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | TR16 | 12 months |
| 2.16 | 5 th Floor: Law Department Suite 5100 | | |
| 2.16.a | The exit sign protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 2.16.b | The drinking fountain is inaccessible because the control requires 6 pounds of force to operate. | DF2 | 12 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 2.16.c | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 2.17 | Inaccessible 5 th Floor Toilet Rooms. The toilet rooms lack accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | TR16 | 24 months |
| 2.18 | Drinking Fountain 5 th Floor Atrium: East. The drinking fountain is inaccessible because the water flow is less than 4 inches high. | DF7 | 12 months |
| 2.19 | 6 th Floor: Accounts Payable Suite 6100 | | |
| 2.19.a | The exit sign protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 2.19.b | The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 2.19.c | The route to room 6190 is inaccessible because it narrows to 28½ inches wide. | AR3 | 24 months |
| 3 | CYCLORAMA & CIVIL WAR MUSEUM, located at 800-C Cherokee Ave, SE | | |
| 3.1 | Parking. In the parking lot, with a total of 316 parking spaces, all of the rear tier of designated | P3 | 30 months |

| | | | |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | accessible parking spaces have "Van-Accessible" signage, although 5 of the spaces do not have van accessible access aisles, and the 4 van accessible parking spaces nearest to the zoo entrance have no vertical signage. This lot requires 1 van accessible space and 7 standard accessible spaces. | | |
| 3.2 | Accessible Route. The route leading to the exterior entrance is inaccessible because the running slope is 8.7% and the route has no ramp features. | AR1 | 30 months |
| 3.3 | 1 st Floor Auditorium | | |
| 3.3.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 3.3.b | The auditorium, with 187 fixed seats, is inaccessible because a fixed companion seat is not provided for all wheelchair seating locations. | AA6 | 30 months |
| 3.3.c | The ramp on the route connecting the wheelchair seating areas and the stage is inaccessible because it has a handrail on only one side, the existing handrail has no extensions at the top or bottom, and the ramp lacks edge protection. | R5 | 30 months |
| 3.3.d | The auditorium is inaccessible because it lacks fixed aisle seating without armrests. | AA2 | 30 months |

| | | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 3.3.e | There is no signage informing the public of the availability of an assistive listening system. | AA3 | 30 months |
| 3.4 | Women's Toilet Room with Stalls 1 st Floor | | |
| 3.4.a | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 3.4.b | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 3.5 | Men's Toilet Room With Stalls 1 st Floor | | |
| 3.5.a | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 3.5.b | The lavatory is inaccessible because it has twist-type hardware. | TR10 | 24 months |
| 3.5.c | The lower urinal is inaccessible because the rim is 19 inches high. | TR20 | 24 months |
| 3.5.d | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |

| | | | |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 3.6 | Elevator. The elevator is inaccessible because the car control buttons do not have Braille or raised characters to the left of the buttons and the main entry floor is not designated by a raised star. | E4 | 30 months |
| 3.7 | Interior Accessible Route: 1 st Floor. The area under the escalators is inaccessible because there are less than 80 inches of head room provided. | AR7 | 24 months |
| 3.8 | Ramp: From Auditorium to Cyclorama. The ramp is inaccessible because the handrails are mounted 32½ inches high. | R4 | 24 months |
| 3.9 | Cyclorama. The Cyclorama is inaccessible because there are no fixed companion seats next to the wheelchair locations. | AA6 | 30 months |
| 4 | ATLANTA POLICE DEPARTMENT ZONE 2, located at 3120 Maple Drive | | |
| 4.1 | Parking. The parking lot, with a total of 43 parking spaces, is inaccessible because it only has no spaces designated as accessible. This lot requires 1 van accessible space and 1 standard accessible space. | P3 | 24 months |
| 4.2 | Accessible Route: From Parking Lot to Exterior Entrance. The route is inaccessible because a barrel and sign placed in the walkway obstruct the route and because the surface has a | AR1 | 30 months |

| | | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | change in level in excess of ½ inch vertically. | | |
| 4.3 | Front Desk Counter. The counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 4.4 | Men's Toilet Room With Stalls | | |
| 4.4.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 12 months |
| 4.4.b | The door is inaccessible because it requires 15 pounds of force to open. | D2 | 12 months |
| 4.4.c | The pull side of the door to the toilet room, which is accessed through a front approach, is inaccessible because the maneuvering space is obstructed by a table. | D6 | 12 months |
| 4.4.d | There is no accessible toilet stall provided. | ST15 | 30 months |
| 4.5 | Women's Single-User Toilet Room | | |
| 4.5.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 12 months |
| 4.5.b | The pull side of the door to the toilet room, which is accessed through a front approach, is inaccessible because the maneuvering space is blocked by a chair. | D6 | 12 months |

| | | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 4.5.c | The push side of the door to the women's toilet room, which is accessed through a front approach and which has both a closer and a latch, is inaccessible because it has only 9 inches of clearance on the latch side. | D7 | 30 months |
| 4.5.d | There is insufficient turning space within the toilet room. | TR19 | 30 months |
| 4.5.e | The toilet is inaccessible because the centerline is 19 inches from the side wall. | SU15 | 30 months |
| 4.5.f | The toilet is inaccessible because the flush control is on the closed side. | SU1 | 30 months |
| 4.5.g | The overall length of the side grab bar is 30 inches and the distance from the farther end to the rear wall is 33½ inches. | SU6 | 24 months |
| 4.5.h | The overall length of rear grab bar is 24 inches, and the distance from the closer end to the side wall is 6½ inches. | SU3 | 24 months |
| 5 | ATLANTA POLICE DEPARTMENT ZONE 6, located at 2025 Hosea Williams Drive, SE | | |
| 5.1 | Accessible Route: Ramp. The ramp on the route to the main entrance is inaccessible because it slopes up to 12.1%, the cross-slope is greater than 2.0%, the bottom landing is not level, and the handrails are 33 inches high and lack extensions. | R5 | 30 months |

| | | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 5.2 | Exterior Entrance and Doors. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 12 months |
| 5.3 | Men's Single-User Toilet Room | | |
| 5.3.a | The toilet room sign is mounted on the door and has no raised and Braille characters. | TR18 | 24 months |
| 5.3.b | The door swings into the clear floor space of the lavatory. | TR6 | 30 months |
| 5.3.c | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 5.3.d | No accessible mirror has been provided. | TR14 | 12 months |
| 5.3.e | The lavatory is inaccessible because the rim or counter is 27 inches high to the bottom. | TR11 | 24 months |
| 5.3.f | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 5.3.g | The toilet is inaccessible because the flush control is mounted on the closed side. | SU1 | 30 months |
| 5.3.h | There is no accessible toilet paper dispenser provided. | SU17 | 12 months |

| | | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 5.3.i | The rear grab bar at the toilet is inaccessible because it is mounted 7 inches from the side wall. | SU3 | 12 months |
| 5.4 | Women's Single-User Toilet Room | | |
| 5.4.a | The toilet room sign is mounted on the door and has no raised and Braille characters. | TR18 | 24 months |
| 5.4.b | The second door leading to the toilet room is blocked by a ladder and prevented from opening to a 90 degree angle. | D25 | 12 months |
| 5.4.c | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 5.4.d | No accessible mirror has been provided. | TR14 | 12 months |
| 5.4.e | The lavatory is inaccessible because the rim or counter is 27¼ inches high to the bottom. | TR11 | 24 months |
| 5.4.f | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 5.4.g | The toilet is inaccessible because the top of the seat is 16 inches high. | SU18 | 30 months |
| 5.4.h | The toilet is inaccessible because there is insufficient clear floor | SU16 | 30 months |

| | | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | space due to the lavatory post. | | |
| 5.4.i | The toilet is inaccessible because the centerline is 16 inches from the wall. | SU15 | 30 months |
| 5.4.j | The toilet is inaccessible because the flush control is mounted on the closed side. | SU1 | 30 months |
| 6 | BOISFEUILLET JONES ATLANTA CIVIC CENTER, located at 395 Piedmont Ave, NE | | |
| 6.1 | Parking. All of the lots, which have a total of 882 parking spaces, have a total of 24 designated accessible parking spaces, many of which have slopes and cross-slopes exceeding 2% or are lacking vertical signage; there is no "Van-Accessible" signage; and several of the designated accessible spaces are in the Piedmont lot, which has no access aisles and no accessible route to an accessible entrance. This lot requires 3 van accessible spaces and 15 standard accessible spaces. | P3 | 30 months |
| 6.2 | Accessible Route: From Parking To Entrance | | |
| 6.2.a | On the routes from both sides of the parking lot to the entrance, the slope of most of the curb cuts is greater than 8.33%, and some of the flared sides slope greater than 10%. | AR5 | 30 months |

| | | | |
|--------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 6.2.b | On the route from the left side of the parking lot to the entrance, the slope between the planters is 5.2% with no ramp features; on the route from the right side of the parking lot to the entrance, the slope between the planters is 8% and the slope on the island is 7.8% with no ramp features; and on the routes from both sides, there is broken asphalt creating level changes exceeding ½ inch. | AR1 | 30 months |
| 6.2.c | The route from the right side of the parking to the entrance is inaccessible because the underside of the stairs provides less than 80 inches of head room. | AR7 | 24 months |
| 6.3 | Main Entrance - East - Passenger Loading Zone. The slope of the primary curb cut is 13.6%, and the slope of the flared sides is 22% and 25%. | AR5 | 30 months |
| 6.4 | Exterior Entrances. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 12 months |
| 6.5 | Public Elevators | | |
| 6.5.a | The elevator is inaccessible because the call buttons are centered at 49 inches above the finished floor and are recessed. | E3 | 30 months |
| 6.5.b | The elevator is inaccessible because hall lanterns are not provided. | E11 | 30 months |

| | | | |
|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.5.c | The elevator is inaccessible because it lacks signage at hoistway entrances. | E12 | 30 months |
| 6.5.d | The elevator is inaccessible because it does not emit an audible signal as the car passes or stops at a floor. | E5 | 30 months |
| 6.6 | Assembly Area: Piedmont Room A & B | | |
| 6.6.a | The Piedmont room is inaccessible to people with hearing disabilities because there is no assistive listening system provided. | AA5 | 30 months |
| 6.6.b | There is no accessible route connecting the wheelchair seating areas and the portable stage. | AA1 | 30 months |
| 6.7 | Staff Toilet Rooms By Piedmont Meeting Room. Although these are staff-only toilet rooms, they are used by the public, and there is no signage directing people with disabilities to the accessible public toilet rooms. | TR16 | 24 months |
| 6.8 | Accessible Route: From East Entrance to Orchestra Level. The doors on the route from the east entrance to the orchestra level are inaccessible because they have an opening width of only 29 inches. | D25 | 30 months |
| 6.9 | Women's Toilet Room With Stalls: Orchestra Level | | |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.9.a | The toilet room sign is mounted above the door and has no raised or Braille characters. | TR18 | 24 months |
| 6.9.b | There is no side grab bar provided at the designated accessible toilet. | ST6 | 24 months |
| 6.9.c | The rear grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet flush valve. | ST5 | 24 months |
| 6.9.d | Although there are 14 stalls, there is no ambulatory stall provided. | ST1 | 30 months |
| 6.10 | Men's Toilet Room With Stalls: Orchestra Level | | |
| 6.10.a | The toilet room sign is mounted above the door and has no raised or Braille characters. | TR18 | 24 months |
| 6.10.b | The urinals are inaccessible because they are mounted with their rims 20½ inches above the finished floor. | TR20 | 30 months |
| 6.10.c | The rear grab bar at the designated accessible toilet is inaccessible because it is obstructed by the toilet flush valve. | ST5 | 24 months |
| 6.10.d | Although there are 6 stalls, there is no ambulatory stall provided. | ST1 | 30 months |
| 6.11 | Drinking Fountains: Orchestra Level | | |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 6.11.a | The drinking fountain is inaccessible because the control requires 10 pounds of force to operate. | DF2 | 12 months |
| 6.11.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 6.12 | Accessible Route To Orchestra Level Seats. The route leading to the Orchestral Level seats is inaccessible because the slope of one leg is 10.1%, the slope of the landing between the legs is 3.5%, and handrails are not provided. | R3 | 30 months |
| 6.13 | Auditorium | | |
| 6.13.a | The seating is inaccessible because the wheelchair locations do not have fixed companion seats. | AA6 | 30 months |
| 6.13.b | There is no accessible route connecting the wheelchair seating areas and the stage. | AA1 | 30 months |
| 6.14 | Plaza Box Office Ticket Window. The counter at the ticket window is 42 inches above the finished floor and a clipboard is unable to fit through the opening. | C6 | 24 months |
| 6.15 | Drinking Fountain: Plaza Level | | |
| 6.15.a | The drinking fountain is inaccessible because the control requires 12 pounds of force to operate. | DF2 | 12 months |

| | | | |
|-----------------|--------------------------------------------------------------------------------------------------------|------|-----------|
| 6.15.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 6.16 | Women's Toilet Room With Stalls: Plaza Level | | |
| 6.16.a | The toilet room sign is mounted above the door and has no raised or Braille characters. | TR18 | 24 months |
| 6.16.b | The seat cover dispenser is mounted 56½ inches above the finished floor. | TR5 | 12 months |
| 6.16.c | Left Standard Toilet Stall | | |
| 6.16.c.1 | The toilet is inaccessible because the centerline is 24 inches from the side partition. | ST17 | 30 months |
| 6.16.c.2 | The toilet is inaccessible because the side grab bar is obstructed by the toilet seat cover dispenser. | ST9 | 12 months |
| 6.16.c.3 | The toilet is inaccessible because the rear grab bar is mounted 13 inches from the side wall. | ST4 | 12 months |
| 6.16.d | Right Standard Toilet Stall | | |
| 6.16.d.1 | The toilet is inaccessible because the stall is 57½ inches wide. | ST16 | 30 months |
| 6.16.d.2 | The toilet is inaccessible because the side grab bar is obstructed by the toilet seat cover dispenser. | ST9 | 12 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.17 | Accessible Route: Plaza Level | | |
| 6.17.a | The route from the front entrance is inaccessible because there are only 55 inches of head room provided under the stairs. | AR7 | 24 months |
| 6.17.b | The defibrillator protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 6.18 | Men's Toilet Room With Stalls: Loge Level | | |
| 6.18.a | The toilet room sign is mounted above the door and has no raised or Braille characters. | TR18 | 24 months |
| 6.18.b | The urinals are inaccessible because their rims are 20 inches high. | TR20 | 30 months |
| 6.18.c | Although there are 6 stalls, there is no ambulatory stall provided. | ST1 | 30 months |
| 6.18.d | The designated accessible toilet is inaccessible because the stall is 56½ inches deep with a floor-mounted toilet. | ST16 | 30 months |
| 6.18.e | The designated accessible toilet is inaccessible because its centerline is 16 inches from the side wall. | ST17 | 30 months |
| 6.18.f | There is no accessible coat hook provided. | TR1 | 12 months |
| 6.18.g | The designated accessible toilet is inaccessible because the rear | ST5 | 30 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------|------|-----------|
| | grab bar is obstructed by the flush valve. | | |
| 6.19 | Women's Toilet Room With Stalls: Loge Level | | |
| 6.19.a | The toilet room sign is mounted above the door and has no raised or Braille characters. | TR18 | 24 months |
| 6.19.b | The designated accessible toilet is inaccessible because its centerline is 16 inches from the side wall. | ST17 | 30 months |
| 6.19.c | Although there are 13 stalls, there is no ambulatory stall provided. | ST1 | 30 months |
| 6.19.d | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 6.19.e | The designated accessible toilet is inaccessible because the rear grab bar is obstructed by the flush valve. | ST5 | 30 months |
| 6.20 | Drinking Fountain: Loge Level | | |
| 6.20.a | The drinking fountain is inaccessible because the control requires 7 pounds of force to operate. | DF2 | 12 months |
| 6.20.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 6.21 | Auditorium: Loge Level | | |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.21.a | Each leaf of the double entry doors is inaccessible because it has an opening width of 29½ inches and requires 12 pounds of force to open. | D5 | 30 months |
| 6.21.b | The seating is inaccessible because the slope of the wheelchair locations is 4.4%, the cross-slope is 7.5%, and the wheelchair seating areas lack fixed companion seating. | AA6 | 30 months |
| 6.22 | Auditorium: Balcony Level | | |
| 6.22.a | A pipe protrudes into the walkway on the route to the balcony seating that is not detectable to blind persons using a cane. | AR8 | 30 months |
| 6.22.b | Each leaf of the double doors to the Balcony Level seating is inaccessible because it has an opening width of only 30 inches and requires 11 pounds of force to open. | D5 | 30 months |
| 6.23 | Accessible Dressing Room No. 8 | | |
| 6.23.a | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 6.23.b | The shower stall is inaccessible because the clear floor space outside the stall is inadequate, the transfer seat does not extend the full depth of the stall, and a grab bar is not provided on the back wall. | B8 | 30 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 6.24 | Drinking Fountain: Back Stage Area. The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 6.25 | Elevator: Backstage Freight | | |
| 6.25.a | The elevator is inaccessible because the hall call buttons are centered 51 inches high and they have a diameter less than $\frac{3}{4}$ inches. | E3 | 30 months |
| 6.25.b | The elevator is inaccessible because it lacks hall lanterns. | E11 | 30 months |
| 6.25.c | The elevator is inaccessible because it lacks hoistway signage. | E12 | 30 months |
| 6.25.d | The elevator is inaccessible because it lacks a door protective and reopening device. | E6 | 30 months |
| 6.25.e | The elevator is inaccessible because the car control buttons are less than $\frac{3}{4}$ inches in dimension and lack Braille and raised characters, the highest button is 61 $\frac{1}{2}$ inches above the car floor, car position indicators are not provided, and the main entry floor call button is not designated by a raised star. | E4 | 30 months |
| 6.25.f | The elevator is inaccessible because, although emergency communications are provided, the door to the emergency communications requires tight pinching to open. | E8 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.26 | Accessible Route: Main Lobby Exhibition Hall. The route through the main lobby is inaccessible because the underside of the stairs provides less than 80 inches of head room. | AR7 | 30 months |
| 6.27 | Exhibition Hall Main Lobby Box Office (Temporary With Exhibit). The lobby box office counter is inaccessible because it is 46 inches high. | C6 | 12 months |
| 6.28 | Men's Toilet Room with Stalls: Exhibition Hall | | |
| 6.28.a | The toilet room sign is less than 60 inches high and has no raised or Braille characters. | TR18 | 24 months |
| 6.28.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 6.28.c | The paper towel dispenser is inaccessible because the controls are mounted 59 inches high. | TR5 | 12 months |
| 6.28.d | The urinals are inaccessible because their rims are 20 inches high. | TR20 | 30 months |
| 6.28.e | There is no accessible toilet stall provided. | ST15 | 30 months |
| 6.28.f | The ambulatory stall has partitions 37 inches apart, and the toilet paper dispenser is mounted above one side grab bar. | ST1 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.29 | Women's Toilet Room with Stalls: Exhibition Hall | | |
| 6.29.a | The toilet room sign is less than 60 inches high and has no raised or Braille characters. | TR18 | 24 months |
| 6.29.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 6.29.c | No accessible mirror has been provided. | TR14 | 12 months |
| 6.29.d | The paper towel dispenser is inaccessible because the controls are mounted 60 inches high. | TR5 | 12 months |
| 6.29.e | The lavatory is inaccessible because the rim or counter is 27 inches high to the bottom. | TR11 | 24 months |
| 6.29.f | There is no accessible toilet stall provided. | ST15 | 30 months |
| 6.29.g | The ambulatory stall has partitions 38 inches apart, and the toilet paper dispenser is mounted above one side grab bar. | ST1 | 30 months |
| 6.30 | Drinking Fountain: Exhibition Hall by Toilet Rooms | | |
| 6.30.a | The drinking fountain is inaccessible because the control requires 12 pounds of force to operate. | DF2 | 12 months |
| 6.30.b | Although a designated accessible | DF3 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------|
| | drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | | |
| 6.31 | Public Elevator: Exhibition Hall | | |
| 6.31.a | The elevator is inaccessible because the hall call buttons are recessed. | E3 | 30 months |
| 6.31.b | The elevator is inaccessible because the doors fail to reopen without contact when obstructed. | E6 | 30 months |
| 6.31.c | The elevator is inaccessible because the car control buttons are recessed, raised characters are not provided, and the call button for the main entry floor is not designated by a raised star. | E4 | 30 months |
| 6.32 | Accessible Route: Exhibition Hall 1 st Floor. The route is inaccessible because adequate head room is not provided in the exit area under the stairs. | AR7 | 30 months |
| 6.33 | Exhibition Hall 2 nd Floor Meeting Room | | |
| 6.33.a | The door is inaccessible because it requires 9 pounds of force to open and the hardware is mounted 53 inches above the floor and requires twisting to operate. | D1 D18 | 24 months |
| 6.33.b | The meeting room is inaccessible to people with hearing disabilities because no assistive listening | AA5 | 30 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | system is provided. | | |
| 6.34 | Drinking Fountain: Exhibition Hall 2 nd Floor Meeting Room. Although a designated accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |
| 6.35 | Women's Toilet Room Single-User: Exhibition Hall 2 nd Floor Meeting Room | | |
| 6.35.a | The toilet room sign is mounted on the door and does not have raised or Braille characters. | TR18 | 24 months |
| 6.35.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 6.35.c | The toilet is inaccessible because its centerline is 19½ inches from the side wall. | SU15 | 30 months |
| 6.36 | Men's Toilet Room Single-User: Exhibition Hall 2 nd Floor Meeting Room | | |
| 6.36.a | The toilet room sign is mounted on the door and does not have raised or Braille characters. | TR18 | 24 months |
| 6.36.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 6.36.c | The paper towel dispenser is inaccessible because the controls are mounted at 56 inches high. | TR5 | 12 months |
| 6.36.d | The toilet is inaccessible because there is insufficient clear floor space due to the placement of the lavatory. | SU16 | 30 months |
| 6.36.e | The toilet is inaccessible because its centerline is 19 inches from the side wall. | SU15 | 30 months |
| 6.36.f | The toilet is inaccessible because the flush control is on the closed side. | SU1 | 30 months |
| 6.36.g | The rear grab bar at the toilet is inaccessible because its overall length is 24 inches. | SU3 | 24 months |
| 7 | CANDLER PARK GOLF COURSE, located at 585 Candler Park Dr, NE | | |
| 7.1 | Parking Lot. Although the parking lot has a total of 5 parking spaces, there are no accessible parking spaces provided. This lot requires 1 van accessible space. | P3 | 24 months |
| 7.2 | Club House Main Entrance | | |
| 7.2.a | The Club House is inaccessible because there is a 4 inch step on the route leading to the main entrance. | AR1 | 30 months |
| 7.2.b | The main entrance door is inaccessible because it has an opening width of only 28 inches | D25 | 30 months |

| | | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | per leaf. | | |
| 7.2.c | The main entrance door is inaccessible because it has a 1½ inch high threshold. | D23 | 24 months |
| 7.3 | Counter. The counter in the clubhouse is inaccessible because it is 39½ inches high. | C6 | 24 months |
| 7.4 | Men's & Women's Toilet Rooms with Stalls. The men's and women's toilet rooms contain a number of inaccessible elements and are not accessible to people with disabilities. | ST14 | 30 months |
| 7.5 | Drinking Fountain. The drinking fountain is inaccessible because the spout is 43 inches high. | DF6 | 12 months |
| 8 | OAKLAND RECREATION CENTER, located at 1305 Oakland Rd, SW | | |
| 8.1 | Parking Lot. The parking reserved for persons with disabilities is inaccessible because it lacks appropriate vertical signage. | P6 | 24 months |
| 8.2 | Women's Toilet Room With Stalls: 1 st Floor | | |
| 8.2.a | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 8.2.b | No accessible mirror has been provided. | TR14 | 12 months |

| | | | |
|--------------|--------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 8.2.c | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.2.d | The lavatory is inaccessible because it has no knee or toe clearance. | TR11 | 24 months |
| 8.2.e | There is no standard accessible stall provided. | ST15 | 30 months |
| 8.3 | Men's Toilet Room With Stalls: 1 st Floor | | |
| 8.3.a | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 8.3.b | No accessible mirror has been provided. | TR14 | 12 months |
| 8.3.c | The urinal is inaccessible because its rim is 23 inches high. | TR20 | 24 months |
| 8.3.d | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 8.3.e | The lavatory is inaccessible because it has no knee or toe clearance. | TR11 | 24 months |
| 8.3.f | There is no standard accessible stall provided. | ST15 | 30 months |
| 8.4 | Drinking Fountain. The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |

| | | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 9 | ADAMS PARK & RECREATION CENTER, located on Delowe Dr, SW | | |
| 9.1 | Parking Lot. The parking lot, with a total of 6 parking spaces, has no van accessible parking space, and the existing designated accessible parking space has no access aisle and no vertical signage. This lot requires 1 van accessible space. | P3 | 24 months |
| 9.2 | Accessible Route: From Parking Lot To Main Entrance. The route is inaccessible because the curb ramp is steeper than 8.33%, and although it does not have handrails or guardrails to protect against cross traffic, it also does not have flared sides. | AR5 | 30 months |
| 9.3 | Exterior Entrances. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 12 months |
| 9.4 | Interior Doors. The interior doors are inaccessible because knob hardware is used. | D1 | 24 months |
| 9.5 | Access Among Levels. There is no access to upper and lower levels of the facility for people with mobility impairments. | AR9 | 30 months |
| 9.6 | Drinking Fountain | | |
| 9.6.a | Although an accessible drinking | DF3 | 30 months |

| | | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | | |
| 9.6.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 9.7 | Women's Toilet Room With Stalls: 1 st Level | | |
| 9.7.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 24 months |
| 9.7.b | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 9.7.c | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 9.7.d | The designated accessible toilet is inaccessible because its centerline is 16½ inches from the side wall. | ST17 | 30 months |
| 9.7.e | The designated accessible toilet is inaccessible because the side grab bar is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 9.7.f | The grab bars at the designated accessible toilet are inaccessible because they are mounted 30½ inches above the finished floor. | ST12 | 12 months |

| | | | |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 9.7.g | The grab bars at the designated accessible toilet are inaccessible because the space between the grab bars and the wall is 2¾ inches. | ST13 | 12 months |
| 9.7.h | The rear grab bar at the designated accessible toilet is inaccessible because it is 24 inches long. | ST4 | 24 months |
| 9.8 | Men's Toilet Room With Stalls: 1 st Level | | |
| 9.8.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 24 months |
| 9.8.b | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 9.8.c | No accessible mirror has been provided. | TR14 | 12 months |
| 9.8.d | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 9.8.e | The urinal is inaccessible because the rim is more than 17 inches high. | TR20 | 24 months |
| 9.8.f | The designated accessible toilet is inaccessible because its centerline is 20½ inches from the side wall. | ST17 | 30 months |

| | | | |
|--------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 9.8.g | The designated accessible toilet is inaccessible because the side grab bar is obstructed by the toilet paper dispenser. | ST8 | 12 months |
| 9.8.h | The grab bars at the designated accessible toilet are inaccessible because the space between the grab bars and the wall is 2¾ inches. | ST13 | 24 months |
| 9.8.i | The rear grab bar at the toilet is inaccessible because its overall length is 24 inches and it is mounted with the closer end 12 inches from the side wall. | ST4 | 24 months |
| 9.9 | Spectator Area 1 st Floor. The door is inaccessible because it requires 12 pounds of force to open. | D2 | 12 months |
| 9.10 | Stairs. The stairs to the basketball court are inaccessible because there are less than 80 inches of head room provided. | AR7 | 30 months |
| 9.11 | Accessible Route: To Tennis Courts. There is no accessible route to the tennis courts. | AR1 | 30 months |
| 10 | MCGHEE TENNIS CENTER, located at 820 Beecher Ct, SW | | |
| 10.1 | Parking Lot. The parking lot, with a total of 36 parking spaces, has no van accessible parking space, and has no vertical signage designating accessible parking spaces. This lot requires 1 van accessible space and 1 standard accessible space. | P3 | 24 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 10.2 | Accessible Route: From Parking Lot to Main Entrance. The route is inaccessible because the slope of the curb cut is 12.2%, and the flared sides are too steep. | AR5 | 30 months |
| 10.3 | Main Entrance. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 12 months |
| 10.4 | Interior Doors. The doors are inaccessible because knob hardware is used. | D1 | 24 months |
| 10.5 | Women's Locker Room: Near Lobby | | |
| 10.5.a | The sign is mounted on the door and lacks raised and Braille characters. | TR18 | 24 months |
| 10.5.b | The door is inaccessible because it requires 11 pounds of force to open. | D2 | 12 months |
| 10.5.c | The lavatory is inaccessible because there is no knee space provided. | TR11 | 24 months |
| 10.5.d | The designated accessible toilet stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 10.5.e | The designated accessible shower has a number of inaccessible elements and is not | B8 | 30 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | accessible to people with disabilities. | | |
| 10.5.f | The air dryer is inaccessible because the controls are mounted 69 inches above the finished floor. | TR5 | 12 months |
| 10.5.g | The bench is inaccessible because it is 9½ inches wide and is not fixed to a wall. | LR1 | 30 months |
| 10.5.h | The lockers are inaccessible because they require tight grasping to open. | LR3 | 30 months |
| 10.6 | Men's Locker Room: Near Lobby | | |
| 10.6.a | The sign is mounted on the door and lacks raised and Braille characters. | TR18 | 24 months |
| 10.6.b | The door is inaccessible because it requires 11 pounds of force to open. | D2 | 12 months |
| 10.6.c | The lavatory is inaccessible because there is no knee space provided. | TR11 | 24 months |
| 10.6.d | The urinals are inaccessible because their rims are 25 inches high. | TR20 | 24 months |
| 10.6.e | The designated accessible toilet stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 10.6.f | The paper towel dispenser is | TR5 | 12 months |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | inaccessible because the controls are mounted more than 54 inches high. | | |
| 10.6.g | There is no accessible shower provided. | B8 | 30 months |
| 10.6.h | The air dryer is inaccessible because the controls are mounted 77 inches above the finished floor. | TR5 | 12 months |
| 10.6.i | The bench is inaccessible because it is 9½ inches wide and is not fixed to a wall. | LR1 | 30 months |
| 10.6.j | The lockers are inaccessible because they require tight grasping to open. | LR3 | 30 months |
| 10.7 | Welcome Desk: Lobby Area. The welcome desk is inaccessible because the counter is 44 inches high. | C6 | 12 months |
| 10.8 | Accessible Route: From Side Exit to Tennis Court #7. The ramp leading to the tennis court has a 1 inch change in level at the top, has a slope of 10.3% near the bottom, and lacks handrails. | AR1 | 30 months |
| 11 | GRANT PARK RECREATION CENTER, located at 537 Park Ave, SE | | |
| 11.1 | Parking Lot | | |
| 11.1.a | The parking lot, with a total of 30 parking spaces, has only one designated accessible parking space, which has no access aisle | P3 | 24 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | and no vertical signage. This lot requires 1 van accessible space and 1 standard accessible space. | | |
| 11.1.b | The curb ramp leading to the basketball and tennis courts is inaccessible because it slopes 15%, the cross-slope is 3.2%, there is a ½ change in level at the bottom of the curb ramp, and the flared sides are too steep. | AR5 | 30 months |
| 11.1.c | The curb ramp leading to the main entrance under the stairs is inaccessible because it slopes 13.9%, the flared sides are too steep, and there is a ¾ inch change in level at the top of the curb ramp. | AR5 | 30 months |
| 11.2 | Exterior Accessible Route. The route from the parking lot to the basketball and tennis courts is inaccessible because the running slope is 6% with no ramp features, the cross-slope is 5.5%, and there is a 2½ inch change in level at the entrance of the tennis court. | AR1 | 30 months |
| 11.3 | Main Entrance. The front entrance is inaccessible because the threshold is 4 inches high. | D23 | 24 months |
| 11.4 | Interior Accessible Route. There is no access to the 2 nd floor of the facility for people with mobility impairments. | AR9 | 30 months |
| 11.5 | Dance Room: 1 st Floor. The dance room is inaccessible because the door has knob | D1 | 24 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | hardware. | | |
| 11.6 | Side Entrance by Game Room | | |
| 11.6.a | The route to the side entrance by the game room is inaccessible because there is a 3¼ change in level leading to the entrance. | AR1 | 24 months |
| 11.6.b | The door is inaccessible because there is a 1 inch high threshold. | D23 | 24 months |
| 11.7 | Classroom: 1 st Floor. The classroom is inaccessible because the door has knob hardware. | D1 | 24 months |
| 11.8 | Women's Toilet Room With Stalls: 1 st Floor | | |
| 11.8.a | The toilet room sign is not mounted on the latch side of the door and lacks raised and Braille characters. | TR18 | 24 months |
| 11.8.b | The door to the toilet room is inaccessible because it has an opening width of only 29 inches. | D25 | 30 months |
| 11.8.c | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 11.8.d | The pull side of the door to the toilet room, which is accessed through a front approach, is inaccessible because the clearance on the latch side of the door is only 6 inches wide. | D6 | 30 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 11.8.e | No accessible mirror has been provided. | TR14 | 12 months |
| 11.8.f | The lavatory is inaccessible because the rim or counter is 27 inches high to the bottom. | TR11 | 24 months |
| 11.8.g | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 11.8.h | The lavatory is inaccessible because the faucet requires tight grasping or twisting of the wrist to operate. | TR10 | 24 months |
| 11.8.i | There is no accessible toilet stall provided. | ST15 | 30 months |
| 11.9 | Men's Toilet Room With Stalls: 1 st Floor | | |
| 11.9.a | The toilet room sign is not mounted on the latch side of the door and lacks raised and Braille characters. | TR18 | 24 months |
| 11.9.b | The door to the toilet room is inaccessible because it has an opening width of only 29 inches. | D25 | 30 months |
| 11.9.c | The door is inaccessible because it requires 8 pounds of force to open. | D2 | 12 months |
| 11.9.d | The pull side of the door to the women's toilet room, which is accessed through a front approach, is inaccessible | D6 | 30 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | because the clearance on the latch side of the door is only 4½ inches wide. | | |
| 11.9.e | No accessible mirror has been provided. | TR14 | 12 months |
| 11.9.f | The lavatory is inaccessible because the rim or counter is 27 inches high to the bottom. | TR11 | 24 months |
| 11.9.g | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 11.9.h | The lavatory is inaccessible because the faucet requires tight grasping or twisting of the wrist to operate. | TR10 | 24 months |
| 11.9.i | The urinals are inaccessible because the rims are 23 inches high. | TR20 | 24 months |
| 11.9.j | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 11.10 | Drinking Fountain: 1 st Floor. The drinking fountain is inaccessible because its spout is 45 inches high. | DF6 | 24 months |
| 11.11 | Stairs: Leading to Gymnasium (Two Sets of Stairs) | | |

| | | | |
|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 11.11.a | The stairs have a number of inaccessible features and are not accessible to people with disabilities. | AR10 | 30 months |
| 11.11.b | The route by the stairs is inaccessible because a cane detectable barrier is not provided under the stairs. | AR7 | 24 months |
| 11.12 | Gymnasium. The gymnasium, containing approximately 480 seats, is inaccessible because it has bleacher style fixed seating and wheelchair seating areas are not provided. A total of 6 wheelchair seating areas is required. | AA6 | 30 months |
| 11.13 | Women's Gym Locker Room: Ground Level | | |
| 11.13.a | The sign is not mounted on the latch side of the door and does not have raised or Braille characters. | TR20 | 24 months |
| 11.13.b | The locker room is inaccessible because the opening width of both entrance doors is 29 inches, and the outer door requires 6 pounds of force to open and has a 2 inch high threshold. | D18 | 30 months |
| 11.13.c | No accessible mirror has been provided. | TR14 | 12 months |
| 11.13.d | The paper towel dispenser is inaccessible because the controls are mounted 56 inches high. | TR5 | 12 months |

| | | | |
|----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 11.13.e | The lavatory is inaccessible because the bottom of the apron is 27½ inches high, the hot water pipes are not insulated or otherwise configured to protect against contact, and the faucet requires tight grasping or twisting of the wrist to operate. | TR9 | 30 months |
| 11.13.f | There is no accessible toilet stall provided. | ST15 | 30 months |
| 11.13.g | There is no accessible shower provided. | B8 | 30 months |
| 11.13.h | No accessible towel hook has been provided. | TR1 | 12 months |
| 11.13.i | The towel hooks protrude into the walkway and would not be detectable to a blind person using a cane | AR8 | 12 months |
| 11.13.j | There is no accessible locker provided. | LR3 | 30 months |
| 11.14 | Men's Gym Locker Room: Ground Level | | |
| 11.14.a | The sign is not mounted on the latch side of the door and does not have raised or Braille characters. | TR20 | 24 months |
| 11.14.b | The locker room is inaccessible because the opening width of both entrance doors is 29½ | D25 | 30 months |

| | | | |
|----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | inches. | | |
| 11.14.c | The outer door to the locker is inaccessible because there is a 2 inch high threshold. | D23 | 24 months |
| 11.14.d | The soap dispenser is inaccessible because the controls are mounted 56 inches high. | TR5 | 12 months |
| 11.14.e | The lavatory is inaccessible because the bottom of the apron is 27½ inches high, the hot water pipes are not insulated or otherwise configured to protect against contact, and the faucet requires tight grasping or twisting of the wrist to operate. | TR9 | 30 months |
| 11.14.f | The urinals are inaccessible because they are mounted with the rims 26 inches high. | TR20 | 24 months |
| 11.14.g | There is no accessible toilet stall provided. | ST15 | 30 months |
| 11.14.h | There is no accessible shower provided. | B8 | 30 months |
| 11.14.i | There is no accessible locker provided. | LR3 | 30 months |
| 11.15 | Drinking Fountain: Gymnasium Area. The drinking fountain is inaccessible because its spout is 43 inches high. | DF6 | 24 months |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12 | GRANT PARK SWIMMING POOL, located at 25 Park Ave, SE | | |
| 12.1 | Parking Lot. The parking lot, with a total of approximately 20 parking spaces, has no parking spaces provided for people with disabilities. This lot requires 1 van accessible parking space. | P3 | 24 months |
| 12.2 | Accessible Route: From Parking Lot to Rear Entrance. The route is inaccessible because there is a ½ inch unbeveled change in level at the gate. | AR1 | 24 months |
| 12.3 | Men's Locker Room | | |
| 12.3.a | The locker room sign is mounted more than 60 inches high and has no raised or Braille characters. | TR18 | 24 months |
| 12.3.b | The door to the locker room is inaccessible because there is a 3¾ inch high threshold. | D23 | 24 months |
| 12.3.c | No accessible mirror has been provided. | TR14 | 12 months |
| 12.3.d | The lavatory is inaccessible because the faucet requires tight grasping or twisting of the wrist to operate. | TR10 | 24 months |
| 12.3.e | The designated accessible toilet stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12.3.f | There is no accessible shower provided. | B8 | 30 months |
| 12.3.g | The benches are less than 24 inches wide and are not attached to the wall. | LR1 | 30 months |
| 12.4 | Women's Locker Room | | |
| 12.4.a | The locker room sign is not mounted in the proper position and has no raised or Braille characters. | TR18 | 24 months |
| 12.4.b | The door to the locker room is inaccessible because the threshold is more than ½ inch high. | D23 | 24 months |
| 12.4.c | No accessible mirror has been provided. | TR14 | 12 months |
| 12.4.d | The sanitary napkin dispenser is inaccessible because the controls are mounted 57 inches high. | TR5 | 12 months |
| 12.4.e | The lavatory is inaccessible because the bottom edge of the apron is 24½ inches high, and the faucet requires twisting to operate. | TR9 | 24 months |
| 12.4.f | The designated accessible toilet stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 12.4.g | There is no accessible shower provided. | B8 | 30 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 12.4.h | The benches are less than 24 inches wide and are not attached to the wall. | LR1 | 30 months |
| 12.5 | Picnic Tables. The picnic tables at the pool area are inaccessible because none provide adequate knee space. | PD6 | 30 months |
| 12.6 | Accessible Route: To Pools | | |
| 12.6.a | The route from the lockers and picnic area to the pools is inaccessible because it slopes 6.6% and has no ramp features. | R3 | 30 months |
| 12.6.b | The stairs to the diving pool are inaccessible because they lack handrails | AR10 | 24 months |
| 13 | BROWNWOOD RECREATION CENTER, located at 602 Brownwood Ave, SE | | |
| 13.1 | Parking Lot. The parking lot, with a total of 15 parking spaces, has no van accessible parking space provided. This lot requires 1 van accessible parking space. | P3 | 24 months |
| 13.2 | Exterior Accessible Route. There is no accessible route provided from the parking lot to the tennis, basketball, or volleyball courts. | AR1 | 30 months |
| 13.3 | Main Entrance. The door is inaccessible because there is a 1½ inch high threshold. | D23 | 24 months |
| 13.4 | Interior Room Signage. Although room signage is provided, many | D26 | 24 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | of the signs are not mounted on the latch sides of the doors. | | |
| 13.5 | Alarms. Although the facility contains an emergency alarm system, the alarm system is inaccessible because visual alarms are not provided in all required locations. | AL1 | 30 months |
| 13.6 | Main Recreation Room | | |
| 13.6.a | The kitchen counter protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 13.6.b | The fire extinguisher protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 13.6.c | No accessible coat hook has been provided. | TR1 | 12 months |
| 13.6.d | The pool sticks are inaccessible because they are mounted 55½ inches high. | TR5 | 12 months |
| 13.7 | Picnic Tables in Pavilion. The picnic tables are inaccessible because none provide the required knee space. | PD6 | 30 months |
| 13.8 | Ramp: Behind Recreation Center. The ramp is inaccessible because it slopes more than 8.33%, and the handrails are 41 inches high and lack extensions at the bottom. | R5 | 30 months |

| | | | |
|----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 13.9 | Computer Room. The pull side of the door, which can be accessed from the latch side of the door, is inaccessible because it has only 7 inches of clear width on the latch side. | D10 | 30 months |
| 13.10 | Drinking Fountain: Near Toilet Rooms | | |
| 13.10.a | Although an accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | DF3 | 30 months |
| 13.10.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 13.11 | Women's Toilet Room With Stalls | | |
| 13.11.a | The door is inaccessible because it requires 11 pounds of force to open. | D2 | 12 months |
| 13.11.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 13.11.c | The paper towel dispenser is inaccessible because the controls are mounted 50 inches high over an obstruction. | TR4 | 12 months |
| 13.11.d | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |

| | | | |
|----------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 13.11.e | The soap dispenser is inaccessible because it requires 13 pounds of force to operate. | TR3 | 12 months |
| 13.11.f | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 13.12 | Men's Toilet Room With Stalls | | |
| 13.12.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 13.12.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 13.12.c | The soap dispenser is inaccessible because the controls are mounted 56 inches high over an obstruction. | TR4 | 12 months |
| 13.12.d | The urinal is inaccessible because the rim is 24 inches high and the flush control is 49½ inches high. | TR20 | 30 months |
| 13.12.e | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 13.12.f | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |

| | | | |
|----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 13.12.g | There is no accessible locker provided. | LR3 | 30 months |
| 13.13 | Assembly Area: Weight Training Room. The weight lifting equipment at the entrance door protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 14 | BESSIE BRANHAM RECREATION CENTER, located at 2051 Brownwood Avenue, SE | | |
| 14.1 | Parking Lot. The parking lot, with a total of 25 parking spaces, has no van accessible parking space, and the designated accessible parking spaces are not level. This lot requires 1 van accessible parking space. | P3 | 30 months |
| 14.2 | Accessible Route: From Parking Lot To Main Entrance. The route is inaccessible because the flared sides on the curb cut are too steep. | AR5 | 30 months |
| 14.3 | Arts and Crafts Room. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 14.4 | Community Room. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 14.5 | Men's and Women's Toilet Rooms: Old Section. The toilet rooms have a number of inaccessible features and are not accessible to people with | ST14 | 30 months |

| | | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | disabilities. | | |
| 15 | BITSY GRANT CENTER, located at 2125 Northside Dr., NW | | |
| 15.1 | Accessible Route: to Clubhouse Entrance. The route from the parking area to the clubhouse is inaccessible because the curb ramp has flared sides that slope up to 23.1%. | AR5 | 30 months |
| 15.2 | Pro's Office: Clubhouse. The door to the Pro's office is inaccessible because it has an opening width of 29 inches. | D25 | 30 months |
| 15.3 | Ramp: to Clubhouse Exterior Viewing Deck. The ramp is inaccessible because it lacks edge protection and handrails. | R5 | 30 months |
| 15.4 | Exterior Entrance and Doors: Clubhouse | | |
| 15.4.a | The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 12 months |
| 15.4.b | The double-leaf clubhouse entrance door is inaccessible because each leaf is 27½ inches wide. | D24 | 30 months |
| 15.5 | Interior Clubhouse Signage. There is no signage directing people with disabilities to the accessible toilet room and | TR16 | 24 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | shower. | | |
| 15.6 | Unisex Single-User Toilet Room and Shower: Clubhouse | | |
| 15.6.a | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 15.6.b | The light switch is inaccessible because it is mounted 57 inches high. | TR5 | 12 months |
| 15.6.c | The toilet is inaccessible because the flush control is on the closed side. | SU1 | 24 months |
| 15.6.d | The rear grab bar at the toilet is inaccessible because it is 30 inches long. | SU3 | 24 months |
| 15.6.e | The shower is inaccessible because the clear floor space outside the shower is 36 inches wide, the spray unit hose is 57 inches long, and there is a 1½ inch high curb at the entrance of the stall. | B8 | 30 months |
| 15.7 | Clubhouse Lower Level. There is no access to the lower level of the facility for people with mobility impairments. | AR9 | 30 months |
| 15.8 | Exterior Drinking Fountain: By Hard Tennis Courts. The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 24 months |
| 15.9 | Exterior Accessible Routes: To | | |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | Tennis Courts | | |
| 15.9.a | The route to the clay courts is inaccessible because there is a 1 inch change in level on the sidewalk. | AR1 | 24 months |
| 15.9.b | The route to the clay courts is inaccessible because the built-up curb ramp at the courts slopes 13.5%. | AR5 | 30 months |
| 15.9.c | The route to the hard courts is inaccessible because the built-up curb ramps slope 17.8% at the first set of courts and 20.5% at the second set of courts. | AR5 | 30 months |
| 15.10 | Parking: By Hard Tennis Courts. The parking lot, with a total of 104 parking spaces, has two spaces designated as reserved for people with disabilities. This lot requires 1 van accessible space and 4 standard accessible spaces. | P3 | 30 months |
| 16 | COLLIER PARK AND RECREATION CENTER, located at 3691 Collier Drive, NW | | |
| 16.1 | Parking Lot. The parking lot, with a total of 38 parking spaces, has two designated accessible spaces with no access aisles, and no vertical signage, and one of the designated accessible spaces is not level. This lot requires 1 van accessible space and 1 standard accessible space. | P3 | 30 months |
| 16.2 | Accessible Route: From Parking Lot to Entrance. The route is | AR1 | 30 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | inaccessible because the slope near the entrance is 10.5%. | | |
| 16.3 | Men's Toilet Room With Stalls | | |
| 16.3.a | The door is inaccessible because it requires 12 pounds of force to open. | D2 | 12 months |
| 16.3.b | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 16.3.c | The lavatory is inaccessible because it has twist-type faucets. | TR10 | 24 months |
| 16.3.d | The urinal is inaccessible because the rim is 23 inches high and the flush is 51 inches high. | TR20 | 30 months |
| 16.3.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 16.4 | Women's Toilet Room With Stalls | | |
| 16.4.a | The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 16.4.b | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 16.4.c | The designated accessible stall is incorrectly configured as an | ST15 | 30 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | ambulatory stall, and there is no standard accessible stall provided. | | |
| 16.5 | Recreation Room. The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 16.6 | Exterior Accessible Route | | |
| 16.6.a | The route from the parking lot to the sidewalk is inaccessible because the slope of the curb ramp is 9.1%, the slope of the flared sides is 24%, and there is a 2 inch change in level at the bottom of the curb ramp. | AR5 | 30 months |
| 16.6.b | The sidewalk to the play area is inaccessible because the slope is between 6.1% and 7.4%, and there are no ramp features. | R3 | 30 months |
| 16.6.c | The play area is inaccessible because the play equipment is blocked by wooden and rubber barriers, and there is no stable, firm, and slip resistant route. | AR1 | 30 months |
| 16.6.d | The Life Trail and the routes to the volleyball court and the ball fields are inaccessible because the sidewalks slope up to 14.5%. | AR1 | 30 months |
| 16.7 | Exterior Drinking Fountains. The drinking fountains are operated by foot pedals and are not accessible to people with disabilities. | DF2 | 30 months |
| 17 | ZABAN RECREATION CENTER, located at 241 Daniel Avenue, | | |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | SE | | |
| 17.1 | Parking Lot. The parking lot, with a total of 65 parking spaces, has no designated accessible parking spaces. This lot requires 1 van accessible space and 2 standard accessible spaces. | P3 | 30 months |
| 17.2 | Exterior Accessible Routes | | |
| 17.2.a | The routes throughout the park, including the route from the parking lot to the recreation center, are inaccessible because they are covered in gravel and wood chips. | AR1 | 30 months |
| 17.2.b | The sidewalk to the main entrance is inaccessible because the running slope is 10.9% and the cross-slope is 4.3%. | AR1 | 30 months |
| 17.3 | Recreation Center Main Entrance. The exterior ramp is inaccessible because it does not have accessible handrails. | R4 | 30 months |
| 17.4 | Drinking Fountain: Near Toilet Rooms. Although an accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping | DF3 | 30 months |
| 17.5 | Men's Toilet Room With Stalls | | |
| 17.5.a | The door is inaccessible because it requires 12 pounds of force to open. | D2 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 17.5.b | The toilet room is inaccessible because there is insufficient turning space provided within the room. | TR19 | 30 months |
| 17.5.c | The urinal is inaccessible because the width of the clear floor space is only 28 inches. | TR20 | 30 months |
| 17.5.d | The toilet stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 17.6 | Women's Toilet Room With Stalls | | 30 months |
| 17.6.a | The door is inaccessible because it requires 12 pounds of force to open. | D2 | 30 months |
| 17.6.b | The toilet room is inaccessible because there is insufficient turning space provided within the room. | TR19 | 30 months |
| 17.6.c | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 30 months |
| 17.6.d | The toilet stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 17.7 | Interior Ramp: Down to Exercise/Storage Room The ramp is inaccessible because the inside handrail is not continuous and the ramp is covered in stored | R3 | 30 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | furniture and other items. | | |
| 18 | ATLANTA POLICE ZONE 3, located at 880 Cherokee Avenue | | |
| 18.1 | Accessible Route: Curb Ramp to Main Exterior Door. The route is inaccessible because the short ramp has a 2 inch step at the bottom and a ¾ inch step at the top. | AR1 | 30 months |
| 18.2 | Main Entrance. The pull side of the main entrance door, which is accessed through a front approach, is inaccessible because it has only 3 inches of maneuvering space on the latch side. | D6 | 30 months |
| 18.3 | Unisex Single-User Toilet Room: Main Lobby | | |
| 18.3.a | The door is inaccessible because it requires 20 pounds of force to open. | D2 | 12 months |
| 18.3.b | The toilet room is inaccessible because the door has knob hardware. | D1 | 24 months |
| 18.3.c | The toilet is inaccessible because the centerline is 16 inches from the side wall. | SU15 | 30 months |
| 18.4 | 2 nd Floor. There is no access to the upper level of the facility for people with mobility impairments. | AR9 | 30 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 18.5 | Drinking Fountain: Lower Level. Although an accessible drinking fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping | DF3 | 30 months |
| 18.6 | Women's Toilet Room With Stalls: Lower Level | | |
| 18.6.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 24 months |
| 18.6.b | The door is inaccessible because it requires 6 pounds of force to open. | D2 | 12 months |
| 18.6.c | The pull side of the door to the toilet room, which is accessed through a front approach, is inaccessible because it has only 17 inches of maneuvering space on the latch side. | D6 | 30 months |
| 18.6.d | The toilet room door swings into the required clear floor space at the lavatory. | TR6 | 30 months |
| 18.6.e | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 18.6.f | The designated accessible toilet is inaccessible because the stall is 45 inches wide. | ST16 | 30 months |
| 18.6.g | The designated accessible toilet is inaccessible because its centerline is 14 inches from the side wall. | ST17 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 18.6.h | The designated accessible toilet is inaccessible because the flush control is on the closed side. | ST2 | 30 months |
| 18.6.i | No accessible coat hook has been provided. | TR1 | 12 months |
| 18.7 | Men's Toilet Room With Stalls: Lower Level | | |
| 18.7.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 24 months |
| 18.7.b | The door is inaccessible because it requires 6 pounds of force to open. | D2 | 12 months |
| 18.7.c | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 18.7.d | The urinal is inaccessible because the rim is 23 inches high and the flush is 51 inches high. | TR20 | 30 months |
| 18.7.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 19 | ATLANTA POLICE ZONE 4, located at 1125 Cascade Circle | | |
| 19.1 | Exterior Accessible Route: From Street Parking to Entrance. The route is inaccessible because the it slopes between 5.6% and 7.1% and has no ramp features. | R3 | 30 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 19.2 | Interior Accessible Route: From Main Lobby to Toilet Rooms. The office doors are inaccessible because knob hardware is used. | D1 | 24 months |
| 19.3 | Men's Toilet Room With Stalls | | |
| 19.3.a | The toilet room sign is mounted on the door and lacks raised and Braille characters. | TR18 | 24 months |
| 19.3.b | The door is inaccessible because it requires 9 pounds of force to open. | D2 | 12 months |
| 19.3.c | The pull side of the door, which is accessed through a front approach, is inaccessible because it has only 2½ inches of maneuvering space on the latch side. | D6 | 30 months |
| 19.3.d | The toilet room door swings into the required clear floor space at the lavatory. | TR6 | 30 months |
| 19.3.e | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 19.3.f | No accessible mirror has been provided. | TR14 | 12 months |
| 19.3.g | The toilet room is inaccessible because there is insufficient turning space provided within the room. | TR19 | 30 months |
| 19.3.h | The soap dispenser is inaccessible because it is | TR4 | 12 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | mounted with the controls 55 inches high over the lavatory. | | |
| 19.3.i | The lavatory is inaccessible because the rim or counter is 35½ inches high to the top. | TR11 | 24 months |
| 19.3.j | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 19.3.k | The urinal is inaccessible because the rim is 24 inches high and the flush control is 48 inches high. | TR20 | 30 months |
| 19.3.l | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 19.4 | Women's Toilet Room With Stalls | | |
| 19.4.a | The toilet room sign is mounted on the door and lacks raised and Braille characters. | TR18 | 24 months |
| 19.4.b | The door is inaccessible because it requires 9 pounds of force to open. | D2 | 12 months |
| 19.4.c | The pull side of the door, which is accessed through a front approach, is inaccessible because it has only 7 inches of maneuvering space on the latch side. | D6 | 30 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 19.4.d | The toilet room door swings into the required clear floor space at the lavatory. | TR6 | 30 months |
| 19.4.e | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 19.4.f | No accessible mirror has been provided. | TR14 | 12 months |
| 19.4.g | The toilet room is inaccessible because there is insufficient turning space provided within the room. | TR19 | 30 months |
| 19.4.h | The seat cover dispenser is inaccessible because it is mounted with the controls 58 inches high. | TR5 | 12 months |
| 19.4.i | The lavatory is inaccessible because the hot water pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 19.4.j | The urinal is inaccessible because the rim is 24 inches high and the flush control is 48 inches high. | TR20 | 30 months |
| 19.4.k | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 20 | ATLANTA FIRE STATION 15, located at 170 10th Street, NE | | |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 20.1 | Unisex Single-User Toilet Room | | |
| 20.1.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 24 months |
| 20.1.b | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 20.1.c | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 20.1.d | The lavatory is inaccessible because the hot water and drain pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 20.1.e | The toilet is inaccessible because the top of the seat is 16 inches high. | SU18 | 30 months |
| 20.1.f | The toilet is inaccessible because the centerline is 27 inches from the side wall. | SU15 | 30 months |
| 20.1.g | The toilet is inaccessible because the rear grab bar is 24 inches long and it is mounted 14½ inches from the side wall. | SU3 | 24 months |
| 21 | ATLANTA FIRE STATION 17, located at 1489 Ralph David Abernathy Boulevard, SW | | |
| 21.1 | Parking Lot. The parking lot, with a total of 4 parking spaces, has no designated accessible parking | P3 | 24 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | space. This lot requires 1 van accessible space. | | |
| 21.2 | Accessible Route: From Street to Main Entrance. The route is inaccessible because the slope of the walkway is 13%. | AR1 | 30 months |
| 21.3 | Unisex Single-User Toilet Room: 1 st Floor | | |
| 21.3.a | The toilet room sign is mounted on the door and has no raised or Braille characters. | TR18 | 24 months |
| 21.3.b | Although an audible alarm is provided in this facility, there is no visual alarm appliance in the toilet room. | TR21 | 30 months |
| 21.3.c | The lavatory is inaccessible because the rim or counter is 26 inches high to the bottom. | TR11 | 24 months |
| 21.3.d | The lavatory is inaccessible because the hot water and drain pipes are not insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 21.3.e | The toilet is inaccessible because the flush control is on the closed side. | SU1 | 24 months |
| 21.3.f | The toilet is inaccessible because the side grab bar is mounted with the far end 50½ inches from the rear wall. | SU6 | 12 months |
| 22 | ATLANTA FIRE STATION 35, located at 2150 East | | |

| | Non-Licensed Vehicle Road | | |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 22.1 | Parking Lot. The parking lot, with 25 total parking spaces, is inaccessible because it has no space designated as van accessible. This lot requires 1 van accessible space. | P3 | 24 months |
| 22.2 | Exterior Accessible Route: From Parking Lot to Entrance | | |
| 22.2.a | The route is inaccessible because the width of the walkway narrows to 21 inches at the pipes and to 22½ inches at the barbeque grill. | AR3 | 30 months |
| 22.2.b | The shelf of the barbeque grill protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 22.3 | Interior Accessible Route: To Blood Pressure Screening Room 127. The route from the entrance to room 127 is inaccessible because it narrows to 22 inches wide at the sofa. | AR3 | 12 months |
| 22.4 | Blood Pressure Screening Room: 127 | | |
| 22.4.a | The signage provided has no raised or Braille characters. | D26 | 24 months |
| 22.4.b | The route inside the room is inaccessible because it is only 30 inches wide between the chair and the open door. | AR3 | 12 months |
| 22.5 | Unisex Toilet Room With Stalls: | | |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | 124 | | |
| 22.5.a | The toilet room sign has no raised or Braille characters. | TR18 | 24 months |
| 22.5.b | The door is inaccessible because it requires 7 pounds of force to open. | D2 | 12 months |
| 22.5.c | The urinal is inaccessible because the rim is 18 inches high and the flush control is 46 inches high. | TR20 | 30 months |
| 22.5.d | No accessible coat hook has been provided. | TR1 | 12 months |
| 22.5.e | The designated accessible toilet is inaccessible because the rear grab bar is mounted 7 inches from the near side wall. | SU3 | 12 months |
| 23 | DUNBAR NEIGHBORHOOD FACILITY, located at 477 Windsor Street, SW | | |
| 23.1 | Parking Lot. The parking lot, with a total of 106 parking spaces, has only 4 designated accessible parking spaces, the designated accessible parking spaces have no vertical signage and no access aisles, and one of the designated accessible spaces has a cross slope of 3.4%. This lot requires 1 van accessible space and 4 standard accessible spaces. | P3 | 30 months |
| 23.2 | Accessible Route: 2 nd Floor. The defibrillator protrudes into the walkway and is not detectable to | AR8 | 12 months |

| | | | |
|---------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | blind persons using a cane. | | |
| 23.3 | Drinking Fountains: 2 nd Floor | | |
| 23.3.a | The drinking fountain is inaccessible because the control requires 15 pounds of force to operate. | DF2 | 12 months |
| 23.3.b | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 23.4 | Women's Toilet Room With Stalls: 2 nd Floor | | |
| 23.4.a | The toilet room sign is mounted above the door and has no raised or Braille characters. | TR18 | 24 months |
| 23.4.b | The door is inaccessible because it requires 10 pounds of force to open. | D2 | 12 months |
| 23.4.c | The pull side of the door, which is accessed through a front approach, is inaccessible because it has only 12 inches of clear space on the latch side. | D6 | 30 months |
| 23.4.d | No accessible mirror has been provided. | TR14 | 12 months |
| 23.4.e | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 23.4.f | The designated accessible stall is incorrectly configured as an | ST15 | 30 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | ambulatory stall, and there is no standard accessible stall provided. | | |
| 23.5 | Men's Toilet Room With Stalls: 2 nd Floor | | |
| 23.5.a | The toilet room sign is mounted above the door and has no raised or Braille characters. | TR18 | 24 months |
| 23.5.b | The door is inaccessible because it requires 11 pounds of force to open. | D2 | 12 months |
| 23.5.c | No accessible mirror has been provided. | TR14 | 12 months |
| 23.5.d | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 23.5.e | The urinals are inaccessible because the rims are 21 inches high. | TR20 | 24 months |
| 23.5.f | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 23.6 | Elevator. The elevator is inaccessible because, although emergency communications are provided, the system does not work without voice communication. | E8 | 30 months |
| 23.7 | Offices and Rooms. The doors are inaccessible because they | D2 | 12 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | require more than 5 pounds of force to open. | | |
| 24 | JOHN C. BIRDINE NEIGHBORHOOD FACILITY, located at 215 Lakewood Way, SW | | |
| 24.1 | Parking Lot. The parking lot, with a total of 81 parking spaces, has no van accessible parking space, has no vertical signage designating spaces as accessible, and has designated accessible spaces and access aisles that slope between 5.2% and 7.7%. This lot requires 1 van accessible space and 3 standard accessible spaces. | P3 | 30 months |
| 24.2 | Exterior Accessible Route: From Parking Lot to Main Entrance | | |
| 24.2.a | The route is inaccessible because the cross-slope of the walkway is 6.4%. | AR1 | 30 months |
| 24.2.b | The route is inaccessible because the slope of the curb ramp is 17.6%, and the flared sides are too steep. | AR5 | 30 months |
| 24.3 | Main Lobby: Counter. The reception counter in the 1 st floor lobby is inaccessible because it is 42½ high. | C6 | 24 months |
| 24.4 | Women's Toilet Room With Stalls: 1 st Floor West Side | | |
| 24.4.a | The toilet room sign is mounted | TR17 | 24 months |

| | | | |
|---------------|---------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | on the door and has no raised or Braille characters and no International Symbol of Accessibility. | | |
| 24.4.b | The door is inaccessible because it requires 17 pounds of force to open. | D2 | 12 months |
| 24.4.c | No accessible mirror has been provided. | TR14 | 12 months |
| 24.4.d | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 24.4.e | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 24.5 | Men's Toilet Room With Stalls: 1 st Floor West Side | | |
| 24.5.a | The toilet room sign is mounted on the door and has no raised or Braille characters and no International Symbol of Accessibility. | TR17 | 24 months |
| 24.5.b | The door is inaccessible because it requires 14 pounds of force to open. | D2 | 12 months |
| 24.5.c | No accessible mirror has been provided. | TR14 | 12 months |
| 24.5.d | The air dryer protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 24.5.e | The urinal is inaccessible because the rim is 23 inches high. | TR20 | 24 months |
| 24.5.f | The designated accessible stall is incorrectly configured as an ambulatory stall, and there is no standard accessible stall provided. | ST15 | 30 months |
| 24.6 | Drinking Fountains: 1 st Floor West Side. The higher drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 24.7 | Women's and Men's Toilet Rooms with Stalls: 1 st Floor East Side. The toilet rooms lack accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible toilet room. | TR16 | 24 months |
| 24.8 | Interior Accessible Route: 1 st Floor East Side. The defibrillator protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 24.9 | Library. The library is inaccessible because the automatic door opener requires 14 pounds of force to operate. | TR3 | 12 months |
| 24.10 | Women's and Men's Toilet Rooms with Stalls: 2 nd Floor West Side: The toilet rooms lack accessible directional signage with the International Symbol of Accessibility indicating the location of the nearest accessible | TR16 | 24 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| | toilet room. | | |
| 24.11 | Drinking Fountains: 2 nd Floor West Side. The higher drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 24.12 | East Wing Counter. The counter is inaccessible because it is 40 inches high. | C6 | 24 months |
| 25 | MADDOX PARK, located at 1145 North Avenue, NW | | |
| 25.1 | Parking Lot. The parking lot, with a total of 12 parking spaces, has no designated accessible parking spaces. This lot requires 1 van accessible space. | P3 | 24 months |
| 25.2 | Exterior Accessible Routes | | |
| 25.2.a | There is no accessible route to the tennis court because there is no curb ramp from the road. | AR5 | 30 months |
| 25.2.b | The route to the pavilion is inaccessible because it has numerous stairs. | AR1 | 30 months |
| 25.3 | Picnic Tables. There are no accessible picnic tables provided. | PD6 | 30 months |
| 25.4 | Locker Rooms. The men's and women's locker rooms contain a number of inaccessible elements and are not accessible to people with disabilities. | LR4 | 30 months |

| | | | |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----------|
| 26 | CHASTAIN ARTS CENTER, located at 135 W. Wieuca Road, NW | | |
| 26.1 | Parking. The parking lot, with a total of 28 parking spaces, is inaccessible because the designated accessible spaces have no access aisles and no vertical signage. This lot requires 1 van accessible space and 1 standard accessible space. | P3 | 24 months |
| 26.2 | Ramp to Entry | | |
| 26.2.a | The ramp is inaccessible because it has a lip at the top and the bottom 1 inch high. | AR1 | 30 months |
| 26.2.b | The ramp is inaccessible because it has insufficient landing at the bottom and at the change in direction, it slopes between 10.5% and 11.1%, it does not have adequate edge protection, and the handrails lack extensions. | R3 | 30 months |
| 26.3 | Curb Ramp. The curb ramp is inaccessible because it has a slope of 9.6%. | AR5 | 24 months |
| 26.4 | Entrances. The building does not have directional signage posted at inaccessible entrances and does not have the International Symbol of Accessibility posted at accessible entrances. | D16 | 24 months |
| 26.5 | Front Entrance | | |
| 26.5.a | The route from the entry ramp to | AR1 | 24 months |

| | | | |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| | the front door is inaccessible because it slopes 9.4% and has no handrails. | | |
| 26.5.b | The route to the front door is inaccessible because the ramp's front edge has a 1 inch high step up onto it. | AR1 | 24 months |
| 26.5.c | The front door is inaccessible because there is a slope of 10.8% within the door's required maneuvering clearance. | D13 | 24 months |
| 26.6 | Children's Studio Entrance. The ramp to the entrance is inaccessible because it slopes up to 16.8%, it does not have adequate edge protection, and the handrail is mounted 2 inches from the wall. | R3 | 24 months |
| 26.7 | Men's Single-User Toilet Room: Near Children's Studio | | |
| 26.7.a | No accessible mirror has been provided. | TR14 | 12 months |
| 26.7.b | The lavatory is inaccessible because the hot water pipes are not fully insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 26.7.c | The toilet is inaccessible because its centerline is 19½ inches from the side wall. | SU15 | 30 months |
| 26.7.d | The side grab bar at the toilet is inaccessible because it is mounted 15 inches from the rear wall. | SU6 | 12 months |

| | | | |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 26.8 | Women's Single-User Toilet Room: Near Children's Studio | | |
| 26.8.a | No accessible mirror has been provided. | TR14 | 12 months |
| 26.8.b | The lavatory is inaccessible because the hot water pipes are not fully insulated or otherwise configured to protect against contact. | TR12 | 24 months |
| 26.8.c | The side grab bar at the toilet is inaccessible because it is mounted 15 inches from the rear wall. | SU6 | 12 months |
| 26.9 | Drinking Fountain: Main Entry. The drinking fountain is inaccessible because the spout is 41½ inches high, the water flow is 3 inches high, the water flows 4 inches from the front of the fountain, and the controls require 9 pounds of force to operate. | DF1 | 30 months |
| 26.10 | Interior Doors. Many of the doors are inaccessible because knob hardware is used. | D1 | 24 months |
| 26.11 | Interior Accessible Route. The suggestion box in the classroom hallway protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 26.12 | Inaccessible Toilet Rooms. There is no signage directing people with disabilities to the accessible toilet rooms. | TR16 | 30 months |

| | | | |
|----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------|
| 26.13 | Pottery Studio: Main Building | | |
| 26.13.a | No accessible coat hook has been provided. | TR1 | 12 months |
| 26.13.b | The fire extinguisher protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 26.14 | City Gallery: Main Entrance. The door is inaccessible because there is a 1½ inch high threshold. | D23 | 24 months |
| 26.15 | City Gallery: Painting Studio. The door is inaccessible because there is a 1½ inch high threshold. | D23 | 24 months |
| 26.16 | City Gallery: Studio I and II. The doors are inaccessible because knob hardware is used. | D1 | 24 months |
| 26.17 | City Gallery: Toilet Rooms. The toilet rooms contain a number of inaccessible elements and are not accessible to people with disabilities, and there is no signage directing people with disabilities to the accessible toilet rooms. | TR16 | 30 months |
| 26.18 | City Gallery: Drinking Fountain. | | |
| 26.18.a | The drinking fountain protrudes into the walkway and is not detectable to blind persons using a cane. | AR8 | 12 months |
| 26.18.b | Although an accessible drinking | DF3 | 30 months |

| | | | |
|--|------------------------------------------------------------------------------------------------------------------|--|--|
| | fountain is provided, there is no drinking fountain provided for people who have difficulty bending or stooping. | | |
|--|------------------------------------------------------------------------------------------------------------------|--|--|

[Project Civic Access](#) | [ADA Home Page](#)

Attachment L

Reserved.

[Project Civic Access](#) | [ADA Home Page](#)

Attachment M: Actions Required to Remedy Accessibility Violations

This Attachment provides a detailed description of the actions that must be taken to remedy accessibility violations listed in other parts of this Agreement. Each required action is referenced by an alphanumeric code – *i.e.*, a code consisting of one or more letters followed by a number. The required actions are listed in alphabetic/numeric order based on the specific code used to reference each required action. The term "Standards" refers to the ADA Standards for Accessible Design, 28 C.F.R. Pt. 36, Appendix A.

| Code | Required Actions |
|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AA1 | Provide an accessible route connecting the wheelchair seating locations with all performing areas, including stages, arena floors, dressing rooms, locker rooms, and other spaces used by performers. Standards §§ 4.1.3(19)(a), 4.3, 4.33.5. |
| AA2 | Provide aisle seats with no armrest on the aisle side, or with a removable or folding armrest on the aisle side, identified by a sign or marker, equal in number to 1% of the total number of seats (but not less than 1). Provide signage in the ticket office notifying patrons that such seating is available. Standards § 4.1.3(19)(a). |
| AA3 | Provide accessible signage indicating the availability of the assistive listening system. 28 C.F.R. § 35.160; Standards §§ 4.1.3(19)(b), 4.30. |
| AA4 | Provide a permanently installed assistive listening system serving the fixed seating. Ensure that the seating served by the system is located within a 50 foot viewing distance of the stage or playing area and has a complete view of the stage or playing area. Provide receivers equal in number to 4% of the total number of seats (but at least 2) for use by the general public, and provide signage indicating their availability. 28 C.F.R. § 35.160, Standards §§ 4.1.3(19)(b), 4.30, 4.33. |
| AA5 | Provide a permanently installed assistive listening system (ALS) or a portable ALS with an adequate number of electrical outlets or other supplementary wiring necessary to support a portable assistive listening system. Also provide receivers equal in number to 4% of the total number of seats (but no fewer than 2) for use by the general public, and provide signage indicating their availability. 28 C.F.R. § 35.160, Standards §§ 4.1.3(19)(b), 4.30, 4.33. |
| AA6 | Provide the number of wheelchair seating areas shown in the following |

| Code | Required Actions | |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------|
| | <p>chart, each with a minimum clear ground or floor space of 33 inches wide by 48 inches deep for forward or rear access, or 33 inches wide by 60 inches deep for side access. Ensure that the ground or floor at all wheelchair locations is level, firm, stable, and slip resistant; that wheelchair seating areas are an integral part of the fixed seating plan and are located so as to provide people with physical disabilities a choice of admission prices and lines of sight comparable to those available to members of the general public; that wheelchair seating areas adjoin an accessible route that also serves as a means of egress in case of emergency; and that at least one fixed companion seat, identified by signage, is provided next to each wheelchair location. When the seating capacity exceeds 300, wheelchair seating areas shall be provided in more than one location. Standards §§ 4.1.3(19)(a), 4.5, 4.33, Fig. 46.</p> | |
| | Seating Capacity of Assembly Area | Number of Required Wheelchair Locations |
| | 4 to 25 | 1 |
| | 26 to 50 | 2 |
| | 51 to 300 | 4 |
| | 301 to 500 | 6 |
| | over 500 | 6, plus 1 additional space for each total seating capacity increase of 100 |
| AA7 | <p>Provide the number of wheelchair seating areas shown in the preceding chart, each with a minimum clear ground or floor space of 33 inches wide by 48 inches deep for forward or rear access, or 33 inches wide by 60 inches deep for side access. Ensure that the ground or floor at all wheelchair locations is level, firm, stable, and slip resistant; that wheelchair seating areas are an integral part of the fixed seating plan and are located in all areas, including specialty areas, such as skyboxes and suites, so as to provide people with physical disabilities a choice of admission prices and lines of sight comparable to those available to members of the general public; that wheelchair seating areas adjoin an accessible route that also</p> | |

| Code | Required Actions |
|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | serves as a means of egress in case of emergency; and that at least one fixed companion seat, identified by signage, is provided next to each wheelchair seating area. In stadiums where spectators can be expected to stand during the show or event (for example, football, baseball, basketball games, or rock concerts), all or substantially all of the wheelchair seating locations must provide a line of sight over standing spectators. Standards §§ 4.1.3(19)(a), 4.5, 4.33, Fig. 46. |
| AA8 | Install a ramp or platform lift in compliance with the Standards or establish a procedure for providing access to this area. Any procedure shall not require lifting or carrying persons with mobility impairments or require them to traverse unnecessary or extreme distances. Provide a wheelchair seating area with a minimum clear ground or floor space of 33 inches wide by 48 inches deep for forward or rear access, or 33 inches wide by 60 inches deep for side access. Standards §§ 4.33.5, 4.3.8, 4.8, 4.11, Fig. 46. |
| AA9 | Provide at least one wheelchair seating area within the jury box with a minimum clear ground or floor space of 66 inches wide by 48 inches deep for forward or rear access, or 66 inches wide by 60 inches deep for side access. Ensure that wheelchair seating areas are an integral part of the fixed seating plan of the jury box and are located so as to provide people with physical disabilities with a line of sight comparable to those available for other members of the jury; and that wheelchair seating areas adjoin an accessible route that also serves as a means of egress in case of emergency. Standards §§ 4.1.3(19)(a), 4.5, 4.33. |
| AL1 | Provide visual alarm devices in toilet rooms and any other general usage areas (e.g., meeting rooms), hallways, lobbies, and any other area for common use. Such devices shall be integrated into the facility alarm system and shall meet the requirements of the Standards for lamp type, color, pulse duration, intensity, and flash rate. Visual alarm appliances shall be placed 80 inches above the highest floor level within the space or 6 inches below the ceiling, whichever is lower. Visual alarm appliances shall be located such that no place in any room or space, including common corridors or hallways, required to have a visual alarm appliance shall be more than 50 feet from the signal. In large rooms and spaces exceeding 100 feet across, without obstructions 6 feet above the finished floor, devices may be placed around the perimeter, spaced a maximum of 100 feet apart, in lieu of suspending appliances from the ceiling. Standards §§ 4.1.3(14), 4.28.3. |

| Code | Required Actions |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AR1 | Provide at least one accessible route to each area, feature, or element described that, to the maximum extent feasible, coincides with the route for the general public. The accessible route must have a minimum clear width of 36 inches, or a minimum clear width of 42 inches if there is a turn around an obstruction less than 48 inches wide; have passing spaces at least 60 inches by 60 inches at least every 200 feet; have a minimum clear headroom of 80 inches; have a surface that is firm, stable, and slip resistant; have, in the absence of a curb ramp, ramp, elevator, or platform lift, no level changes in excess of ½ inch vertically; have no level changes greater than ¼ inch vertically unless they are beveled with a slope no greater than 50%; and have a running slope no greater than 5% (or have been constructed as a fully accessible ramp) and a cross slope no greater than 2%. Standards §§ 4.1.3(1), 4.3, 4.5, Fig. 7. |
| AR2 | Provide at least one accessible route to each area, feature, or element described. The accessible route must have a minimum clear width of 36 inches, or a minimum clear width of 42 inches if there is a turn around an obstruction less than 48 inches wide; have passing spaces at least 60 inches by 60 inches at least every 200 feet; have a minimum clear headroom of 80 inches; have a surface that is firm, stable, and slip resistant; have, in the absence of a curb ramp, ramp, elevator, or platform lift, no level changes in excess of ½ inch vertically; have no level changes greater than ¼ inch vertically unless they are beveled with a slope no greater than 50%; and have a running slope no greater than 5% (or have been constructed as a fully accessible ramp) and a cross slope no greater than 2%. Standards §§ 4.1.3(1), 4.3, 4.5, Fig. 7. |
| AR3 | Provide an accessible route to each area, feature, or element described with a minimum clear width of 36 inches, except at doors, where the width may decrease to 32 inches. Standards §§ 4.1.3(1), 4.3.3, 4.13.5. |
| AR4 | Provide a curb ramp in each area or location described, which is located so that it does not project into the element described and all aspects of the ramp or curb cut comply with the Standards. Standards §§ 4.1.2(1), 4.1.2(2), 4.3.8, 4.7.6. |
| AR5 | Provide a curb ramp that is at least 36 inches wide, has a maximum slope of 8.33% and a maximum cross slope of 2%, is located so that it cannot be obstructed by parked vehicles, has transitions on and off that are flush and free of abrupt changes, and has a stable, firm, and slip-resistant surface with a detectable warning extending the full width and depth of the ramp. If the curb ramp is located where pedestrians must walk across it, provide |

| Code | Required Actions |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | either flared sides (with a maximum slope of 10%) or handrails or guardrails to protect against cross traffic. Standards §§ 4.1.2(1), 4.1.2(2), 4.3.7, 4.3.8, 4.7, Fig. 12. |
| AR6 | Where gratings are provided on walking surfaces, provide gratings that have spaces no greater than ½ inch wide in one direction. If gratings have elongated openings, then they shall be placed so that the long dimension is perpendicular to the dominant direction of travel. Standards §§ 4.1.2(1), 4.5.4, Figs. 8(g), 8(h). |
| AR7 | Provide an accessible route at this location with a minimum of 80 inches of clear head room throughout. If the vertical clearance is reduced to less than 80 inches at any point, provide a barrier. Standards §§ 4.1.3(2), 4.4.2, Fig. 8(c-1). |
| AR8 | Provide a circulation path at this location such that no objects have their leading edges protruding more than 4 inches into walks, halls, corridors, passageways, or aisles at a height between 27 inches and 80 inches above the finished floor or ground. Free-standing objects mounted on posts or pylons may overhang no more than 12 inches at a height between 27 and 80 inches above the finished floor or ground. Providing a cane-detectable barrier is an acceptable solution. A protruding object (and cane-detectable barrier) shall not reduce the clear width of an accessible route or maneuvering space. Standards §§ 4.1.2(3), 4.4. |
| AR9 | Establish a procedure for providing access to programs in upper and lower levels of the facility or install ramps, platform lifts, or an elevator in compliance with the Standards. Any procedure shall not require lifting or carrying persons with mobility impairments or require them to traverse unnecessary or extreme distances. Standards §§ 4.33.5, 4.3.8, 4.8, 4.11. |
| AR10 | Provide stairs with closed risers, uniform tread width and riser height, a tread depth of at least 11 inches measured from riser to riser, and nosings, treads, and risers that otherwise comply fully with the Standards. Provide handrails on both sides of the stairs such that the inside handrail on switchbacks or doglegs is continuous. Ensure that handrails which do not continue beyond the top and bottom of the stairs extend at least 12 inches beyond the top riser and at least 12 inches plus the width of one tread beyond the bottom riser; that there is a clear space between the handrails and the wall of 1½ inches; that handrail gripping surfaces are uninterrupted by newel posts, other construction elements, or obstructions; that handrails |

| Code | Required Actions |
|-------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | are mounted between 34 and 38 inches above stair nosings; and that the ends of the handrails are either rounded or returned smoothly to the floor, wall, or post; and the handrails do not rotate within their fittings. Standards §§ 4.1.3(4), 4.9. |
| B1 | Provide a bathtub that has a minimum clear floor space measuring at least 30 inches wide by 60 inches long alongside the bathtub. An accessible lavatory may be provided within the clear space at the foot end of the tub (shower head side). Standards §§ 4.1.3(11), 4.23.8, 4.20.2. |
| B2 | Provide a bathtub that has a minimum clear floor space measuring at least 48 inches wide by 60 inches long alongside the bathtub. An accessible lavatory may be provided within the clear space at the foot end of the tub (shower head side). Standards §§ 4.1.3(11), 4.23.8, 4.20.2. |
| B3 | Provide a bathtub with clear floor space measuring at least 30 inches wide by 75 inches long alongside the bathtub. Ensure that the seat is at least 15 inches wide, measured from the back wall to the front of the seat, and that it extends the full width of the tub. An accessible lavatory is permitted within the clear space at the foot end of the tub (shower head side). Standards §§ 4.1.3(11), 4.23.8, 4.20.2. |
| B4 | Provide a bathtub that has one horizontal grab bar at the foot of the tub that extends at least 24 inches from the outer edge of the tub toward the back (long) wall of the tub; two parallel horizontal grab bars, each at least 24 inches long, located no more than 12 inches from the foot of the tub and 24 inches from the head of the tub (one bar should be mounted 9 inches above the rim of the tub and the other mounted between 33 and 36 inches above the bathroom floor); and one horizontal grab bar at least 12 inches long located on the wall at the head of the tub, towards the outside of the tub. Standards §§ 4.1.3(11), 4.23.8, 4.20.4, 4.26, Fig. 34(a). |
| B5 | Provide a bathtub that has one horizontal grab bar at the foot of the tub that extends at least 24 inches from the outer edge of the tub toward the back (long) wall of the tub; two parallel horizontal grab bars, each at least 48 inches long, located on the back (long) wall no more than 12 inches from the foot of the tub and 15 inches from the head of the tub (one bar should be mounted 9 inches above the rim of the tub and the other should be mounted between 33 and 36 inches above the bathroom floor); and no grab bar at the head of the tub. Standards §§ 4.1.3(11), 4.23.8, 4.20.4, 4.26, Fig. 34(b). |

| Code | Required Actions |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| B6 | Provide a bathtub that has the following: a transfer seat securely mounted such that it does not slip during use; clear floor space that complies with Fig. 33; controls mounted below the grab bar at the foot of the tub, which are operable with one hand, without tight grasping, pinching, or twisting of the wrist, and which require no more than 5 pounds of force to operate; an adjustable height shower spray unit mounted on a vertical bar with a hose at least 60 inches long that can be used both as a fixed shower head and as a hand-held shower; grab bars that comply with Fig. 34; and enclosures, if any, that do not obstruct bathtub controls or obstruct transfers from wheelchairs onto bathtub seats or into tubs and that do not have tracks mounted on their rims. Standards §§ 4.1.3(11), 4.23.8, 4.20, Figs. 33, 34. |
| B7 | Provide accessible entry into shower stalls that are exactly 36 inches wide and 36 inches deep such that any curb at the shower entrance is no higher than ½ inch. Provide accessible entry into shower stalls that are at least 30 inches deep and 60 inches wide such that there is no curb or threshold at the shower entrance. Standards §§ 4.1.3(11), 4.21.7. |
| B8 | Provide a shower in this room that is exactly 36 inches wide and 36 inches deep with an L-shaped shower seat mounted on the wall opposite the controls and extending the full depth of the stall, with a 48 inch long and 36 inch wide clear floor space alongside the shower opening which extends 12 inches beyond the shower wall on which the seat is mounted, enabling a parallel approach (Fig. 35(a)), and with a curb no greater than ½ inch OR a shower that is at least 30 inches deep and 60 inches wide with no curb or threshold and with a 36 inch deep and 60 inch wide clear floor space at the shower opening (Fig. 35(b)). Ensure that the shower has grab bars, controls, a shower spray unit, and a seat, curb, and enclosure, if provided, that comply fully with the Standards and with Figs. 35, 36, and 37, as applicable. Standards §§ 4.1.3(11), 4.21, Figs. 35, 36, 37. |
| B9 | Provide grab bars that extend 18 inches on the wall adjacent to the seat, with the closer end touching the control wall, and that extend the full length of the control wall, between 33 and 36 inches high. Standards §§ 4.1.3(11), 4.21.4, Fig. 37. |
| B10 | For shower stalls that are exactly 36 inches wide and 36 inches deep, provide a seat mounted between 17 and 19 inches high on the wall opposite the controls and extending the full depth of the stall. Standards §§ 4.1.3(11), 4.21.3. |

| Code | Required Actions | |
|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| B11 | Provide a shower in this room that has a shower spray unit with a hose at least 60 inches long that can be used both as a fixed shower head and as a hand-held shower. In unmonitored facilities where vandalism is a consideration, a fixed shower head mounted at 48 inches above the shower floor may be used in lieu of a hand-held shower head. Standards §§ 4.1.3(11), 4.21.6, Fig. 37. | |
| C1 | Provide at least one accessible check-out aisle at least 36 inches wide (or 32 inches wide at any point not exceeding 24 inches in length) with maximum adjoining counter height of no more than 38 inches above the finished floor and a counter lip no more than 40 inches above the finished floor. Provide signage identifying accessible check-out aisles in the same location where the check-out number or type is displayed. Standards §§ 4.1.1(2), 7.3. | |
| C2 | Provide accessible check-out aisles, as required in the following chart, at least 36 inches wide (or 32 inches wide at any point not exceeding 24 inches in length) with maximum adjoining counter height of no more than 38 inches above the finished floor and a counter lip no more than 40 inches above the finished floor. Provide signage identifying accessible check-out aisles in the same location where the check-out number or type is displayed. Standards §§ 4.1.2(2), 7.3. | |
| | Total Check-out Aisles of Each Design | Minimum Number of Accessible Check-out Aisles of Each Design |
| | 1 to 4 | 1 |
| | 5 to 8 | 2 |
| | 9 to 15 | 3 |
| over 15 | 3, plus 20% of additional aisles | |
| C3 | Provide a computer on a table or counter that has clear floor space that is 30 inches wide and 48 inches deep, knee clearance at least 27 inches high, | |

| Code | Required Actions |
|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | 30 inches wide, and 19 inches deep, and a writing surface between 28 and 34 inches above the finished floor. Standards §§ 4.1.3(18), 4.2.4.1, 4.32. |
| C4 | Provide counters dispersed throughout the facility on accessible routes such that each counter has a portion at least 36 inches wide and no more than 36 inches above the finished floor. Standards §§ 4.1.1(2), 7.2(1), 4.1.3(1), 4.3. |
| C5 | Provide a counter on an accessible route such that a portion of the counter is at least 36 inches wide and no more than 36 inches above the finished floor. Standards §§ 4.1.1(2), 7.2(1), 4.1.3(1), 4.3. |
| C6 | Provide a counter on an accessible route such that a portion of the counter is at least 36 inches wide and no more than 36 inches above the finished floor, or provide an auxiliary counter with a maximum height of 36 inches in close proximity to the main counter, or provide equivalent facilitation. Equivalent facilitation may be provided in the form of a folding shelf attached to the main counter, an auxiliary table nearby, a clip board made available to the public, or other effective means. Standards §§ 4.1.1(2), 7.2(2), 4.1.3(1), 4.3. |
| C7 | Provide a counter on an accessible route with a speaker that is between 40 and 48 inches above the finished floor. 28 C.F.R. § 35.160(a). Standards § 4.2, Fig. A3. |
| C8 | Provide a counter no higher than 34 inches above the finished floor with clear floor space at least 30 inches by 48 inches. Standards §§ 4.2.4, 9.2.2(7). |
| D1 | Provide a door with hardware, mounted no more than 48 inches above the finished floor, that is easy to grasp with one hand and does not require tight grasping, pinching, or twisting of the wrist to operate; and that requires no more than five pounds of force to operate. Lever-operated mechanisms, push-type mechanisms, and U-shaped handles are acceptable designs. Standards §§ 4.1.3(7), 4.13.9. |
| D2 | Provide a door that requires no more than 5 pounds of force to open. Standards §§ 4.1.3(7), 4.13.11(2)(b). |

| Code | Required Actions |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| D3 | Provide a door that has a minimum space between two hinged or pivoted doors of 48 inches plus the width of any door swinging into the space, with doors swinging in either the same direction or away from the space between the doors. Standards §§ 4.1.3(7), 4.13.7, Fig. 26. |
| D4 | Provide a door that has at least one active leaf with a minimum 32 inch clear opening width, measured between the face of the door and the opposite stop, when the door is open 90 degrees; that has either an automatic door operator or clear and level maneuvering clearance that complies fully with Fig. 25; and that has a threshold not exceeding ½ inch in height and, if it is greater than ¼ inch in height, beveled with a slope no greater than 50%. Ensure that all hardware and operating devices have shapes that are easy to grasp with one hand and do not require tight grasping, pinching, or twisting of the wrist to operate; require no more than five pounds of force to operate; and are mounted no higher than 48 inches above the finished floor. If a control must be operated to activate an automatic door opener, such control shall be located on an accessible route and shall be accompanied by a clear floor space that is 48 inches long by 30 inches wide. Standards §§ 4.1.3(7), 4.2.4.1, 4.13, Figs. 24, 25. |
| D5 | Provide a door that has at least one active leaf with a minimum 32 inch clear opening width with the door open 90 degrees, measured between the face of the door and the opposite stop; that has either an automatic door operator or clear and level maneuvering clearance that complies fully with Fig. 25; and that has a threshold not exceeding ¾ inch in height and, if the threshold is greater than ¼ inch in height, that the edge treatment of the threshold is beveled with a slope no greater than 50%. Ensure that all hardware and operating devices have shapes that are easy to grasp with one hand; do not require tight grasping, pinching, or twisting of the wrist; do not require more than 5 pounds of force to operate; and are mounted no higher than 48 inches above the finished floor. If a control must be operated to activate an automatic door opener, such control shall be located on an accessible route and shall be accompanied by a clear floor space that is 48 inches long by 30 inches wide. Standards §§ 4.1.3(7), 4.2.4.1, 4.13, Figs. 24, 25. |
| D6 | On the pull side of the door, provide maneuvering clearance at least 60 inches deep and provide a minimum of 18 inches (24 inches is preferred) of maneuvering clearance on the latch side of the door. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(a). |

| Code | Required Actions |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| D7 | On the push side of the door, provide maneuvering clearance at least 48 inches deep and provide a minimum of 12 inches of maneuvering clearance on the latch side of the door, or remove the closer or the latch. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(a). |
| D8 | On the pull side of the door, provide a path of travel at least 60 inches wide when the approach is a side approach from the hinge side and there is a minimum of 36 inches to the latch side of the door, OR provide a path of travel between 54 inches and 59 inches wide when the approach is a side approach from the hinge side and there is a minimum of 42 inches to the latch side of the door. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(b). |
| D9 | On the push side of the door, provide a clear maneuvering space at least 54 inches wide, measured from the latch side, and at least 42 inches deep. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(b). |
| D10 | On the pull side of the door, provide a path of travel at least 48 inches wide for a side approach and at least 24 inches of clear maneuvering space adjacent to the latch side of the door. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(c). |
| D11 | On the push side of the door, provide a clear path of travel for a side approach at least 42 inches wide and at least 24 inches of clear maneuvering space adjacent to the latch side of the door. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(c). |
| D12 | Provide accessible entrances to the building equal in number to 50% of the total number of entrances, and provide signage with the International Symbol of Accessibility at all accessible entrances and signage at all inaccessible entrances directing users to the accessible entrance(s). Standards §§ 4.1.3(8), 4.13, 4.30. |
| D13 | Provide a door so that the floor or ground area within the required clearances is level and clear or provide an automatic door opener. Ensure that all operating devices have shapes that are easy to grasp with one hand; do not require tight grasping, pinching, or twisting of the wrist; do not require more than 5 pounds of force to operate; and are mounted no higher than 48 inches above the finished floor on an accessible route and accompanied by a clear floor space that is 48 inches long by 30 inches wide. If a control must be operated to activate an automatic door opener, |

| Code | Required Actions |
|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | such control shall be located on an accessible route and shall be accompanied by a clear floor space that is 48 inches long by 30 inches wide. Standards §§ 4.1.3(7), 4.2.4.1, 4.13, Figs. 24, 25. |
| D14 | Provide a call button within accessible reach ranges at this entrance, ensure that the door will be unlocked promptly when the call button is used, and ensure that voice communication is not required to gain access. Standards §§ 4.1.3(8), 4.14.1. |
| D15 | Provide an accessible gate or door adjacent to the turnstile or revolving door designed so as to facilitate the same use pattern. Standards §§ 4.1.3(7), 4.13.2. |
| D16 | Provide accessible directional signage at inaccessible entrances directing users to the accessible entrance, and provide accessible signage with the International Symbol of Accessibility at all permanent accessible entrances. Standards §§ 4.1.3(8)(d), 4.1.3(16)(b), 4.13, 4.30. |
| D17 | Provide a door with a clear opening at least 32 inches wide when measured from the face of the door to the opposite stop when the door is opened 90 degrees and with hardware usable with one hand and without tight grasping, pinching, or twisting of the wrist. Lever-operated, push-type, and U-shaped handles are acceptable designs. Unless an automatic door operator is provided, there must be clear and level maneuvering clearances at the pull side and the push side of the door as indicated in Fig. 25. The door's threshold must be ½ inch or less in height and, if it is greater than ¼ inch in height, beveled with a slope of no greater than 50%. If a door closer is provided, it must be set so that the sweep period of the door will, from an open position of 70 degrees, take 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. The door must not take more than 5 pounds of force to open or close. Standards §§ 4.1.3(7), 4.13, Fig. 25. |
| D18 | Provide a door with a clear opening at least 32 inches wide when measured from the face of the door to the opposite stop when the door is opened 90 degrees and with hardware usable with one hand and without tight grasping, pinching, or twisting of the wrist. Lever-operated, push-type, and U-shaped handles are acceptable designs. Unless an automatic door operator is provided, there must be clear and level maneuvering clearances at the pull side and the push side of the door as indicated in Fig. 25. The door's threshold must be ¾ inch or less in height and, if it is greater than ¼ |

| Code | Required Actions |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | inch in height, beveled with a slope of no greater than 50%. If a door closer is provided, it must be set so that the sweep period of the door will, from an open position of 70 degrees, take 3 seconds to move to a point 3 inches from the latch, measured to the leading edge of the door. The door must not take more than 5 pounds of force to open or close. Standards §§ 4.1.3(7), 4.13, Fig. 25. |
| D19 | Provide maneuvering clearance at least 48 inches deep at this door. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(d). |
| D20 | Provide a clear path of travel for a side approach at least 42 inches wide and at least 24 inches of clear maneuvering space adjacent to the latch side of the door. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(f). |
| D21 | Provide a clear maneuvering space at least 42 inches deep by 54 inches wide. Standards §§ 4.1.3(7), 4.13.6, Fig. 25(e). |
| D22 | Provide an accessible door with a threshold that is no more than ¼ inch high, or is between ¼ inch and ½ inch high and is beveled with a slope no greater than 50%. Standards §§ 4.1.3(7), 4.13.8, 4.5.2. |
| D23 | Provide an accessible door with a threshold that is no more than ¼ inch high, or is between ¼ inch and ¾ inch high and is beveled with a slope no greater than 50%. Standards §§ 4.1.3(7), 4.13.8, 4.5.2. |
| D24 | Provide a door at this location that has at least one active leaf with a clear opening at least 32 inches wide when measured from the face of the door to the middle edge of the other door when one door is opened 90 degrees OR provide an automatic door opener that opens both doors simultaneously. If a control must be operated to activate an automatic door opener, such control shall be located on an accessible route and shall be accompanied by a clear floor space that is 48 inches long by 30 inches wide. Standards §§ 4.1.3(7), 4.2.4.1, 4.13.4, 4.13.5, Fig. 24. |
| D25 | Provide a door with a clear opening that is 32 inches wide, measured between the face of the door and the opposite stop, when the door open 90 degrees. Standards §§ 4.1.3(7), 4.13.5, Fig. 24. |

| Code | Required Actions |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| D26 | Provide permanent room signage with upper case, sans serif or simple serif type letters and numerals, meeting the requirements of the Standards for character height, raised characters, finish and contrast, accompanied by Grade 2 Braille; mounted on the wall adjacent to the latch side of the door or on the nearest adjacent wall at a height of 60 inches above the finished floor to the centerline of the sign; and located so that a person may approach within 3 inches of the signage without encountering protruding objects or standing within the swing of a door. Standards §§ 4.1.2(7), 4.30.1, 4.30.4, 4.30.5, 4.30.6. |
| DF1 | Ensure that 50% of all drinking fountains on each floor (but at least 1) have a spout mounted at the front of the unit no higher than 36 inches (measured from the finished floor or ground surface to the spout outlet), which directs the water flow in a trajectory that is nearly parallel to the front of the unit, within 3 inches of the front edge of the fountain, and at least 4 inches high. Ensure that fountain controls are operable with one hand; require no more than 5 pounds of force to operate; do not require tight grasping, pinching, or twisting of the wrist; and are front-mounted or side-mounted near the front edge of the unit. Additionally, provide on each floor a drinking fountain that is accessible to people who have difficulty bending or stooping. This can be achieved by the use of a "hi-lo" fountain; by providing one fountain accessible to persons who use wheelchairs and one fountain at a standard height convenient for persons who have difficulty bending; by providing a fountain accessible to persons who use wheelchairs and a cup dispenser; or by such other means as would achieve the required accessibility for each group of people. Standards §§ 4.1.3(10), 4.15, 4.27.4, Fig. 27. |
| DF2 | Provide a drinking fountain with controls mounted on or near the unit's front edge that are operable with one hand, that require 5 pounds of force or less to operate, and that can be operated without tight grasping, pinching, or twisting of the wrist. Standards §§ 4.1.3(10), 4.15.4, 4.27.4. |
| DF3 | Provide a drinking fountain that is accessible to people who have difficulty bending or stooping. This can be accommodated by the use of a "hi-lo" fountain; by providing one fountain accessible to persons who use wheelchairs and one fountain at a standard height convenient for persons who have difficulty bending; by providing a fountain accessible to persons who use wheelchairs and a cup dispenser, or by such other means as would achieve the required accessibility for each group of people. Standards § 4.1.3(10)(a). |

| Code | Required Actions |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| DF4 | Provide a drinking fountain with a clear floor space of at least 30 inches by 48 inches that allows a person in a wheelchair to make a parallel approach to the unit. Standards §§ 4.1.3(10), 4.15.5(2), 4.2.4, Figs. 27(c), (d). |
| DF5 | Provide a drinking fountain with clear knee space between the bottom of the apron and the finished floor or ground of at least 27 inches high, 30 inches wide, and 17 to 19 inches deep; and a minimum clear floor space of 30 inches by 48 inches to allow a person in a wheelchair to approach the unit facing forward. Standards §§ 4.1.3(10), 4.15.5(1), Figs. 27(a), (b). |
| DF6 | Provide a fountain with a spout no higher than 36 inches, measured from the finished floor or ground surface to the spout outlet, that otherwise complies with the Standards. Standards §§ 4.1.3(10), 4.15, 4.27.4, Fig. 27. |
| DF7 | Provide a drinking fountain that directs the water flow in a trajectory that is at least 4 inches high and no more than 3 inches from the front edge of the fountain. Standards §§ 4.1.3(10), 4.15.3. |
| E1 | Provide a fully accessible passenger elevator that serves all public access areas of the facility. Standards §§ 4.1.3(5), 4.10. |
| E2 | Provide an elevator with a cab that is a minimum of 51 inches deep from the back wall of the cab to the control panel and 54 inches deep from the back wall of the cab to the face of the door; that, if the doors are centered on the wall, is at least 80 inches wide and, if the doors are located to one side of the wall, is at least 68 inches wide. Ensure that the door opening is at least 36 inches wide, and that floor surfaces are firm, stable, and slip-resistant. Standards §§ 4.1.3(5), 4.10.9, 4.10.10, Fig. 22. |
| E3 | Provide hall (lobby) call buttons with visual signals indicating when each call is registered and when each call is answered. Ensure that the call buttons are centered at 42 inches above the finished floor, a minimum of $\frac{3}{4}$ inch in the smallest dimension, with the button designating the up direction on top; that the call buttons are raised or flush; and that objects mounted beneath hall call buttons do not project into the elevator lobby more than 4 inches. Standards §§ 4.1.3(5), 4.10.3, Fig. 20. |
| E4 | Provide car control buttons that are at least $\frac{3}{4}$ inch in their smallest dimension and are raised or flush and that are designated by Braille and by |

| Code | Required Actions |
|-------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | <p>raised standard alphabet characters for letters, arabic characters for numerals, or standard symbols. Ensure that the call button for the main entry floor is designated by a raised star at the left of the floor designation; that all raised designations for control buttons are placed immediately to the left of the buttons to which they apply; that floor buttons are provided with visual indicators to show when each call is registered and are extinguished when each call is answered; that all floor buttons are no higher than 54 inches above the finished floor for a side approach and no more than 48 inches above the finished floor for a front approach; and that emergency controls, including the emergency alarm and emergency stop, are grouped at the bottom of the panel and have their centerlines no less than 35 inches above the finished floor. Standards §§ 4.1.3(5), 4.10.12, Fig. 23.</p> |
| E5 | <p>Provide visual car position indicators above the car control panel or over the door which show the position of the elevator in the hoistway. Ensure that indicators emit an audible and visual signal as the car passes or stops at a floor served by the elevator, with the corresponding floor designation being illuminated; and that numerals are a minimum of ½ inch high. Standards §§ 4.1.3(5), 4.10.13.</p> |
| E6 | <p>Provide doors that open and close automatically with a reopening device that will stop and reopen the car door and hoistway door automatically if the door becomes obstructed by an object or person. Ensure that the device is capable of completing these operations without requiring contact for obstructions passing through the opening at heights of 5 inches and 29 inches above the finished floor; that door reopening devices remain effective for at least 20 seconds, after which the doors may close; that the minimum time from notification that a car is answering a call until the doors of that car start to close is 5 seconds; and that the minimum time for elevator doors to remain fully open in response to a car call is 3 seconds. Standards §§ 4.1.3(5), 4.10.6, 4.10.7, 4.10.8, Figs. 20, 21.</p> |
| E7 | <p>Provide an accessible elevator such that all of its elements, including automatic operation, call buttons, hall lanterns, hoistway signage, door opening, cab size, car controls, and emergency communications, comply with the Standards. Standards §§ 4.1.3(5), 4.10, Figs. 20, 22, 23.</p> |
| E8 | <p>Provide a two-way communication system such that it does not require voice communication, the highest operable part is a maximum of 48 inches above the finished floor of the car, and it is identified by a raised symbol and lettering located adjacent to the device. If the system uses a handset, ensure that the length of the cord from the panel to the handset is at least</p> |

| Code | Required Actions |
|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | 29 inches. If the system is located in a closed compartment, ensure that the compartment door hardware operates without tight grasping, pinching or twisting of the wrist. Standards §§ 4.1.3(5), 4.10.14. |
| E9 | Provide emergency controls, including the emergency alarm and emergency stop, grouped at the bottom of the panel with their centerlines no less than 35 inches above the finished floor. Standards §§ 4.1.3(5), 4.10.12, Fig. 23. |
| E10 | Provide a clearance that does not exceed 1¼ inches. This can be achieved by replacing the sill or by otherwise modifying the conditions. Provide a self-leveling feature that automatically brings the car to floor landings within ½ inch. Standards §§ 4.1.3(5), 4.10.2, 4.10.9. |
| E11 | Provide hall lanterns at each hoistway entrance that emit a visible and audible signal indicating which car is answering a call. Ensure that audible signals sound once for the up direction and twice for the down direction or have verbal annunciators that say "up" or "down;" and that visible signals are mounted so that their centerline is at least 72 inches above the lobby floor, they are at least 2½ inches in the smallest dimension, and they are visible from the vicinity of the hall call button. Lanterns located in cars, visible from the vicinity of hall call buttons, and conforming to the above requirements, are acceptable. Standards §§ 4.1.3(5), 4.10.4, Fig. 20. |
| E12 | Provide signage at hoistway entrances with raised and Braille floor designations on both jambs such that the centerline of the characters is 60 inches above the finished floor and the characters are 2 inches high. Standards §§ 4.1.3(5), 4.10.5, Fig. 20. |
| G1 | The next time that golf carts are purchased, provide a reasonable number of accessible golf carts (but no fewer than one) to provide program accessibility to individuals with mobility disabilities. Additionally, establish and implement policies and procedures to ensure that accessible carts are available to persons with disabilities. These will include, for example, allowing persons with disabilities to reserve an accessible cart or use it without reservations; renting out the accessible golf cart to people without disabilities only when all other carts are in use; charging the same for the use of the accessible cart as for the use of others; and maintaining the accessible cart so it is operable and in good condition. Accessible carts may be used by golfers without disabilities when consistent with the policies set out above. 28 C.F.R. § 35.149. |

| Code | Required Actions |
|-------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| L1 | Provide accessible cabinets, shelves, drawers, or towels that are located between 15 and 48 inches above the finished floor for a front approach or between 9 and 54 inches above the finished floor for a side approach; and that have a clear floor space in front that is 30 inches wide by 48 inches deep. Standards §§ 9.2.2(4), 4.25, 4.27.4, 4.2.5, 4.2.6. |
| L2 | Provide an accessible closet with clear floor space in front that is 30 inches wide and 48 inches deep and with hardware that is operable with one hand, does not require tight grasping, pinching, or twisting of the wrist to operate, and requires no more than 5 pounds of force to activate. Ensure that there are shelves located between 15 and 48 inches above the finished floor for a front approach or between 9 and 54 inches above the finished floor for a side approach. Ensure that clothes rods are located no higher than and 48 inches above the finished floor for a front approach or 54 inches above the finished floor for a side approach, or, if the clear floor space allows a parallel approach and the distance between a wheelchair and the clothes rod will exceed 10 inches, ensure that there is a maximum high side reach of 48 inches and a maximum distance from the user to the clothes rod of 21 inches. Standards §§ 9.2.2(4), 4.25, 4.27.4, 4.2.5, 4.2.6, Fig. 38. |
| L3 | Provide this fixture with controls that are mounted between 15 and 48 inches above the finished floor for a front approach or between 9 and 54 inches above the finished floor for a side approach. Ensure that the controls are operable with one hand; do not require tight grasping, pinching, or twisting of the wrist to operate; and require no more than 5 pounds of force to activate. Standards §§ 9.2.2(5), 4.1.3(13), 4.27.3, 4.27.4, 4.2.5, 4.2.6. |
| L4 | Provide accessible sleeping rooms in each class of sleeping room available to the general public based on amenities such as room size, view, number of beds, etc., and restrictions such as non smoking. Standards § 9.1.4. |
| L5 | Provide a shower in this room that is exactly 36 inches wide and 36 inches deep with a 48 inch long and 36 inch wide clear floor space alongside the shower opening, and an L-shaped shower seat mounted on the wall opposite the controls and extending the full depth of the stall; OR a shower that is at least 30 inches deep and 60 inches wide with no curb or threshold and with a 36 inch deep and 60 inch wide clear floor space at the shower opening; OR a shower that is exactly 36 inches deep and at least 60 inches wide with no curb or threshold, with a minimum clear opening of 36 inches located on the long wall opposite the controls, and with a seat at least 24 inches wide and 16 inches deep. Ensure that the shower has grab bars, |

| Code | Required Actions | | |
|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------|--------------------------------------------------------------------|
| | controls, a shower spray unit, a seat, and a curb and enclosure, if provided, that comply fully with the Standards and with Figs. 35, 36, 37, and 57, as applicable. Standards §§ 9.1.2, 4.21, Figs. 35, 36, 37, 57. | | |
| L6 | Provide accessible sleeping rooms as required in the following chart, ensuring that they are provided in each class of sleeping room available to the general public based on amenities such as room size, view, number of beds, etc., and restrictions such as non smoking. Standards § 9.1.2. | | |
| | Number of Rooms | Wheelchair Accessible Rooms | Additional Wheelchair Accessible Rooms with Roll-In Showers |
| | 1 to 25 | 1 | |
| | 26 to 50 | 2 | |
| | 51 to 75 | 3 | 1 |
| | 76 to 100 | 4 | 1 |
| | 101 to 150 | 5 | 2 |
| | 151 to 200 | 6 | 2 |
| | 201 to 300 | 7 | 3 |
| | 301 to 400 | 8 | 4 |
| | 401 to 500 | 9 | 4 plus 1 for each additional 100 over 400 |
| | 501 to 1000 | 2% of total | |
| | over 1000 | 20 plus 1 for each | |

| Code | Required Actions | | |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|--|
| | | 100 over 1000 | |
| L7 | Provide sleeping rooms, as required in the following chart, with auxiliary aid devices including visual alarms, notification devices, and telephones available for persons with hearing impairments. The number of rooms required to be hearing accessible includes the rooms that are required to be wheelchair accessible. Standards §§ 9.1.3, 9.1.4, 9.3. | | |
| | Number of Rooms | Hearing Accessible Rooms | |
| | 1 to 25 | 2 | |
| | 26 to 50 | 4 | |
| | 51 to 75 | 7 | |
| | 76 to 100 | 9 | |
| | 101 to 150 | 12 | |
| | 151 to 200 | 14 | |
| | 201 to 300 | 17 | |
| | 301 to 400 | 20 | |
| | 401 to 500 | 22 plus 1 for each additional 100 over 400 | |
| | 501 to 1000 | 4% of total plus 1 for each 100 over 400 | |
| | over 1000 | 40 plus 2 for each 100 over 1000 | |

| Code | Required Actions |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| L8 | Provide a minimum clear maneuvering width of 36 inches along both sides of the bed. Standards § 9.2.2(1). |
| L9 | Provide a minimum clear maneuvering width of 36 inches between the two beds. Standards § 9.2.2(1). |
| L10 | Provide a designated accessible route to all spaces within accessible sleeping rooms. Standards § 9.2.2(2). |
| L11 | Provide an electrical outlet within 4 feet of the telephone to facilitate the use of a text telephone and provide a hearing aid compatible telephone fitted with a volume control device. Standards § 9.3.1. |
| L12 | For this room, provide a visual alarm connected to the building emergency alarm system. In the alternative, provide a standard 110-volt electrical receptacle into which such an alarm can be connected, a means by which a signal from the building emergency alarm system can trigger such an auxiliary alarm, a portable auxiliary alarm, and instructions for the use of the auxiliary alarm or receptacle. When visual alarms are in place, the signal shall be visible in all areas of the unit or room, including when interior doors are closed (generally, this requires a visual alarm in the sleeping quarters and a visual alarm in the bathroom). Standards §§ 4.1.3(14), 4.28.4. |
| LB1 | As applicable, provide a card catalog and magazine displays with a minimum of 36 inches of clear width between units and with reach ranges of between 18 inches and 54 inches (maximum height of 48 inches is preferred) above the finished floor. Standards § 8.4, Fig. 55. |
| LB2 | Provide at least one accessible lane at each check out area such that the counter is on an accessible route at least 36 inches wide and it has a section at least 36 inches wide and no more than 36 inches above the finished floor. Standards §§ 8.3, 7.2(1). |
| LB3 | In each seating area, provide accessible seats, tables, or carrels equal in number to 5% of the total number available (or at least one, whichever is greater) . Standards §§ 8.2, 4.2, 4.3, 4.32. |

| Code | Required Actions |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| LB4 | Provide accessible seats, tables, or carrels on an accessible route at least 36 inches wide. Ensure that the seats, tables, or carrels have clear floor space of 30 inches wide by 48 inches deep, knee clearance of at least 27 inches high by 30 inches wide by 19 inches deep, and a writing surface between 28 and 34 inches above the finished floor. Standards §§ 8.2, 4.2.4.1, 4.32. |
| LB5 | Provide at least 36 inches of clear width between all stacks and provide a clear width of 42 inches between stacks where possible. Standards § 8.5, Fig. 56. |
| LF1 | Provide a lift at this location that facilitates unassisted entry, operation, and exit from the lift. Standards §§ 4.1.3(5), 4.11.3. |
| LF2 | Provide a lift that is on an accessible route; has interior dimensions of at least 30 inches by 48 inches; facilitates unassisted entry, operation, and exit; has a floor surface that is firm, stable, and slip-resistant, or, if carpeted, has a carpet with a pile that is no more than ½ inch deep; has a change of level at the entrance that is no more than ½ inch and beveled. Ensure that the lift has operating controls that are located between 15 and 48 inches above the floor for a front approach or between 9 and 54 inches above the floor for a side approach; that are usable with one hand, do not require tight grasping, pinching, or twisting of the wrist to operate, and require no more than 5 pounds of force to operate. Standards §§ 4.1.3(5), 4.11. |
| LR1 | Provide a 24 inch by 48 inch bench fixed to the wall along the bench's longer dimension. Ensure that the bench has sufficient structural strength and is mounted with its surface between 17 inches and 19 inches above the finished floor. Provide clear floor space alongside the bench to allow a person using a wheelchair to make a parallel transfer onto the bench. Standards §§ 4.1.3(21), 4.35.4, 4.26.3. |
| LR2 | Provide at least one accessible dressing or fitting room in this area on an accessible route with accessible signage indicating its location. Ensure that accessible dressing or fitting rooms fitted with swinging or sliding doors contain sufficient clear floor space to allow a person using a wheelchair to make a 180-degree turn inside the room and that no door swings into any part of the turning space. Ensure that private accessible dressing or fitting rooms fitted with curtained openings at least 32 inches wide contain either a clear space of 60 inches in diameter, or a "T" shaped turning space that complies with Fig. 3(b). Provide a bench 24 inches by 48 inches fixed to |

| Code | Required Actions |
|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | the wall along the longer dimension and mounted between 17 and 19 inches above the finished floor to the top of the bench. If mirrors are provided in dressing rooms of the same use, provide one full-length mirror, measuring at least 18 inches wide by 54 inches high, mounted in a position affording a view to a person on the bench as well as to a person in a standing position. Standards §§ 4.1.3(21), 4.35, 4.30, 4.26.3, 4.2, 4.3, Fig. 3. |
| LR3 | Provide at least one accessible locker with accessible controls, reach ranges, storage space, and clear floor space. Standards §§ 4.1.3(12)(a), 4.2.5, 4.2.6, 4.25, 4.27. |
| LR4 | Provide accessible locker rooms such that all of the rooms' elements, including signage, door, door hardware, clear floor space, water closet, stall size and arrangement, stall door, urinal (if provided), grab bars, lavatory, mirror, shower, bench, locker, and controls, and dispensers, comply with the Standards. Standards §§ 4.13, 4.16, 4.17, 4.18, 4.19, 4.21, 4.23, 4.25, 4.26, 4.27, 4.30, 4.35, Fig. 30. |
| M1 | Maintain this feature in operable working condition. 28 C.F.R. § 35.133. |
| M2 | Maintain this feature in such a way that people with disabilities are given an equal opportunity to participate in or benefit from the aid, benefit, or service provided. 28 C.F.R. § 35.130. |
| P1 | At each standard accessible parking space, provide an access aisle that is at least 60 inches wide. At each van accessible parking space, provide an access aisle that is at least 96 inches wide. Ensure that all access aisles are flat and level, with slopes and cross-slopes not exceeding 2% in all directions, and that access aisle surfaces are firm, stable, and slip-resistant. Standards §§ 4.1.2(5), 4.6.3, Fig. 9. |
| P2 | Provide dispersed accessible parking such that some accessible parking spaces serve each of the accessible facility entrances. Standards §§ 4.1.2(5)(a), 4.1.2(5)(b), 4.6.2. |
| P3 | On the shortest accessible route to the accessible entrance, provide accessible parking designated as reserved for people with disabilities, including van accessible spaces and standard spaces, as required in the |

| Code | Required Actions | | |
|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|------------------------------|
| | <p>following chart. Ensure that standard accessible spaces are a minimum of 96 inches wide and served by access aisles at least 60 inches wide. Ensure that van accessible spaces are a minimum of 96 inches wide and served by access aisles at least 96 inches wide. At all spaces designated as reserved for persons with disabilities, provide vertical signs with the International Symbol of Accessibility located such that they cannot be obstructed by parked vehicles. At van accessible spaces, provide an additional "Van-Accessible" sign located below the International Symbol of Accessibility. Ensure that all spaces and access aisles for persons with disabilities are flat and level, with slopes and cross-slopes not exceeding 2% in all directions, and that their surfaces are firm, stable, and slip-resistant. If the parking facility does not serve a particular building or facility, provide accessible parking on the shortest accessible route to an accessible pedestrian entrance of the parking facility. If the parking facility serves a building with multiple accessible entrances or multiple buildings or facilities, provide dispersed parking spaces located on an accessible route closest to the accessible entrances. If the parking facility is a parking garage or otherwise has limitations on vertical clearances, provide minimum vertical clearance of 98 inches at the van accessible parking spaces and along at least one vehicle access route to such spaces from site entrances and exits. Standards §§ 4.1.2(5), 4.6, 4.30.7(1).</p> | | |
| | Total Spaces in Lot | Total Accessible Spaces (Including Van Accessible) | Van Accessible Spaces |
| | 1 to 25 | 1 | 1 |
| | 26 to 50 | 2 | 1 |
| | 51 to 75 | 3 | 1 |
| | 76 to 100 | 4 | 1 |
| | 101 to 150 | 5 | 1 |
| | 151 to 200 | 6 | 1 |

| Code | Required Actions | | |
|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|--------------------------------|
| | 201 to 300 | 7 | 1 |
| | 301 to 400 | 8 | 1 |
| | 401 to 500 | 9 | 2 |
| | 501 to 1000 | 2% of total | 1 in every 8 accessible spaces |
| | over 1000 | 20 plus 1 for each 100 over 1000 | 1 in every 8 accessible spaces |
| P4 | Provide a passenger loading zone on an accessible route such that the loading zone has a vertical clearance of at least 114 inches, has an access aisle at least 60 inches wide and 20 feet long adjacent and parallel to the vehicle pull-up space, and has a surface that is firm, stable, slip-resistant, and level with no more than a 2% slope in all directions. Standards §§ 4.1.2(5)(c), 4.6.6. | | |
| P5 | Provide fully accessible parking that is located on the shortest accessible route to an accessible pedestrian entrance to the facility. Standards §§ 4.1.2(5)(a), 4.1.2(5)(b), 4.6.2. | | |
| P6 | At all spaces designated as reserved for persons with disabilities, provide vertical signs with the International Symbol of Accessibility located such that they cannot be obstructed by vehicles parked in the spaces. At van accessible spaces, provide an additional "Van-Accessible" sign located below the International Symbol of Accessibility. Standards §§ 4.1.2(5), 4.6.4, 4.30.7(1). | | |
| P7 | Provide designated accessible parking spaces and access aisles that are flat and level, with slopes and cross-slopes not exceeding 2% in all directions, with surfaces that are firm, stable, and slip-resistant. Standards §§ 4.1.2(5), 4.3.6, 4.5.1, 4.6.3. | | |
| P8 | Provide designated accessible parking spaces that are a minimum of 96 inches wide and served by access aisles at least 60 inches wide. Provide van accessible spaces that are a minimum of 96 inches wide and served by | | |

| Code | Required Actions |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | access aisles at least 96 inches wide. Standards §§ 4.1.2(5), 4.6.3, Fig.9. |
| P9 | Provide a minimum vertical clearance of 98 inches at designated van accessible parking spaces and along at least one vehicle access route to such spaces from site entrances and exits. Standards §§ 4.1.2(5)(b), 4.6.5. |
| PD1 | Provide access to all dining areas, including raised or sunken dining areas, loggias, and outdoor seating areas. Standards § 5.4. |
| PD2 | Provide a portion of the main counter on an accessible route such that the counter is 60 inches minimum in length and between 28 and 34 inches in height, or provide service at accessible tables within the same area of the facility. Standards § 5.2. |
| PD3 | Provide sufficient accessible tables so that 5% of them (but no fewer than one) are available for use by people with mobility disabilities. Each accessible table must be on an accessible route, must have knee space at the table at least 27 inches high, 30 inches wide, and 19 inches deep, and must have a table top between 28 inches and 34 inches above the floor. Ensure that the tables are distributed throughout the facility. Standards §§ 4.1.3(18), 4.32.3, 4.32.4, 5.1. |
| PD4 | Provide accessible tables distributed among all sections of the facility. Standards § 5.1. |
| PD5 | Provide accessible food service lines with a minimum clear width of 36 inches (42 inches is preferred to allow passage around a person using a wheelchair) and with tray slides mounted no higher than 34 inches above the finished floor. Standards §§ 5.5, 4.2.5, 4.2.6, Fig. 53. |
| PD6 | Provide sufficient accessible picnic tables so that 5% of them (but no fewer than one) are available for use by people with mobility disabilities. Each accessible picnic table must be on an accessible route, must have knee space at the table at least 27 inches high, 30 inches wide, and 19 inches deep, and must have a table top between 28 inches and 34 inches above the ground. Standards §§ 4.1.3(18), 4.32.3, 4.32.4. |
| PD7 | Provide access aisles that are at least 36 inches wide between parallel edges of tables or between walls and table edges. Standards § 5.3. |

| Code | Required Actions |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| PD8 | Provide tableware and condiment dispensers located between 15 and 48 inches above the finished floor for a front approach or between 9 and 54 inches above the finished floor for a side approach. Standards §§ 5.6, 4.2.5, 4.2.6, Fig. 54. |
| PG1 | Ensure program access by providing at least one piece of play equipment that is on an accessible route and has a transfer platform to enable children who use wheelchairs to use it. 28 C.F.R. § 35.149. |
| PJ1 | Provide at least one accessible cell such that all of the cell's elements, including door, clear floor space, water closet, grab bars, lavatory, mirror, bed, controls, and dispensers, comply with the Standards. Standards §§ 4.1.3(7), 4.1.3(11), 4.13, 4.16, 4.19, 4.26, 4.27, 9.2.2, Figs. 28, 29. |
| PJ2 | Provide an accessible cafeteria such that all of its elements, including accessible route, doors, counters, food service lines, tableware and condiments areas, and at least 5 percent of the seating and tables (but not less than 1), comply with the Standards. Standards §§ 4.1.3(1), 4.1.3(7), 4.1.3(18), 4.3, 4.13, 4.27, 4.32, 5.2, 5.5, 5.6. |
| PJ3 | Provide one or more accessible classrooms such that all of its or their elements, including accessible route, doors, and at least 5 percent of the seating and tables (but not less than 1), comply with the Standards. Ensure that classes are scheduled in a manner that ensures persons with disabilities can attend any available classes in an accessible classroom. Standards §§ 4.1.3(1), 4.1.3(7), 4.1.3(18), 4.3, 4.13, 4.32. |
| PJ4 | In each security and classification level provided in the facility, provide rooms or cells equal in number to 5 percent of the total number of rooms or cells in that security and classification level (but not less than one) such that all room or cell elements, including door, clear floor space, mirror, bed, controls, and dispensers, comply with the Standards, and such that a fully accessible shower room and a toilet room or toilet unit is provided on an accessible route convenient to that room or cell. Standards §§ 4.1.3(1), 4.1.3(7), 4.1.3(11), 4.3, 4.13, 4.16, 4.19, 4.21, 4.23, 4.26, 4.27, 9.1.4, 9.2.2. |
| PJ5 | Provide a room within the medical unit such that all elements, including door, clear floor space, bed, controls, and dispensers, comply with the Standards, and such that a fully accessible shower room and toilet room is provided on an accessible route convenient to that room. Standards §§ |

| Code | Required Actions |
|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | 4.1.3(1), 4.1.3(7), 4.1.3(11), 4.3, 4.13, 4.16, 4.19, 4.21, 4.23, 4.26, 4.27, 9.2.2. |
| PJ6 | Provide at least one accessible TTY for use by detainees and inmates. If the TTY is a portable unit, adopt policies and procedures to ensure that access afforded to the TTY for detainees and inmates with disabilities is equal to the access afforded to inmates who use the standard telephone. In addition, where detainee and inmate telephone calls are time-limited, adopt policies permitting detainees and inmates with disabilities who use TTY's a longer period of time to make those calls, due to the slower nature of TTY communications compared with voice communications. 28 C.F.R. § 35.160(a); Standards §§ 4.1.3(17)(c), 4.30.7(3), 4.31.9. |
| PJ7 | Provide a visitation or other such area such that all of the area's elements, including seating, counter, accessible route to and within the area, entrance, signage, telephone, etc., comply with the Standards. Standards §§ 4.1.3, 4.2, 4.3, 4.4, 4.5, 4.13, 4.14, 4.30, 4.31, 4.32. |
| R1 | Provide edge protection at least 2 inches high at the drop off sides. Standards §§ 4.1.2(1), 4.1.2(2), 4.3.8, 4.8.7. |
| R2 | Provide handrails that are between 1¼ inches and 1½ inches in diameter such that the inside handrail is continuous and both handrails have a continuous gripping surface along both sides of the ramp extending at least 12 inches beyond the top and bottom of the ramp parallel with the ground surface; the handrails do not rotate within their fittings; and both handrails are mounted between 34 inches and 38 inches above the ramp surface and 1½ inches from the wall, with ends rounded or returned smoothly to the floor, wall, or post. Standards §§ 4.1.2(1), 4.1.2(2), 4.3.8, 4.8.5. |
| R3 | Provide a ramp that is at least 36 inches wide with a slope not exceeding 8.33% and a cross slope not exceeding 2%; with level landings at least as wide as the ramp and 60 inches long at the top and bottom of the ramp; with level landings measuring at least 60 inches by 60 inches when the ramp changes direction; and with edge protection that is at least 2 inches high at the drop off sides. Provide handrails that are between 1¼ inches and 1½ inches in diameter such that the inside handrail is continuous and both handrails have a continuous gripping surface along both sides of the ramp extending at least 12 inches beyond the top and bottom of the ramp parallel with the ground surface; the handrails do not rotate within their fittings; and both handrails are mounted between 34 inches and 38 inches |

| Code | Required Actions |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | above the ramp surface and 1½ inches from the wall, with ends rounded or returned smoothly to the floor, wall, or post. Ensure that the ramp and approaches are designed so that water will not accumulate on walking surfaces. Standards §§ 4.1.2(1), 4.1.2(2), 4.3.8, 4.8. |
| R4 | Provide handrails that are between 1¼ inches and 1½ inches in diameter with a continuous gripping surface along both sides of the ramp, extending at least 12 inches beyond the top and bottom of the ramp parallel with the ground surface. Ensure that handrails are mounted between 34 inches and 38 inches above the ramp surface and 1½ inches from the wall, with ends rounded or returned smoothly to the floor, wall, or post, and that they do not rotate within their fittings. Standards §§ 4.1.2(1), 4.1.2(2), 4.8.5. |
| R5 | Provide a ramp that is at least 36 inches wide with a slope not exceeding 8.33% and a cross slope not exceeding 2%; with level landings at least as wide as the ramp and 60 inches long at the top and bottom of the ramp; and with edge protection at least 2 inches high at the drop off sides. Provide handrails that are between 1¼ inches and 1½ inches in diameter with a continuous gripping surface along both sides of the ramp, extending at least 12 inches beyond the top and bottom of the ramp parallel with the ground surface. Ensure that handrails are mounted between 34 inches and 38 inches above the ramp surface and 1½ inches from the wall, with ends rounded or returned smoothly to the floor, wall, or post, and that they do not rotate within their fittings. Ensure that the ramp and approaches are designed so that water will not accumulate on walking surfaces. Standards §§ 4.1.2(1), 4.1.2(2), 4.3.8, 4.8. |
| S1 | Provide a shelf and hook that comply with Fig. 5 for a forward reach or with Fig. 6 for a side reach and that are accompanied by clear floor space of 30 inches by 48 inches that allows a forward or parallel approach, respectively, by a person using a wheelchair. Standards §§ 4.1.3(12), 4.25.2, 4.25.3, 4.2.5, 4.2.6. |
| S2 | Provide a sink mounted with the counter or rim no higher 34 inches; with knee clearance at least 27 inches high, 30 inches wide, and 19 inches deep; with clear floor space at least 30 inches by 48 inches; with hot water and drain pipes insulated or otherwise configured to protect against contact; and with faucets that require no more than 5 pounds of force to operate and that are operable with one hand and do not require tight grasping, pinching, or twisting of the wrist to operate. Standards § 4.24. |

| Code | Required Actions |
|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ST1 | Provide at least one stall that is exactly 36 inches wide with a toilet centerline 18 inches from each wall or partition, an outward swinging, self-closing door, parallel grab bars complying with Fig. 30(d), and a toilet complying with Standards § 4.16. Standards §§ 4.1.3(11), 4.16, 4.22.4, Fig. 30(d). |
| ST2 | Provide a flush control mounted on the "open" side of the toilet's clear floor space; 44 inches or less above the finished floor; and requiring a maximum of 5 pounds of force to operate; or provide an automatic flush device. Standards §§ 4.1.3(11), 4.22.4, 4.16.5, 4.17.2, 4.27.4. |
| ST3 | Provide a rear grab bar that is at least 36 inches in overall length, with the closer end no more than 6 inches from the side wall; mounted 33 to 36 inches above the finished floor; with a diameter between 1¼ and 1½ inches; with 1½ inches between the grab bar and the wall; and at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.2, Figs. 30, 39. |
| ST4 | Provide a rear grab bar that is at least 36 inches in overall length with the closer end no more than 6 inches from the side wall. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, Fig. 30. |
| ST5 | Provide a rear grab bar that has at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.2, Fig. 39. |
| ST6 | Provide a side grab bar that is at least 40 inches in overall length, with the far end mounted at least 52 inches from the rear wall and the closer end 12 inches or less from the rear wall; mounted 33 to 36 inches above the finished floor; with a diameter between 1¼ and 1½ inches; with 1½ inches between the grab bar and the wall; and at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Provide a toilet paper dispenser that is mounted no more than 36 inches from the rear wall, with its top at least 1½ inches under the side grab bar, and centered at least 19 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.2, Figs. 30(a), (d), 39. |

| Code | Required Actions |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ST7 | Provide a side grab bar that is at least 40 inches in overall length, with the far end mounted at least 52 inches from the rear wall, with the closer end 12 inches or less from the rear wall, and with at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, Figs. 30(a), (d). |
| ST8 | Provide a side grab bar that has at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Provide a toilet paper dispenser that is mounted no more than 36 inches from the rear wall, with its top at least 1½ inches under the side grab bar, and centered at least 19 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.2, Fig. 39. |
| ST9 | Provide a side grab bar that has at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.2, Fig. 39. |
| ST10 | Provide grab bars that have a diameter between 1¼ and 1½ inches. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.2. |
| ST11 | Provide a rear grab bar that is at least 36 inches in overall length, with the closer end no more than 6 inches from the side wall, and a side grab bar that is at least 40 inches in overall length, with the far end mounted at least 54 inches from the rear wall and the closer end 12 inches or less from the rear wall. Ensure that the grab bars are mounted 33 to 36 inches above the finished floor; with a diameter between 1¼ and 1½ inches; with 1½ inches between the grab bar and the wall; and at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.2, Figs. 30, 39. |
| ST12 | Provide grab bars that are mounted between 33 and 36 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, Fig. 30. |
| ST13 | Provide grab bars such that there is 1½ inches between the grab bar and the wall on which it is mounted. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.2, Fig. 39. |

| Code | Required Actions |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ST14 | Provide an accessible toilet room such that all of the room's elements, including signage, door, door hardware, clear floor space, water closet, stall size and arrangement, stall door, urinal (if provided), grab bars, lavatory, mirror, controls, and dispensers, comply with the Standards. Standards §§ 4.1.3(11), 4.13, 4.16, 4.17, 4.18, 4.19, 4.26, 4.27, 4.30, Fig. 30. |
| ST15 | Provide a "standard" accessible toilet stall at least 60 inches wide and at least 59 inches deep (or at least 56 inches deep with a wall-mounted toilet) such that all of the stall's elements, including stall door, stall door hardware, water closet, size and arrangement, toe clearances, grab bars, controls, and dispensers, comply with the Standards. Standards §§ 4.1.3(11), 4.22.4, 4.22.7, 4.13, 4.16, 4.17, 4.26, 4.27, Fig. 30. |
| ST16 | Provide a toilet stall that is at least 60 inches wide and at least 56 inches deep for a wall-mounted toilet or at least 59 inches deep for a floor-mounted toilet, such that the centerline of the toilet is exactly 18 inches from the near side wall or partition, and there is at least 9 inches of toe clearance above the floor at the front partition if the stall is no more than 60 inches deep. Standards §§ 4.1.3(11), 4.22.4, 4.17, Fig. 30. |
| ST17 | Provide a toilet with its centerline 18 inches from the near side wall. Standards §§ 4.1.3(11), 4.22.4, 4.17.3, Fig. 30. |
| ST18 | Provide clear floor space at the toilet that complies with Fig. 30. Standards §§ 4.1.3(11), 4.22.4, 4.17.3, Fig. 30. |
| ST19 | Provide a toilet paper dispenser that is mounted with its top at least 1½ inches under the side grab bar and 36 inches or less from the rear wall and is centered at least 19 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.17.3, Fig. 30(d). |
| ST20 | Provide a toilet such that the top of the seat is 17 to 19 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.16.3, 4.17.2, Fig. 30(d). |
| ST21 | Provide grab bars with the specified structural strength to safely support a person with a disability who is using them. Standards §§ 4.1.3(11), 4.22.4, 4.17.6, 4.26.3. |

| Code | Required Actions |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| SU1 | Provide a flush control mounted on the "open" side of the toilet's clear floor space; 44 inches or less above the finished floor; and requiring a maximum of 5 pounds of force to operate; or provide an automatic flush device. Standards §§ 4.1.3(11), 4.22.4, 4.16.5, 4.27.4. |
| SU2 | Provide a rear grab bar that is at least 36 inches in overall length, with the closer end no more than 6 inches from the side wall; mounted 33 to 36 inches above the finished floor; with a diameter between 1¼ and 1½ inches; with 1½ inches between the grab bar and the wall; and at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any other object above it. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.26.2, Figs. 29, 39. |
| SU3 | Provide a rear grab bar that is at least 36 inches in overall length with the closer end no more than 6 inches from the side wall. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, Fig. 29. |
| SU4 | Provide a rear grab bar that has at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.26.2, Fig. 39. |
| SU5 | Provide a side grab bar that is at least 42 inches in overall length, with the far end mounted at least 54 inches from the rear wall and the closer end 12 inches or less from the rear wall; mounted 33 to 36 inches above the finished floor; with a diameter between 1¼ and 1½ inches; with 1½ inches between the grab bar and the wall; and at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Provide a toilet paper dispenser that is mounted within reach, with its top at least 1½ inches under the side grab bar, and centered at least 19 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.16.6, 4.26.2, Figs. 29, 39. |
| SU6 | Provide a side grab bar that is at least 42 inches in overall length, with the far end mounted at least 54 inches from the rear wall, with the closer end mounted 12 inches or less from the rear wall, and with at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, Fig. 29(b). |

| Code | Required Actions |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| SU7 | Provide a side grab bar that has at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Provide a toilet paper dispenser that is mounted within reach, with its top at least 1½ inches under the side grab bar, and centered at least 19 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.16.6, 4.26.2, Fig. 39. |
| SU8 | Provide a side grab bar that has at least 1½ inches between the grab bar and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.26.2, Fig. 39. |
| SU9 | Provide grab bars that have a diameter between 1¼ and 1½ inches. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.26.2. |
| SU10 | Provide a rear grab bar that is at least 36 inches in overall length, with the closer end no more than 6 inches from the side wall, and a side grab bar that is at least 42 inches in overall length, with the far end mounted at least 54 inches from the rear wall and the closer end 12 inches or less from the rear wall. Ensure that the grab bars are mounted 33 to 36 inches above the finished floor; with a diameter between 1¼ and 1½ inches; with 1½ inches between the grab bars and the wall; and at least 1½ inches between the grab bars and any object beside or below it and at least 18 inches between the grab bar and any object above it. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.26.2, Figs. 29, 39. |
| SU11 | Provide grab bars that are mounted between 33 and 36 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, Fig. 29. |
| SU12 | Provide grab bars such that there is 1½ inches between the grab bar and the wall on which it is mounted. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.26.2, Fig. 39. |
| SU13 | Provide an accessible toilet room such that all of the room's elements, including signage, door, door hardware, clear floor space, water closet, urinal (if provided), grab bars, lavatory, mirror, controls, and dispensers, comply with the Standards. Standards §§ 4.1.3(11), 4.22, 4.13, 4.16, 4.18, 4.19, 4.26, 4.27, 4.30, Figs. 28, 29. |

| Code | Required Actions |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| SU14 | Provide a toilet with a centerline that is 18 inches from the near side wall; a seat with the top between 17 and 19 inches above the finished floor; clear floor space at the toilet that complies with Fig. 28; and a flush control mounted on the "open" side of the toilet's clear floor space. Standards §§ 4.1.3(11), 4.22.4, 4.16.2, 4.16.3, 4.16.5, Figs. 28, 29. |
| SU15 | Provide a toilet with its centerline 18 inches from the near side wall. Standards §§ 4.1.3(11), 4.22.4, 4.16.2, Fig. 28. |
| SU16 | Provide clear floor space at the toilet that complies with Fig. 28. Standards §§ 4.1.3(11), 4.22.4, 4.16.2, Fig. 28. |
| SU17 | Provide a toilet paper dispenser that is mounted within reach, with its top at least 1½ inches under the side grab bar, and centered at least 19 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.16.6, Fig. 29(b). |
| SU18 | Provide a toilet such that the top of the seat is 17 to 19 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.4, 4.16.3, Fig. 29(b). |
| SU19 | Provide grab bars with the specified structural strength to safely support a person with a disability who is using them. Standards §§ 4.1.3(11), 4.22.4, 4.16.4, 4.26.3. |
| T1 | Provide an accessible table on an accessible route at least 36 inches wide. Ensure that the table has clear floor space of 30 inches wide by 48 inches deep, knee clearance of at least 27 inches high by 30 inches wide by 19 inches deep, and a writing surface between 28 and 34 inches above the finished floor. Standards §§ 4.1.3(18), 4.2.4.1, 4.32. |
| TR1 | Provide a coat or towel hook at a maximum height above the finished floor of 48 inches for a forward approach or 54 inches for a side approach and that is accompanied by clear floor space of 30 by 48 inches that allows a forward or parallel approach by a person using a wheelchair. Standards §§ 4.1.3(12)(a), 4.25.2, 4.25.3, 4.2.4, 4.2.5, 4.2.6. |
| TR2 | Provide this element with mechanical controls, if any, that can be operated with no more than 5 pounds of force and that can be used with one hand and without tight grasping, pinching, or twisting of the wrist (lever-operated, push-type, and electronically controlled mechanisms are examples of |

| Code | Required Actions |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | acceptable designs). Ensure that the controls are a maximum height above the finished floor of 48 inches for a forward approach or 54 inches for a side approach and that it is accompanied by clear floor space of 30 by 48 inches that allows a forward or parallel approach by a person using a wheelchair. Standards §§ 4.1.3(13), 4.27.2, 4.27.3, 4.27.4, 4.2.4, 4.2.5, 4.2.6. |
| TR3 | Provide this element with mechanical controls, if any, that can be operated with no more than 5 pounds of force and that can be used with one hand and without tight grasping, pinching, or twisting of the wrist (lever-operated, push-type, and electronically controlled mechanisms are examples of acceptable designs). Standards §§ 4.1.3(13), 4.27.4. |
| TR4 | Provide this element such that the controls comply with Fig. 5 for a forward reach or with Fig. 6 for a side reach and such that it is accompanied by clear floor space of 30 inches by 48 inches that allows a forward or parallel approach, respectively, by a person using a wheelchair. Standards §§ 4.1.3(13), 4.27.2, 4.27.3, 4.2.4, 4.2.5, 4.2.6. |
| TR5 | Provide this element with the controls located no more than 48 inches above the finished floor for a forward approach or no more than 54 inches above the finished floor for a side approach and that is accompanied by clear floor space of 30 by 48 inches that allows a forward or parallel approach by a person using a wheelchair. Standards §§ 4.1.3(13), 4.27.2, 4.27.3, 4.2.4, 4.2.5, 4.2.6. |
| TR6 | Ensure that no door swings into the required clear floor space at any accessible fixture (e.g., toilet, urinal, lavatory, dispensers). Standards §§ 4.1.3(11), 4.22.2. |
| TR7 | For each one that is required to be accessible, provide an accessible cell such that all of the cell's elements, including door width, clear floor space, water closet, urinal (if provided), grab bars, lavatory, mirror (if provided), controls, and dispensers, comply with the Standards. Where only one cell serves a particular purpose, such as a cell serving a particular courtroom, it shall be accessible. Where multiple cells are grouped together and serve the same purpose, at least one cell shall be accessible. Standards §§ 4.1.3(11), 4.13, 4.16, 4.18, 4.19, 4.22, 4.26, 4.27, 4.30, Figs. 28, 29. |
| TR8 | Provide a lavatory with clear floor space at least 30 inches wide and 48 inches deep centered on the lavatory. Standards §§ 4.1.3(11), 4.22.6, |

| Code | Required Actions |
|-------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | 4.19.3, Fig. 32. |
| TR9 | Provide a lavatory with the top of its rim or counter 34 inches or less above the finished floor; the bottom edge of the apron at least 29 inches above the finished floor; knee and toe clearances that comply with Fig. 31; hot water and drain pipes covered or otherwise configured to protect against contact; clear floor space at least 30 inches wide by 48 inches deep centered on the lavatory; and a faucet that can be operated with no more than 5 pounds of force and can be used with one hand and without tight grasping, pinching, or twisting of the wrist (lever-operated, push-type, and electronically controlled mechanisms are examples of acceptable designs). Standards §§ 4.1.3(11), 4.22.6, 4.19.2, 4.19.3, 4.19.4, 4.19.5, 4.27.4, Figs. 31, 32. |
| TR10 | Provide a lavatory with a faucet that can be operated with no more than 5 pounds of force and can be used with one hand and without tight grasping, pinching, or twisting of the wrist (lever-operated, push-type, and electronically controlled mechanisms are examples of acceptable designs). Standards §§ 4.1.3(11), 4.22.6, 4.19.5, 4.27.4. |
| TR11 | Provide a lavatory with the top of its rim or counter 34 inches or less above the finished floor; the bottom edge of the apron at least 29 inches above the finished floor; and knee and toe clearances that comply with Fig. 31. Standards §§ 4.1.3(11), 4.22.6, 4.19.2, Fig. 31. |
| TR12 | Provide hot water and drain pipes that are insulated or otherwise configured to protect against contact. Standards §§ 4.1.3(11), 4.22.6, 4.19.4. |
| TR13 | Provide a medicine cabinet in this room that has at least one shelf mounted no higher than 44 inches above the finished floor and that has clear floor space in front of it which is at least 30 inches wide by 48 inches deep. Standards §§ 4.1.3(11), 4.23.9, 4.2.4. |
| TR14 | Provide a mirror with the bottom edge of its reflecting surface no more than 40 inches above the finished floor. Standards §§ 4.1.3(11), 4.22.6, 4.19.6. |
| TR15 | Provide an accessible route to the toilet room meeting the requirements for width, passing space, head room, surface textures, slopes, and changes in level. Standards §§ 4.1.3(11), 4.22.1, 4.3.1, 4.3.2, 4.3.3, 4.3.4, 4.3.5, 4.3.6, |

| Code | Required Actions |
|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | 4.3.7, 4.3.8. |
| TR16 | Provide accessible directional signage with the International Symbol of Accessibility at inaccessible toilet rooms indicating the location of the nearest accessible toilet room, and provide accessible signage with the International Symbol of Accessibility at all accessible toilet rooms. Standards §§ 4.1.2(7)(d), 4.1.6(3)(e)(iii), 4.30.1, 4.30.2, 4.30.3, 4.30.5, 4.30.7. |
| TR17 | Provide a toilet or locker room sign with the International Symbol of Accessibility and raised and Braille characters mounted on the wall adjacent to the latch side of the door with the centerline of the sign 60 inches above the finished floor and situated such that a person can approach within 3 inches of the sign without encountering an obstruction or standing within a door swing. Standards §§ 4.1.2(7)(d), 4.30.1, 4.30.4, 4.30.5, 4.30.6, 4.30.7. |
| TR18 | Provide a toilet or locker room sign with raised and Braille characters mounted on the wall adjacent to the latch side of the door with the centerline of the sign 60 inches above the finished floor and situated such that a person can approach within 3 inches of the sign without encountering an obstruction or standing within a door swing. Standards §§ 4.1.2(7)(d), 4.1.6(1)(b), 4.30.1, 4.30.4, 4.30.5, 4.30.6. |
| TR19 | Provide an unobstructed turning space at least 60 inches in diameter or a T-shaped space complying with Fig. 3(b). Standards §§ 4.1.3(11), 4.22.3, 4.2.3, Fig. 3. |
| TR20 | Provide a urinal with an elongated rim mounted 17 inches or less above the finished floor, a clear floor space of at least 30 inches wide and 48 inches deep centered on the urinal, and a flush control height of 44 inches or less above the finished floor. Standards §§ 4.1.3(11), 4.22.5, 4.18.2, 4.18.3, 4.18.4. |
| TR21 | Provide a visual alarm appliance in the toilet room. Standards §§ 4.1.3(14), 4.28.1, 4.28.3. |
| TR22 | Provide an accessible toilet room for each gender such that all of the room's elements, including signage, door, door hardware, clear floor space, |

| Code | Required Actions |
|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | <p>water closet, urinal (if provided), stall size and arrangement (if provided), stall door (if provided), grab bars, lavatory, mirror, controls, and dispensers, comply with the Standards. Alternatively, provide one unisex, single user toilet room such that all of the room's elements, including signage, door, door hardware, clear floor space, water closet, urinal (if provided), grab bars, lavatory, mirror, controls, and dispensers, comply with the Standards. Standards §§ 4.13, 4.16, 4.18, 4.19, 4.26, 4.27, 4.30, Figs. 28, 29, 30.</p> |
| TT1 | <p>Provide an accessible telephone with a clear floor space of at least 30 inches by 48 inches that allows either a forward or parallel approach by a person using a wheelchair such that bases, enclosures, and fixed seats do not impede approaches to the telephone; with the highest operable part of the telephone mounted no more than 48 inches above the floor for a front approach or no more than 54 inches above the floor for a side approach; that is hearing aid compatible and has a volume control mechanism; with telephone books, if provided, located between 15 and 48 inches above the finished floor for a front approach or between 9 and 54 inches above the finished floor for a side approach; with a cord of at least 29 inches long from the telephone to the handset; and with signage that complies with the Standards. Standards §§ 4.1.3(17), 4.31, 4.30.7(2).</p> |
| TT2 | <p>Provide at least one accessible public TTY with appropriate signage. Standards §§ 4.1.3(17)(c), 4.30.7(3), 4.31.9.</p> |
| | |